

The labor and part costs are covered by Raytheon Aircraft Company warranty.

**Authority for This Rulemaking**

What authority does FAA have for issuing this rulemaking action? Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

**Regulatory Findings**

Would this proposed AD impact various entities? We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Would this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD (and other information as included in the Regulatory Evaluation) and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket FAA-2005-21239; Directorate Identifier 2005-CE-27-AD" in your request.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Raytheon Aircraft Company:** Docket No. FAA-2005-21239; Directorate Identifier 2005-CE-27-AD

**When Is the Last Date I Can Submit Comments on This Proposed AD?**

(a) We must receive comments on this proposed airworthiness directive (AD) by August 1, 2005.

**What Other ADs Are Affected by This Action?**

(b) None.

**What Airplanes Are Affected by This AD?**

(c) This AD affects Model 390 Premier I airplanes that:

- (1) Incorporate a serial number of RB-1, RB-4 through RB-84, RB-87 through RB-90, RB-92 through RB-96, RB-98 through RB-101, and RB-103 through RB-107; and
- (2) Are certificated in any category.

**What Is the Unsafe Condition Presented in This AD?**

(d) This AD is the result of reports of inadequate left hand and right hand engine assembly cable, wire, and hose routing clearance. The actions specified in this AD are intended to detect and correct chafing conditions in the engine installation, which could result in leaking flammable fluids near an ignition source. This failure could lead to fire damage or loss of airplane control.

**What Must I Do To Address This Problem?**

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
Install Kit No. 390-9104-0001 to correct chafing conditions in the powerplant left hand and right hand engine assembly cable, wire, and hose routing clearance.	At the first 100 hour or annual inspection that occurs following the next 30 days after the effective date of this AD, unless already done.	Follow Raytheon Aircraft Company Mandatory Service Bulletin No. SB 71-3685, Issued May 2005.

**May I Request an Alternative Method of Compliance?**

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact James P. Galstad, Aerospace Engineer, FAA, Wichita ACO, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4135; facsimile: (316) 946-4107.

**May I Get Copies of the Documents Referenced in This AD?**

(g) To get copies of the documents referenced in this AD, contact Raytheon

Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or 316-676-3140 or 316-676-3140. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>. The docket number is Docket No. FAA-2005-21239; Directorate Identifier 2005-CE-27-AD.

Issued in Kansas City, Missouri, on May 24, 2005.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-10865 Filed 5-31-05; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2005-20501; Directorate Identifier 2004-NM-251-AD]

RIN 2120-AA64

**Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Proposed rule; withdrawal.

**SUMMARY:** The FAA withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD) for all EMBRAER Model ERJ 170 series airplanes. That action would have required inspecting the engine fire handles of the overhead panel in the cockpit, and replacing the engine fire handles if necessary. Since the NPRM was issued, we have received new data that the identified unsafe condition has been corrected on all airplanes that would have been subject to the NPRM. Accordingly, the proposed AD is withdrawn.

**ADDRESSES:** You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, Washington, DC. This docket number is FAA-2005-20501; the directorate identifier for this docket is 2004-NM-251-AD.

**FOR FURTHER INFORMATION CONTACT:** Tom Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with a notice of proposed rulemaking (NPRM) for a new AD for all EMBRAER Model ERJ 170 series airplanes. That NPRM was published in the **Federal Register** on March 8, 2005 (70 FR 11172). The NPRM would have required inspecting the engine fire handles of the overhead panel in the cockpit, and replacing the engine fire handles if necessary. The NPRM was prompted by reports of failure of the internal circuit of the engine fire handles of the overhead panel in the cockpit. The proposed actions were intended to prevent failure of the internal circuit of the engine fire handles, which could result in failure of the fuel shut-off valves to close and failure of the fire extinguishing agent to discharge in the event of an engine fire.

**Actions Since NPRM Was Issued**

Since we issued the NPRM, the airplane manufacturer has provided us with data that indicate that the identified unsafe condition (failure of

the internal circuit of the engine fire handles, which could result in failure of the fuel shut-off valves to close and failure of the fire extinguishing agent to discharge in the event of an engine fire) has already been corrected on all airplanes that would have been subject to the NPRM, and that all affected spare parts have been returned to the manufacturer and destroyed.

**FAA's Conclusions**

Upon further consideration, we have determined that the actions that would have been required by the NPRM have already been done on all affected airplanes, and the identified unsafe condition has been corrected. Accordingly, the NPRM is withdrawn.

Withdrawal of the NPRM does not preclude the FAA from issuing another related action or commit the FAA to any course of action in the future.

**Regulatory Impact**

Since this action only withdraws an NPRM, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Withdrawal**

Accordingly, we withdraw the NPRM, Docket No. FAA-2005-20501; Directorate Identifier 2004-NM-251-AD, which was published in the **Federal Register** on March 8, 2005 (70 FR 11172).

Issued in Renton, Washington, on May 23, 2005.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-10868 Filed 5-31-05; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF THE TREASURY**

**Alcohol and Tobacco Tax and Trade Bureau**

**27 CFR Part 9**

[Notice No. 47]

RIN 1513-AA77

**Proposed Establishment of the Rattlesnake Hills Viticultural Area (2004R-678P)**

**AGENCY:** Alcohol and Tobacco Tax and Trade Bureau, Treasury.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** The Alcohol and Tobacco Tax and Trade Bureau proposes to establish the Rattlesnake Hills viticultural area in Yakima County in south central Washington State. The proposed 68,500-acre area is totally within the established Columbia Valley viticultural area. We designate viticultural areas to allow vintners to better describe the origin of their wines and to allow consumers to better identify wines they may purchase. We invite comments on this proposed addition to our regulations.

**DATES:** We must receive written comments on or before August 1, 2005.

**ADDRESSES:** You may send comments to any of the following addresses:

- Chief, Regulations and Procedures Division, Alcohol and Tobacco Tax and Trade Bureau, Attn: Notice No. 47, P.O. Box 14412, Washington, DC 20044-4412.

- 202-927-8525 (facsimile).

- [nprm@ttb.gov](mailto:nprm@ttb.gov) (e-mail).

- <http://www.ttb.gov/alcohol/rules/index.htm>. An online comment form is posted with this notice on our Web site.

- <http://www.regulations.gov> (Federal e-rulemaking portal; follow instructions for submitting comments).

You may view copies of this notice, the petition, the appropriate maps, and any comments we receive about this notice by appointment at the TTB Library, 1310 G Street, NW., Washington, DC 20220. To make an appointment, call 202-927-2400. You may also access copies of the notice and comments online at <http://www.ttb.gov/alcohol/rules/index.htm>.

See the Public Participation section of this notice for specific instructions and requirements for submitting comments, and for information on how to request a public hearing.

**FOR FURTHER INFORMATION CONTACT:** N.A. Sutton, Regulations and Procedures Division, Alcohol and Tobacco Tax and Trade Bureau, 925 Lakeville St., No. 158, Petaluma, California 94952; telephone 415-271-1254.

**SUPPLEMENTARY INFORMATION:**

**Background on Viticultural Areas**

*TTB Authority*

Section 105(e) of the Federal Alcohol Administration Act (the FAA Act, 27 U.S.C. 201 *et seq.*) requires that alcohol beverage labels provide the consumer with adequate information regarding a product's identity and prohibits the use of misleading information on those labels. The FAA Act also authorizes the Secretary of the Treasury to issue regulations to carry out its provisions.