

Dated: March 27, 2007.

Robert D. Lenhard,

Chairman, Federal Election Commission.

[FR Doc. E7-6185 Filed 4-4-07; 8:45 am]

BILLING CODE 6715-01-P

FARM CREDIT ADMINISTRATION

12 CFR Parts 611, 612, 614, 615, 618, 619, 620, and 630

RIN 3052-AC19

Organization; Standards of Conduct and Referral of Known or Suspected Criminal Violations; Loan Policies and Operations; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; General Provisions; Definitions; Disclosure to Shareholders; Disclosure to Investors in System-Wide and Consolidated Bank Debt Obligations of the Farm Credit System; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Announcement of effective date.

SUMMARY: The Farm Credit Administration (FCA) published a final rule under parts 611, 612, 614, 615, 618, 619, 620, and 630 on February 2, 2006. This final rule amended our regulations affecting the governance of the Farm Credit System and became effective on April 5, 2006 (71 FR 18168, April 11, 2006), except for the amendments to §§ 611.210(a)(2), 611.220(a)(2)(i) and (ii), 611.325, and 620.21(d)(2). This document announces the effective date of those delayed portions of the rule.

EFFECTIVE DATE: The effective date for the amendments to §§ 611.210(a)(2), 611.220(a)(2)(i) and (ii), 611.325, and 620.21(d)(2), published February 2, 2006, at 71 FR 5740, is April 5, 2007.

FOR FURTHER INFORMATION CONTACT: Gary Van Meter, Deputy Director, Office of Regulatory Policy, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4232, TTY (703) 883-4434; or Laura D. McFarland, Senior Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4020, TTY (703) 883-4020.
(12 U.S.C. 2252(a)(9) and (10))

Dated: April 2, 2007.

Roland E. Smith,

Secretary, Farm Credit Administration Board.

[FR Doc. E7-6357 Filed 4-4-07; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27757; Directorate Identifier 2007-NM-030-AD; Amendment 39-15014; AD 2007-07-13]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP Model Galaxy Airplanes and Model Gulfstream 200 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Avionics and electrical wire harnesses are routed behind the Primary Flight Displays (PFD) tray at the rear of the instrument panel. In some cases, the wire harness has been found to be chafing on the PFD tray. That could result in electrical arcing and shorting and subsequent loss of systems essential for safe flight.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective April 20, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of April 20, 2007.

We must receive comments on this AD by May 7, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- *Fax:* (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Mike Borfitz, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2677; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

The Civil Aviation Authority of Israel (CAAI), which is the aviation authority for Israel, has issued Israeli Airworthiness Directive 31-07-01-12, dated February 15, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Avionics and electrical wire harnesses are routed behind the Primary Flight Displays (PFD) tray at the rear of the instrument panel. In some cases, the wire harness has been found to be chafing on the PFD tray. That could result in electrical arcing and shorting and subsequent loss of systems essential for safe flight.

The corrective actions include inspecting the wiring harness for chafing, performing repairs if required; and inspecting the wire harnesses for