

(b) The adjustments in paragraph (a) of this section apply to violations that occur after December 6, 2012.

PART 109—RULES OF PRACTICE AND PROCEDURE IN ADJUDICATORY PROCEEDINGS

■ 3. The authority citation for part 109 continues to read as follows:

Authority: 5 U.S.C. 504, 554–557; 12 U.S.C. 1464, 1467, 1467a, 1468, 1817(j), 1818, 1820(k), 1829(e), 3349, 4717, 5412(b)(2)(B); 15 U.S.C. 78(l), 78o–5, 78u–2; 28 U.S.C. 2461 note; 31 U.S.C. 5321; and 42 U.S.C. 4012a.

■ 4. Section 109.103(c) is amended by revising the last sentence of the introductory text and the chart to read as follows:

§ 109.103 Civil money penalties.

* * * * *

(c) * * * The amounts in this chart apply to violations that occur after December 6, 2012:

U.S. Code citation	CMP description	New maximum amount
12 U.S.C. 1464(v)(4)	Reports of Condition – 1 st Tier	\$3,200
12 U.S.C. 1464 (v)(5)	Reports of Condition – 2 nd Tier	32,500
12 U.S.C. 1464(v)(6)	Reports of Condition – 3 rd Tier	1,425,000
12 U.S.C. 1467(d)	Refusal to Cooperate in Exam	7,500
12 U.S.C. 1467a(r)(1)	Late/Inaccurate Reports – 1 st Tier	3,200
12 U.S.C. 1467a(r)(2)	Late/Inaccurate Reports – 2 nd Tier	32,500
12 U.S.C. 1467a(r)(3)	Late/Inaccurate Reports – 3 rd Tier	1,425,000
12 U.S.C. 1817(j)(16)(A)	Change in Control – 1 st Tier	7,500
12 U.S.C. 1817(j)(16)(B)	Change in Control – 2 nd Tier	37,500
12 U.S.C. 1817(j)(16)(C)	Change in Control – 3 rd Tier	1,425,000
12 U.S.C. 1818(i)(2)(A)	Violation of Law or Unsafe or Unsound Practice – 1 st Tier	7,500
12 U.S.C. 1818(i)(2)(B)	Violation of Law or Unsafe or Unsound Practice – 2 nd Tier	37,500
12 U.S.C. 1818(i)(2)(C)	Violation of Law or Unsafe or Unsound Practice – 3 rd Tier	1,375,000
12 U.S.C. 1820(k)(6)(A)(ii)	Violation of Post Employment Restrictions	275,000
12 U.S.C. 1884	Violation of Security Rules	110
12 U.S.C. 3349(b)	Appraisal Violations – 1 st Tier	7,500
12 U.S.C. 3349(b)	Appraisal Violations – 2 nd Tier	37,500
12 U.S.C. 3349(b)	Appraisal Violations – 3 rd Tier	1,425,000
42 U.S.C. 4012a(f)(5)	Flood Insurance	2,000

Dated: October 26, 2012.
Thomas J. Curry,
Comptroller of the Currency.
 [FR Doc. 2012–27074 Filed 11–5–12; 8:45 am]
BILLING CODE 4810–33–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–0603; Directorate Identifier 2012–NE–17–AD; Amendment 39–17160; AD 2012–16–13]

RIN 2120–AA64

Airworthiness Directives; BRP-Powertrain GmbH & Co KG Rotax Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), DOT.
ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that was published in the **Federal Register**. That AD applies to BRP-Powertrain GmbH & Co KG Rotax 912 F2; 912 F3; 912 F4; 912 S2; 912 S3; and 912 S4 reciprocating engines. The word “not” was improperly omitted from the Installation Prohibition section of the AD, thereby changing the prohibition in the AD. This correction reinserts “not” into the paragraph to correct the omission. In all other respects, the original document remains the same.

DATES: This final rule is effective November 6, 2012. The effective date for AD 2012–16–13 (77 FR 51462, August 24, 2012) remains September 10, 2012.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory

evaluation, any comments received, and other information. The address for the Docket Office (phone: 800–647–5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; email: alan.strom@faa.gov; phone: 781–238–7143; fax: 781–238–7199.

SUPPLEMENTARY INFORMATION: Airworthiness Directive 2012–16–13, amendment 39–17160 (77 FR 51462, August 24, 2012), currently requires replacing the pressure side fuel hose on certain fuel pumps and inspecting the carburetors connected to those fuel pumps for contamination within 5 flight hours after the effective date of this AD

for BRP-Powertrain GmbH & Co KG Rotax 912 F2; 912 F3; 912 F4; 912 S2; 912 S3; and 912 S4 reciprocating engines.

As published, the text of paragraph (g)(3), Installation Prohibition, is incorrect.

No other part of the preamble or regulatory information is in error; therefore, only the changed portion of the final rule is being published in the **Federal Register**.

The effective date of this AD remains September 10, 2012.

Correction of Regulatory Text

§ 39.13 [Corrected]

■ In the **Federal Register** of August 24, 2012, on page 51464, in the 1st column, paragraph (g)(3) of AD 2012-16-13 is corrected to read as follows:

* * * * *

(3) After the effective date of this AD, do not approve for return to service any product or article with a fuel hose removed from a P/N 893114 fuel pump with an S/N listed in Table 1 to paragraph (c) of this AD.

* * * * *

Issued in Burlington, Massachusetts, on October 24, 2012.

Colleen M. D'Alessandro,

Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2012-26772 Filed 11-5-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30866 ; Amdt. No. 3501]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are

designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective November 6, 2012. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of November 6, 2012.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

*Availability—*All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit <http://www.nfdc.faa.gov> to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Richard A. Dunham III, Flight Procedure Standards Branch (AFS-420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPs, Takeoff Minimums

and/or ODPS. The complete regulators description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, in addition to their complex nature and the need for a special format make publication in the **Federal Register** expensive and impractical. Furthermore, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their depiction on charts printed by publishers of aeronautical materials. The advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA forms is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs and the effective dates of the, associated Takeoff Minimums and ODPs. This amendment also identifies the airport and its location, the procedure, and the amendment number.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as contained in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPS, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPS contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedures before