

Cieszynska 325, 43–300 Bielsko-Biala, Poland; telephone: +48 33 812 50 26; fax: +48 33 812 37 39; email: [techsupport@szd.com.pl](mailto:techsupport@szd.com.pl); Internet: <http://szd.com.pl/en/products/szd-50-3-puchacz>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on April 8, 2015.

**Earl Lawrence,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–08733 Filed 4–16–15; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2014–1123; Directorate Identifier 2014–CE–037–AD]

**RIN 2120–AA64**

**Airworthiness Directives; GA 8 Airvan (Pty) Ltd Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for GA 8 Airvan (Pty) Ltd Model GA8–TC320 airplanes that would revise AD 2015–06–02. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 1, 2015.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations,

M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: + 61 03 5172 1200; fax: +61 03 5172 1201; email:

[techpubs@gippsaero.com](mailto:techpubs@gippsaero.com); Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>.

You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–1123; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:**

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: [doug.rudolph@faa.gov](mailto:doug.rudolph@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2014–1123; Directorate Identifier 2014–CE–037–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also

post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

On March 12, 2015, we issued AD 2015–06–02, Amendment 39–18120 (80 FR 14810; March 20, 2015). That AD required actions intended to address an unsafe condition on GA 8 Airvan (Pty) Ltd Model GA8–TC320 airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2015–06–02, a specific serial number range has been identified for applicability.

The Civil Aviation Safety Authority (CASA), which is the aviation authority for Australia, has issued AD/GA8/8, Amdt 1, dated March 26, 2015 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

A recent review of the engine mount installation on the GA8–TC 320 aircraft has highlighted the omission of engine mount fire seal washers during the assembly process.

The current engine mount configuration does not meet the certification basis for the aircraft, specifically regulation 23.865 of the Federal Aviation Regulations of the United States of America, where engine mounts located in designated fire zones are required to be suitably shielded so that they are capable of withstanding the effects of a fire.

The Gippsland Aeronautics GA8–TC 320 aircraft require the installation of an approved steel washer at each of the engine mount locations to address a potential risk of reduced engine retention capability in the event of a fire.

This AD, AD/GA8/8 Amdt 1, amends the applicability statement to be inclusive of the affected aircraft serial number range.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–1123.

**Related Service Information Under 1 CFR 51**

GippsAero has issued Mandatory Service Bulletin SB–GA8–2014–115, Issue 1, dated October 6, 2014. The service bulletin describes procedures for inspecting the orientation of the engine isolator mounts to verify proper installation, re-installing if necessary, and installing steel washers on the forward side of each side of the engine isolator mounts. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

### FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

### Costs of Compliance

We estimate that this proposed AD will affect 13 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$10 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$5,655, or \$435 per product.

According to the manufacturer, all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,  
 (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39–18120 (80 FR 14810, March 20, 2015), and adding the following new AD:

**GA 8 Airvan (Pty) Ltd:** Docket No. FAA–2014–1123; Directorate Identifier 2014–CE–037–AD.

#### (a) Comments Due Date

We must receive comments by June 1, 2015.

#### (b) Affected ADs

This AD revises AD 2015–06–02, Amendment 39–18120 (80 FR 14810; March 20, 2015).

#### (c) Applicability

This AD applies to GA 8 Airvan (Pty) Ltd GA8–TC320 airplanes, all serial numbers up to and including GA8–TC 320–14–205, certificated in any category.

#### (d) Subject

Air Transport Association of America (ATA) Code 71: Power Plant.

#### (e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another

country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this proposed AD to revise the applicable airplane serial numbers and to detect and correct the omission of steel washers at each isolator mount location, which, if not corrected, could result in reduced engine retention capability in the event of a fire.

### (f) Actions and Compliance

Unless already done, comply with this AD within the compliance times specified in paragraphs (f)(1) through (f)(3) of this AD:

(1) Within the next 300 hours time-in-service after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first, inspect the orientation of the engine isolator mounts to verify that the mounts have been installed properly following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB–GA8–2014–115, Issue 1, dated October 6, 2014.

(2) Before reinstalling the engine isolator mounts following the inspection required in paragraph (f)(1) of this AD, before further flight, install a part number J–2218–61 steel washer on the forward side of each of the four engine isolator mounts, following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB–GA8–2014–115, Issue 1, dated October 6, 2014.

(3) If during the inspection required in paragraph (f)(1) of this AD, any of the engine isolator mounts are found to not comply with the specifications found in the Accomplishment Instructions of GippsAero Mandatory Service Bulletin SB–GA8–2014–115, Issue 1, dated October 6, 2014, before further flight, re-install the isolators to the correct orientation, or if damage is found, replace with airworthy parts.

### (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: [doug.rudolph@faa.gov](mailto:doug.rudolph@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(h) Related Information**

Refer to MCAI Civil Aviation Safety Authority (CASA) AD No. AD/GA8/8, Amdt 1, dated March 26, 2015. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123. For service information related to this AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: + 61 03 5172 1200; fax: +61 03 5172 1201; email: [techpubs@gippsaero.com](mailto:techpubs@gippsaero.com); Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on April 8, 2015.

**Earl Lawrence,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2015-08720 Filed 4-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF EDUCATION****34 CFR Part 396**

[Docket ID ED-2015-OSERS-0024]

**Proposed Waiver and Extension of the Project Period; Regional Interpreter Education Centers for the Training of Interpreters for Individuals Who Are Deaf or Hard of Hearing and Individuals Who Are Deaf-Blind**

**AGENCY:** Rehabilitation Services Administration (RSA), Office of Special Education and Rehabilitative Services (OSERS), Department of Education.

**ACTION:** Proposed waiver and extension of the project period.

Catalog of Federal Domestic Assistance (CFDA) Number: 84.160A.

**SUMMARY:** The Secretary proposes to waive the requirements that generally prohibit project periods exceeding five years and extensions of project periods involving the obligation of additional Federal funds for five 60-month projects initially funded in fiscal year (FY) 2010. The Secretary also proposes to extend the project period for these projects for one year. The proposed waiver and extension would enable the currently funded Regional Interpreter Education Centers for the training of interpreters for individuals who are deaf or hard of hearing and individuals who are deaf-blind to receive funding through September 30, 2016.

**DATES:** We must receive your comments on or before May 18, 2015.

**ADDRESSES:** Submit your comments through the Federal eRulemaking Portal or via postal mail, commercial delivery, or hand delivery. We will not accept comments submitted by fax or by email or those submitted after the comment period. To ensure that we do not receive duplicate copies, please submit your comments only once. In addition, please include the Docket ID at the top of your comments.

- *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) to submit your comments electronically. Information on using [Regulations.gov](http://Regulations.gov), including instructions for accessing agency documents, submitting comments, and viewing the docket, is available on the site under "Are you new to the site?"

- *Postal Mail, Commercial Delivery, or Hand Delivery:* If you mail or deliver your comments about this proposed waiver and extension of the project period, address them to Kristen Rhinehart-Fernandez, U.S. Department of Education, 400 Maryland Avenue SW., Room 5027, Potomac Center Plaza (PCP), Washington, DC 20202-2800.

*Privacy Note:* The Department's policy is to make all comments received from members of the public available for public viewing in their entirety on the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov). Therefore, commenters should be careful to include in their comments only information that they wish to make publicly available.

**FOR FURTHER INFORMATION CONTACT:**

Kristen Rhinehart-Fernandez.  
Telephone: (202) 245-6103 or by email: [Kristen.rhinehart@ed.gov](mailto:Kristen.rhinehart@ed.gov).

If you use a telecommunications device for the deaf (TDD) or a text telephone (TTY), call the Federal Relay Service (FRS), toll-free, at 1-800-877-8339.

**SUPPLEMENTARY INFORMATION:**

*Invitation to Comment:* We invite you to submit comments about this proposed waiver and extension of the project period. During and after the comment period, you may inspect all public comments about this proposed waiver and extension of the project period by accessing [Regulations.gov](http://Regulations.gov). You may also inspect all public comments in Room 5027, Potomac Center Plaza, 550 12th Street SW., Washington, DC, between the hours of 8:30 a.m. and 4:00 p.m., Washington, DC time, Monday through Friday of each week except Federal holidays.

*Assistance to Individuals with Disabilities in Reviewing the Rulemaking Record:* On request we will supply an appropriate accommodation or auxiliary aid to an individual with a

disability who needs assistance to review the comments or other documents in the public rulemaking record for this proposed waiver and extension of the project period. If you want to schedule an appointment for this type of accommodation or auxiliary aid, please contact the person listed under **FOR FURTHER INFORMATION CONTACT**.

**Background**

On June 7, 2010, the Department published a notice inviting applications for new awards for FY 2010 (75 FR 32164) for Regional Interpreter Education Centers (Regional Centers) to be funded under the Rehabilitation Training Program, authorized under section 302 of the Rehabilitation Act of 1973, as amended (Rehabilitation Act). The purpose of the Regional Centers is to establish regional interpreter training programs that will train a sufficient number of qualified interpreters to meet the communications needs of individuals who are deaf or hard of hearing and individuals who are deaf-blind. The Department awarded grants to five Regional Centers in FY 2010 for a period of 60 months. All five projects are scheduled to end on September 30, 2015.

We have determined that it would not be in the public interest to run a competition under this program in FY 2015 for new Regional Centers. RSA has funded interpreter training programs since 1964 to meet the needs of its vocational rehabilitation (VR) consumers who are deaf, hard of hearing, and deaf-blind. At each critical juncture RSA has re-evaluated its interpreter training program to determine how to best meet the evolving needs of consumers of interpreting services. In the course of this ongoing re-evaluation, we have concluded that, since 2005, when the current priorities were established for the Regional Centers, the training needs of interpreters have changed as a result of new and emerging issues facing VR consumers who are deaf, hard of hearing, and deaf-blind.

Conducting a competition before the Department has had an opportunity to engage in strategic planning activities for the current program could result in (1) an ineffective or poorly targeted investment that would not meet the training needs of qualified interpreters and (2) the inability to sufficiently meet the communication needs of individuals who are deaf or hard of hearing and individuals who are deaf-blind. We intend to use the remainder of FY 2015 and part of FY 2016 to consider how Regional Centers can employ promising