

(ii) Any outdoor unit model that has a certified combination with a rating below the applicable standard level(s) for a region cannot be installed in that region. The least-efficient combination of each basic model must comply with this standard.

\* \* \* \* \*

[FR Doc. 2016-29990 Filed 1-5-17; 8:45 am]

BILLING CODE P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-9569; Directorate Identifier 2016-NM-052-AD]

RIN 2120-AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2013-03-12 for all Dassault Aviation Model MYSTERE-FALCON 50 airplanes. AD 2013-03-12 currently requires revising the maintenance program to incorporate new or revised maintenance requirements and airworthiness limitations. Since we issued AD 2013-03-12, the manufacturer has issued a revision to the airplane maintenance manual (AMM) that introduces new or more restrictive maintenance requirements and/or airworthiness limitations. This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate new or revised maintenance requirements and airworthiness limitations. We are proposing this AD to prevent reduced structural integrity of the airplane.

**DATES:** We must receive comments on this proposed AD by February 21, 2017.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE.,

Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9569; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-9569; Directorate Identifier 2016-NM-052-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

##### Discussion

On February 1, 2013, we issued AD 2013-03-12, Amendment 39-17347 (78 FR 9798, February 12, 2013) (“AD 2013-

03-12”). AD 2013-03-12 requires actions intended to address an unsafe condition on all Dassault Aviation Model MYSTERE-FALCON 50 airplanes. Since we issued AD 2013-03-12, the manufacturer has issued a revision to the AMM that introduces new or more restrictive maintenance requirements and/or airworthiness limitations.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016-0067, dated April 7, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Dassault Aviation Model MYSTERE-FALCON 50 airplanes. The MCAI states:

The airworthiness limitations and maintenance requirements for the Mystère Falcon 50 type design are included in DA Mystère Falcon 50 Aircraft Maintenance Manual (AMM) chapter 5-40 and are approved by EASA.

Failure to implement these limitations or accomplish these tasks could result in an unsafe condition [reduced structural integrity of the airplane]. Consequently, compliance with these actions has been identified as mandatory for continued airworthiness.

Consequently, EASA issued AD 2011-0246 [which corresponds to FAA AD 2013-03-12] to require accomplishment of the maintenance tasks, and implementation of the airworthiness limitations, as specified in DA Mystère Falcon 50 AMM chapter 5-40 Revision 21.

Since that [EASA] AD was issued, DA issued revision 23 of the Mystère Falcon 50 AMM chapter 5-40 (hereafter referred to as ‘the ALS’ in this [EASA] AD), which introduces new and more restrictive maintenance requirements and/or airworthiness limitations.

The ALS introduces, among others, the following changes:

- Addition of more detailed data regarding SSIP program,
- Task 53-50-35-220-802 “Detailed inspection of the frame 35 upper and lower sections”, replacing Task 53-50-35-220-801,
- Task 55-00-00-270-801 “Ultrasonic inspection for stress corrosion in stabilizer hinges”, replacing Task 55-00-00-250-801, and
- Task 78-31-00-250-802 “Special detailed inspection (fluorescent penetrant) of thrust reverser door hinge fittings”, replacing Task 78-31-00-250-801.

For the reasons described above, this [EASA] AD, retains the requirements of EASA AD 2011-0246, which is superseded, and requires the implementation of the maintenance tasks and airworthiness limitations, as specified in the ALS.

This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate

new or revised maintenance requirements and airworthiness limitations. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9569.

#### Related Service Information Under 1 CFR Part 51

Dassault Aviation has issued Section 05-40/00, Airworthiness Limitations, of Chapter 5-40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015. The service information describes maintenance requirements and/or airworthiness limitations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

This AD requires revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (l)(1) of this proposed AD. The request should include a description of changes to the required actions that will ensure the continued damage tolerance of the affected structure.

#### Costs of Compliance

We estimate that this proposed AD affects 249 airplanes of U.S. registry.

The actions required by AD 2013-03-12, and retained in this proposed AD, take about 1 work-hour per product, at an average labor rate of \$85 per work-

hour. Based on these figures, the estimated cost of the actions that are required by AD 2013-03-12 is \$85 per product.

We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$21,165, or \$85 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2013-03-12, Amendment 39-17347 (78 FR 9798, February 12, 2013), and adding the following new AD:

**Dassault Aviation:** Docket No. FAA-2016-9569; Directorate Identifier 2016-NM-052-AD.

#### (a) Comments Due Date

We must receive comments by February 21, 2017.

#### (b) Affected ADs

(1) This AD replaces AD 2013-03-12, Amendment 39-17347 (78 FR 9798, February 12, 2013) ("AD 2013-03-12").

(2) This AD affects AD 2010-26-05, Amendment 39-16544 (75 FR 79952, December 21, 2010) ("AD 2010-26-05"), and AD 2012-02-18, Amendment 39-16941 (77 FR 12175, February 29, 2012) ("AD-2012-02-18").

#### (c) Applicability

This AD applies to Dassault Aviation Model MYSTERE-FALCON 50 airplanes, certificated in any category, all manufacturer serial numbers.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Periodic inspections.

#### (e) Reason

This AD was prompted by a manufacturer revision to the airplane maintenance manual (AMM) that introduces new or more restrictive maintenance requirements and/or airworthiness limitations. We are issuing this AD to prevent reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Maintenance Program Revision, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2013-03-12, with no changes. Within 30 days after March 19, 2013 (the effective date of AD 2013-03-12): Revise the maintenance program to incorporate all airworthiness limitations and maintenance tasks specified in Section 05-40/00, Airworthiness Limitations, of Chapter 5-40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual,

Revision 21, dated June 2011. The initial compliance times for the tasks are at the applicable times specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011, or within 30 days after March 19, 2013, whichever occurs later.

**(h) Retained Provision Regarding Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs), With New Exception**

This paragraph restates the requirements of paragraph (h) of AD 2013–03–12, with a new exception. Except as required by paragraph (i) of this AD: After accomplishing the revisions required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections), intervals, and/or CDCCLs may be used other than those specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011, unless the actions, intervals, and/or CDCCLs are approved as an alternative methods of compliance (AMOC) in accordance with the procedures specified in paragraph (l)(1) of this AD.

**(i) New Maintenance or Inspection Program Revision**

Within 30 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate airworthiness limitations, maintenance tasks, and associated thresholds and intervals specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015. The initial compliance times for the tasks are at the applicable times specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015, or within 30 days after the effective date of this AD, whichever occurs later. Accomplishing the revision of the maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

**(j) New Provision Regarding Alternative Actions and Intervals**

After the maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (l)(1) of this AD.

**(k) Terminating Action for Certain ADs**

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates all requirements of AD 2010–26–05 and AD 2012–02–18 for the Dassault Aviation Model MYSTERE–FALCON 50 airplanes specified in those ADs.

**(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016–0067, dated April 7, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9569.

(2) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; Internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on December 27, 2016.

**Jeffrey E. Duven,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016–31963 Filed 1–5–17; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2016–9567; Directorate Identifier 2016–NM–147–AD]

**RIN 2120–AA64**

**Airworthiness Directives; Airbus Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2007–13–08, for certain Airbus Model A318, A319, A320, and A321 series airplanes. AD 2007–13–08 currently requires repetitive inspections of the auxiliary power unit (APU) starter motor, APU inlet plenum, and APU air intake for discrepancies; repetitive cleaning of the APU air intake, and applicable corrective actions. Since we issued AD 2007–13–08, a determination was made that the unsafe condition could occur on additional airplanes. This proposed AD would expand the applicability in AD 2007–13–08, and include an optional terminating installation for the repetitive actions. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by February 21, 2017.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus, Airworthiness Office–ELAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet: <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on