

Paperwork Reduction Act

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. Chapter 35), the information collection and recordkeeping requirements imposed by the Order have been approved previously under OMB control number 0581-0093. This proposal imposes no additional reporting and recordkeeping burden on domestic manufacturer and importers of softwood lumber. The reporting requirements pertaining to this proposed rule are described in the following paragraphs.

As previously mentioned, pursuant to section 1217.53(a) of the Order, domestic manufacturers and importers who domestically ship or import less than the de minimis threshold must apply to the Board each year for a certificate of exemption and provide documentation as appropriate to support their request. The reporting burden for this collection of information is estimated to average 0.25 hours per domestic manufacturer or importer per report, or 0.25 hours per year (1 request per year per exempt entity). This computes to a total annual burden of 199.75 hours (0.25 hours times 799 exempt entities at the 15 mmbf de minimis exemption threshold from Table 4).

Further, pursuant to section 1217.70 of the Order, domestic manufacturers and importers that ship or import at or over the de minimis exemption level and pay their assessments directly to the Board must submit a shipment/import report for each quarter when assessments are due. The reporting burden for this collection of information is estimated to average 0.5 hours per domestic manufacturer or importer per report, or 2 hours per year (4 reports per year times 0.5 hours per report). This computes to a total annual burden of 510 hours (255 assessed entities (from Table 4—No. of Assessed Entities at 15 mmbf) at 2 hours each equals 510 hours).

All domestic manufacturers and importers must also maintain records sufficient to verify their reports. The recordkeeping burden for keeping this information is estimated to average 0.5 hours per record keeper maintaining such records, or 527 hours (1,054 total entities assessed (from Table 4—No. of Assessed Entities at no exemption) times 0.5 hours).

As with all Federal promotion programs, reports and forms are periodically reviewed to reduce

the Board. By this metric, the Order to-date has been effective. USDA therefore finds that 15 mmbf is a reasonable exemption level for de minimis.

information requirements and duplication by industry and public sector agencies. Finally, USDA has not identified any relevant Federal rules that duplicate, overlap, or conflict with this proposed rule.

USDA is committed to complying with the E-Government Act, to promote the use of the internet and other information technologies to provide increased opportunities for citizen access to Government information and services, and for other purposes.

Regarding outreach efforts, USDA initiated this action in response to a May 2016 federal court decision in *Resolute*. USDA proposes to establish the de minimis quantity exemption under the softwood lumber Order as contained herein.

We have performed this initial RFA analysis regarding the impact of the proposed action on small entities and we invite comments concerning the potential effects of this action.

USDA has determined that this proposed rule is consistent with and would effectuate the purposes of the 1996 Act.

A 60-day comment period is provided to allow interested persons to respond to this proposed rule. All written comments received in response to this proposed rule by the date specified will be considered.

List of Subjects in 7 CFR Part 1217

Administrative practice and procedure, Advertising, Consumer information, Marketing agreements, Promotion, Reporting and recordkeeping requirements, Softwood lumber.

The authority citation for 7 CFR part 1217 continues to read as follows:

Authority: 7 U.S.C. 7411-7425; 7 U.S.C. 7401.

Dated: May 23, 2017.

Bruce Summers,

Acting Administrator.

[FR Doc. 2017-10997 Filed 5-26-17; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2017-0499; Directorate Identifier 2016-NM-205-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 747-400, 747-400F, and 747-8F series airplanes. This proposed AD was prompted by reports of failure of the fastener assemblies on the crew access ladder handrails. This proposed AD would require replacing the fastener assemblies. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 14, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0499.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0499; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be

available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA; phone: 425-917-6457; fax: 425-917-6590; email: susan.l.monroe@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0499; Directorate Identifier 2016-NM-205-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of failure of the fastener assemblies on the crew access ladder handrails. Bolts on existing fastener assemblies for the crew ladder handrail are too short to ensure self-locking nut elements are fully engaged. This condition, if not corrected, could result in the fastener assemblies on the crew access ladder handrails coming loose, which could result in serious or fatal injury to personnel.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Special Attention Service Bulletin 747-25-3693, dated November 10, 2016. The service information describes procedures for replacing the existing fastener assemblies with new assemblies on the crew access ladder handrails. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the Service Information.” For information on the procedures, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0499.

Differences Between This Proposed AD and the Service Information

Boeing Special Attention Service Bulletin, 747-25-3693, dated November 10, 2016, applies to certain The Boeing Company Model 747-400, 747-400F, and 747-8F series airplanes. This proposed AD would apply to those airplanes and all Model 747-8F airplanes with an original certificate of airworthiness, or an original export certificate of airworthiness, issued after November 10, 2016. Because the affected parts are rotatable parts, we have determined that these parts could later be installed on airplanes that were initially delivered with acceptable parts, thereby subjecting those airplanes to the unsafe condition. We have coordinated this difference with Boeing.

Costs of Compliance

We estimate that this proposed AD affects 84 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	3 work-hours × \$85 per hour = \$255	\$2,418	\$2,673	\$224,532

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII,

Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on

the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2017–0499; Directorate Identifier 2016–NM–205–AD.

(a) Comments Due Date

We must receive comments by July 14, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Model 747–400, 747–400F, and 747–8F series airplanes, as identified in Boeing Special Attention Service Bulletin 747–25–3693, dated November 10, 2016.

(2) Model 747–8F series airplanes with an original certificate of airworthiness, or an original export certificate of airworthiness, issued after November 10, 2016, and before the effective date of this AD.

(3) Model 747–8F series airplanes with an original certificate of airworthiness, or an original export certificate of airworthiness, issued on or after the effective date of this AD.

(d) Subject

Air Transport Association (ATA) of America Code 25; Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports of failure of the fastener assemblies on the crew access ladder handrails. We are issuing this AD to prevent the fastener assemblies from coming loose on the crew access ladder handrails, which could result in serious or fatal injury to personnel.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

For airplanes identified in paragraph (c)(1) of this AD: Within 36 months after the

effective date of this AD, replace the fastener assemblies in the crew access ladder handrails with new fastener assemblies, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3693, dated November 10, 2016.

(h) Inspection and Replacement

(1) For airplanes identified in paragraph (c)(2) of this AD: Within 36 months after the effective date of this AD, do a general visual inspection of the crew access ladder handrails for the discrepant fastener assembly hardware identified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3693, dated November 10, 2016. A review of airplane maintenance records is acceptable in lieu of this inspection, if the part number(s) of the fastener assembly hardware can be conclusively determined from that review.

(2) If any discrepant fastener assembly hardware is found, within 36 months after the effective date of this AD, replace the discrepant fastener assemblies in the crew access ladder handrails with new fastener assemblies, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3693, dated November 10, 2016.

(i) Parts Installation Limitation

For airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD: As of the effective date of this AD, no person may install the discrepant fastener hardware identified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3693, dated November 10, 2016, on a crew access ladder on any airplane.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for

Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA; phone: 425–917–6457; fax: 425–917–6590; email: susan.l.monroe@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on May 17, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–10606 Filed 5–26–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2017–0500; Directorate Identifier 2017–NM–009–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model MD–11 and MD–11F airplanes. This proposed AD was prompted by fuel system