

members of the general public and regulated entities.<sup>41</sup> The comments the Bureau received in response to the Guidance RFI highlight the importance of guidance and compliance aids for regulatory implementation, specifically for implementing highly technical rules such as the TRID Rule.<sup>42</sup> They also highlighted certain aspects of guidance that were not addressed or guidance styles that did not work well such as providing more guidance on what requirements of the TRID Rule apply to different segments of the market and providing specific examples to facilitate compliance. For assessment purposes of the TRID Rule, the Bureau is interested in learning more about any aspects of the Rule that were confusing or on which more guidance was needed, whether at the time the Rule took effect or afterwards, and the effects of this confusion or lack of guidance (including any unintended effects on market liquidity in any sectors of the housing finance system).

#### Request for Comment

The Bureau hereby invites members of the public to submit information and other comments relevant to the issues identified above and below, information relevant to enumerating costs and benefits of the TRID Rule to inform the assessment's cost-benefit perspective, and any other information relevant to assessing the effectiveness of the TRID Rule in meeting the purposes and objectives of title X of the Dodd-Frank Act (section 1021) and the specific goals of the Bureau. In particular, the Bureau invites the public, including consumers and their advocates, housing counselors, mortgage creditors, settlement agents, and other industry participant, industry analysts, and other interested persons to submit comments on any or all of the following:

(1) Comments on the feasibility and effectiveness of the assessment plan, the objectives of the TRID Rule that the Bureau intends to use in the assessment, and the outcomes, metrics, baselines, and analytical methods for assessing the effectiveness of the Rule as described in part IV above;

<sup>41</sup> For the full electronic docket, see <https://www.regulations.gov/docket?D=CFPB-2018-0013>. The Bureau received approximately 49 comments on this RFI (42 that addressed the substance of the RFI). The Bureau received a number of comments related to guidance but for the purpose of the TRID assessment, only comments received related to TRID guidance are mentioned.

<sup>42</sup> The Bureau continues to update and improve its regulatory guidance and implementation aids. Several materials were, and will be, published after the implementation of the TRID Rule to provide more guidance and clarity, and the Bureau continues to work to identify and address additional guidance needs.

(2) Data and other factual information that the Bureau may find useful in executing its assessment plan and answering related research questions, particularly research questions that may be difficult to address with the data currently available to the Bureau, as described in part IV above;

(3) Recommendations to improve the assessment plan, as well as data, other factual information, and sources of data that would be useful and available to the Bureau to execute any recommended improvements to the assessment plan;

(4) Data and other factual information about the benefits and costs of the TRID Rule for consumers, creditors, or other stakeholders;

(5) Data and other factual information about the effects of the Rule on transparency, efficiency, access, and innovation in the mortgage market;

(6) Data and other factual information about the Rule's effectiveness in meeting the purposes and objectives of title X of the Dodd-Frank Act (section 1021), which are listed in part IV above;

(7) Data and other factual information on the disclosure dataset specified in the Assessing Firm Effects section above under part IV;

(8) Comments on any aspects of the TRID Rule that were or are confusing or on which more guidance was or is needed during implementation including whether the issues have been resolved or remain unresolved; and

(9) Recommendations for modifying, expanding, or eliminating the TRID Rule.

Dated: November 13, 2019.

**Kathleen L. Kraninger,**

*Director, Bureau of Consumer Financial Protection.*

[FR Doc. 2019-25260 Filed 11-21-19; 8:45 am]

**BILLING CODE 4810-AM-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0906; Product Identifier 2019-NE-31-AD]

RIN 2120-AA64

#### Airworthiness Directives; International Aero Engines Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for

certain International Aero Engines, LLC (IAE) PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines. This proposed AD was prompted by reports of failures of certain low-pressure turbine (LPT) 3rd-stage blades. This proposed AD would require replacement of the affected LPT 3rd-stage blades. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 6, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact International Aero Engines, LLC, 400 Main Street, East Hartford, CT 06118; phone: 800-565-0140; email: [help24@pw.utc.com](mailto:help24@pw.utc.com); internet: <https://fleetcare.pw.utc.com>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0906; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7088; fax: 781-238-7199; email: [kevin.m.clark@faa.gov](mailto:kevin.m.clark@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2019–0906; Product Identifier 2019–NE–31–AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

**Discussion**

The FAA received several reports of failures of the affected LPT 3rd-stage blades. These failures appear to be caused by debris passing through the engine. The manufacturer has determined the need to replace any affected LPT 3rd-stage blade with an LPT blade made of a different material that is less susceptible to impact damage. This condition, if not addressed, could result in uncontained release of the LPT 3rd-stage blades, failure of one or more engines, loss of thrust control, and loss of the airplane.

**Related Service Information**

The FAA reviewed Pratt & Whitney Service Bulletin PW1000G–C–72–00–0111–00A–930A–D, Issue No. 002, dated October 18, 2019. The service information describes procedures for removal of the affected LPT 3rd-stage blades and their replacement with parts eligible for installation.

**FAA’s Determination**

The FAA is proposing this AD because the Agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require removal from service of LPT 3rd-stage blades part/number (P/N) 5387343, 5387493, 5387473, or 5387503, and their replacement with parts eligible for installation.

**Costs of Compliance**

The FAA estimates that this proposed AD affects 65 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace set of LPC 3rd-stage blades ..	0 work-hours × \$85 per hour = \$0 .....	\$750,000 per blade set .....	\$750,000	\$48,750,000

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs

applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, the FAA certifies this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**International Aero Engines Turbofan**

**Engines:** Docket No. FAA–2019–0906; Product Identifier 2019–NE–31–AD.

**(a) Comments Due Date**

The FAA must receive comments by January 6, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to International Aero Engines (IAE) PW1133G–JM, PW1133GA–JM, PW1130G–JM, PW1129G–JM, PW1127G–JM, PW1127GA–JM, PW1127G1–JM, PW1124G–JM, PW1124G1–JM, and PW1122G–JM turbofan model engines with low-pressure turbine (LPT) 3rd-stage blades, part number

(P/N) 5387343, 5387493, 5387473 or 5387503, installed.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

**(e) Unsafe Condition**

This AD was prompted by reports of failure of certain LPT 3rd-stage blades. The FAA is issuing this AD to prevent failure of these LPT 3rd-stage blades. The unsafe condition, if not addressed, could result in uncontained release of the LPT 3rd-stage blades, failure of one or more engines, loss of thrust control, and loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

At the next engine shop visit after the effective date of this AD, remove from service any LPT 3rd-stage blade, P/N 5387343, 5387493, 5387473, or 5387503, and replace with a part eligible for installation.

**(h) Definitions**

(1) For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation of the engine without subsequent engine maintenance does not constitute an engine shop visit.

(2) For the purpose of this AD, a “part eligible for installation” is any LPT 3rd-stage blade that does not have a P/N 5387343, 5387493, 5387473, or 5387503.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

(1) For more information about this AD, contact Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7088; fax: 781-238-7199; email: [kevin.m.clark@faa.gov](mailto:kevin.m.clark@faa.gov).

(2) For service information identified in this AD, contact International Aero Engines, LLC, 400 Main Street, East Hartford, CT, 06118; phone: 800-565-0140; email: [help24@pw.utc.com](mailto:help24@pw.utc.com); internet: <https://fleetcare.pw.utc.com>. You may view this

referenced service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Issued in Burlington, Massachusetts, on November 15, 2019.

**Robert J. Ganley,**

*Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.*

[FR Doc. 2019-25224 Filed 11-21-19; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2019-0873; Product Identifier 2019-NM-164-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Airbus SAS Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A319-112, -115, and -132 airplanes; and Model A320-214, -216, -232, and -233 airplanes. This proposed AD was prompted by a report that a possible interference was identified between 1M and 2M wiring harnesses and the tapping units, and that the interference could adversely affect the lavatory smoke detection system and/or the passenger oxygen system. This proposed AD would require modifying the 1M and 2M harness routing, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 6, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0873.

**Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0873; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0873; Product Identifier 2019-NM-164-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.