

J. Other Comments on Specific Implementation Issues

The Bureau received comments on a number of other subjects. These include comments on the structure of the Bureau's internal deliberative process for considering advisory opinion requests; timelines for deciding advisory opinion requests; details of how the Bureau should communicate with requestors after the Bureau receives their requests, such as what the Bureau should say in the letters that it sends denying requests; general outreach that commenters recommend that the Bureau conduct with outside bodies or groups; recommendations regarding the types of requests the Bureau should prioritize; and details of how the Bureau should post advisory opinions on its website.

The Bureau appreciates receiving commenters' views on all aspects of the program. However, the Bureau has decided not to expand the scope of the Advisory Opinions Policy, which is intended to establish the general procedures of the program, to cover these specific implementation issues. Instead, the Bureau will consider these comments as it proceeds with implementation of the Advisory Opinions Policy.

IV. Regulatory Requirements

This Advisory Opinions Policy is a rule of agency organization, procedure, or practice, and it is therefore exempt from the notice-and-comment rulemaking requirements of the APA.²⁷ For the same reason, it is not subject to the 30-day delayed effective date for substantive rules under the APA.²⁸ Because no notice of proposed rulemaking is required, the Regulatory Flexibility Act does not require an initial or final regulatory flexibility analysis.²⁹

V. Paperwork Reduction Act

The Paperwork Reduction Act of 1995 (PRA) (44 U.S.C. 3501 *et seq.*) requires that Federal agencies may not conduct or sponsor, and notwithstanding any other provision of law, a person is not required to respond to a collection of information unless it displays a currently valid Office of Management and Budget (OMB) control number. The information collection requirements as contained in this final Policy and identified below have been approved by OMB and assigned the OMB control number 3170-0072. OMB's approval will expire on November 30, 2023.

²⁷ 5 U.S.C. 553(b).

²⁸ 5 U.S.C. 553(d).

²⁹ 5 U.S.C. 603(a), 604(a).

The Bureau's Advisory Opinions Proposal, published June 22, 2020, sought comment on these information collection requirements. While the Bureau received numerous comments on the Advisory Opinions Proposal, which are addressed above, the Bureau received no comments specifically regarding the burden estimates or the utility or appropriateness of these information collections. Additional details on comments received can be found in the Supporting Statement for the related 30-day notice published as required under the PRA.³⁰

A complete description of the information collection requirements, including the burden estimate methods, is provided in the information collection request (ICR) that the Bureau submitted to OMB under the requirements of the PRA. The ICR submitted to OMB requesting approval under the PRA for the information collection requirements contained herein is available at OMB's public-facing docket at <https://www.reginfo.gov/public/>.

VI. Signing Authority

The Director of the Bureau, Kathleen L. Kraninger, having reviewed and approved this document, is delegating the authority to electronically sign this document to Grace Feola, a Bureau Federal Register Liaison, for purposes of publication in the **Federal Register**.

Dated: November 30, 2020.

Grace Feola,

Federal Register Liaison, Bureau of Consumer Financial Protection.

[FR Doc. 2020-26661 Filed 12-2-20; 8:45 am]

BILLING CODE 4810-AM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1031; Project Identifier AD-2020-00846-T; Amendment 39-21334; AD 2020-24-04]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all The

Boeing Company Model 787-8, 787-9, and 787-10 airplanes. This AD requires revising the existing airplane flight manual (AFM) to incorporate procedures for conducting an approach with a localizer-based navigation aid, monitoring localizer raw data, calling out any significant deviations, and performing an immediate go around if the airplane has not intercepted the final approach course as shown by the localizer deviation. This AD was prompted by reports that the autopilot flight director system (AFDS) failed to transition to the instrument landing system localizer (LOC) beam after the consistent localizer capture function in the flight control modules initiated a transition to capture LOC during approach. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 18, 2020.

The FAA must receive comments on this AD by January 19, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1031.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1031; or in person at Docket Operations

³⁰ See <https://beta.regulations.gov/docket/CFPB-2020-0019>.

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3539; email: frank.carreras@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA has received reports indicating that the AFDS failed to transition to the instrument landing system LOC beam after the consistent localizer capture function in the flight control modules initiated a transition to capture LOC during approach. This condition, if not addressed, could result in localizer overshoot leading to glideslope descent on the wrong heading. Combined with a lack of flight deck effects for a consistent localizer capture mode failure, this condition could result in a controlled flight into terrain.

FAA's Determination

The FAA is issuing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires revising the existing AFM to incorporate procedures for conducting an approach with a localizer-based navigation aid, monitoring localizer raw data, calling out any significant deviations, and performing an immediate go around if the airplane has not intercepted the final approach course as shown by the localizer deviation.

Interim Action

The FAA considers this AD interim action. The manufacturer is currently developing a modification that will address the unsafe condition identified in this AD. Once this modification is

developed, approved, and available, the FAA might consider additional rulemaking.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because the failure of the AFDS to transition to the instrument LOC beam, after the consistent localizer capture function in the flight control modules initiated a transition to capture LOC during approach, could result in localizer overshoot leading to glideslope descent on the wrong heading. Combined with a lack of flight deck effects for a consistent localizer capture mode failure, this condition could result in a controlled flight into terrain. In addition, the compliance time for the required action is shorter than the time necessary for the public to comment and for publication of the final rule. Therefore, the FAA finds good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reasons stated above, the FAA finds that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written comments, data, or views about this AD. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one copy of the comments. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-1031; Project Identifier AD-2020-00846-T" at the beginning of your comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other

information as described in 14 CFR 11.35, the FAA will post all comments received, without change, as well as a report summarizing each substantive public contact with FAA personnel concerning this AD. The FAA will consider all comments received by the closing date for comments. The FAA may amend this AD because of those comments.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3539; email: frank.carreras@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 144 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise the AFM	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$12,240

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020–24–04 The Boeing Company:
Amendment 39–21334 ; Docket No. FAA–2020–1031; Project Identifier AD–2020–00846–T.

(a) Effective Date

This AD is effective December 18, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 787–8, 787–9, and 787–10 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Unsafe Condition

This AD was prompted by reports indicating that the autopilot flight director system (AFDS) failed to transition to the instrument landing system localizer (LOC) beam after the consistent localizer capture function in the flight control modules initiated a transition to capture LOC during approach. The FAA is issuing this AD to address the AFDS failing to transition, which could result in localizer overshoot leading to glideslope descent on the wrong heading. Combined with a lack of flight deck effects for a consistent localizer capture mode failure, this condition could result in a controlled flight into terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revise the Airplane Flight Manual (AFM)

Within 14 days after the effective date of this AD, revise the limitations section of the existing AFM and applicable corresponding operational procedures to incorporate the procedures specified in figure 1 to paragraph (g) of this AD. Revising the existing AFM to include the changes specified in paragraph (g) of this AD may be done by inserting a copy of figure 1 to paragraph (g) of this AD into the existing AFM.

Figure 1 to paragraph (g) – *Operating Instructions*

Operating Instructions:

(Required by AD 2020-24-04)

When conducting an approach with a localizer-based navigation aid, monitor localizer raw data and call out any significant deviations. If AFDS performance is not satisfactory, the flight crew must intervene. Perform an immediate go-around if the airplane has not intercepted the final approach course as shown by the localizer deviation.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this

AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make

those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(i) Related Information

For more information about this AD, contact Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3539; email: frank.carreras@faa.gov.

(j) Material Incorporated by Reference

None.

Issued on November 13, 2020.

Lance T. Gant,*Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2020-26680 Filed 12-1-20; 11:15 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF HOMELAND
SECURITY****Coast Guard****33 CFR Part 117**

[Docket No. USCG-2020-0658]

**Drawbridge Operation Regulation;
Indian Creek, Miami Beach, FL****AGENCY:** Coast Guard, DHS.**ACTION:** Notification of temporary deviation from regulations; request for comments.

SUMMARY: The Coast Guard has issued a temporary deviation from the operating schedule that governs the 63rd Street Bridge across Indian Creek, mile 4.0, at Miami Beach, Florida. A request was made to place the drawbridge on a weekend operating schedule to alleviate vehicle congestion due to on demand bridge openings. This deviation will test a change to the drawbridge operation schedule to determine whether a permanent change to the schedule is needed. The Coast Guard is seeking comments from the public regarding these proposed changes.

DATES: This deviation is effective from 12:01 a.m. on December 14, 2020, through 11:59 p.m. on June 11, 2021.

Comments and relate material must reach the Coast Guard on or before February 11, 2021.

ADDRESSES: You may submit comments identified by docket number USCG-2020-0658 using Federal eRulemaking Portal at <https://www.regulations.gov>.

See the "Public Participation and Request for Comments" portion of the **SUPPLEMENTARY INFORMATION** section below for instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions on this test deviation, call or email LT Samuel Rodriguez-Gonzalez, U.S. Coast Guard, Sector Miami Waterways Management Division; telephone 305-535-4307, email Samuel.Rodriguez-Gonzalez@uscg.mil.

SUPPLEMENTARY INFORMATION:**I. Background, Purpose and Legal Basis**

The 63rd Street Bridge across Indian Creek, mile 4.0, at Miami Beach, Florida is a double-leaf bascule bridge with an 11 foot vertical clearance at mean high water in the closed position. The normal operating schedule for the bridge is set forth in 33 CFR 117.293. Navigation on the waterway is commercial and recreational.

A private citizen requested the Coast Guard consider placing the drawbridge on a weekend operating schedule to alleviate vehicle congestion due to on demand bridge openings. The Coast Guard contacted the bridge owner, Florida Department of Transportation (FDOT), and requested a copy of the bridge logs for the month of August 2020. After reviewing the logs, the Coast Guard determined placing the bridge on a schedule during the weekend may alleviate vehicle congestion while maintaining the reasonable needs of navigation. This test deviation provides for scheduled opening times on Saturdays and Sundays. There will be no change to the published weekday operating schedule.

Under this test deviation, from 7 a.m. to 7 p.m., the draw shall open on the hour and half-hour; except Federal Holidays and all other times, the draw shall operate on demand. From 7:10 a.m. to 9:55 a.m. and 4:05 p.m. to 6:59 p.m., Monday through Friday, except Federal Holidays, the draw need not open for the passage of vessels. In February of each year during the period seven days prior to the City of Miami Beach Yacht and Brokerage Show and the four days following the show, from 10 a.m. to 4 p.m., the bridge need not open except for 10 minutes at the top of the hour. At all other times the bridge shall operate on its normal schedule.

The Coast Guard will also inform the users of the waterways through our Local and Broadcast Notices to Mariners of the change in operating schedule for the bridge so that vessel operators can arrange their transits to minimize any impact caused by the temporary deviation.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.

II. Public Participation and Request for Comments

We view public participation as essential to effective rulemaking, and will consider all comments and material received during the comment period.

Your comment can help shape the outcome of this rulemaking. If you submit a comment, please include the docket number for this rulemaking, indicate the specific section of this document to which each comment applies, and provide a reason for each suggestion or recommendation.

We encourage you to submit comments through the Federal eRulemaking Portal at <https://www.regulations.gov>. If your material cannot be submitted using <https://www.regulations.gov>, contact the person in the **FOR FURTHER INFORMATION CONTACT** section of this document for alternate instructions.

We accept anonymous comments. All comments received will be posted without change to <https://www.regulations.gov> and will include any personal information you have provided. For more about privacy and submissions in response to this document, see DHS's eRulemaking System of Records notice (85 FR 14226, March 11, 2020).

Documents mentioned in this notification as being available in this docket and all public comments, will be in our online docket at <https://www.regulations.gov> and can be viewed by following that website's instructions. Additionally, if you go to the online docket and sign up for email alerts, you will be notified when comments are posted or a final rule is published.

Dated: November 23, 2020.

Randall D. Overton,*Director, Bridge Administration, Seventh
Coast Guard District.*

[FR Doc. 2020-26415 Filed 12-2-20; 8:45 am]

BILLING CODE 9110-04-P

**DEPARTMENT OF HOMELAND
SECURITY****Coast Guard****33 CFR Part 165**

[Docket Number USCG-2020-0641]

RIN 1625-AA08

**Safety Zone; Lower Mississippi River,
Natchez, MS****AGENCY:** Coast Guard, DHS.**ACTION:** Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary safety zone for all navigable waters of the Lower Mississippi River between Mile Marker (MM) 364.5 and MM 365.5. This action is necessary to provide for the safety of persons, vessels, and the marine environment during a fireworks display.