

Rules and Regulations

Federal Register

Vol. 90, No. 223

Friday, November 21, 2025

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-4004; Project Identifier MCAI-2025-01666-R; Amendment 39-23195; AD 2025-23-52]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model EC130B4 and EC130T2 helicopters. The FAA previously sent this AD as an emergency AD to all known U.S. owners and operators of these helicopters. This AD was prompted by a determination that the service life limit of the center shaft assembly needs to be corrected because a crack could initiate on the center shaft assembly. This AD requires replacing the center shaft assembly with a serviceable center shaft assembly (either a shaft with another part number (P/N) or the same P/N with lower hours time-in-service (TIS)). This AD also prohibits installing a center shaft assembly that is not a serviceable center shaft assembly on any helicopter. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 8, 2025. Emergency AD 2025-23-52, issued on November 10, 2025, which contains the requirements of this amendment, was effective with actual notice.

The Director of the Federal Register approved the incorporation by reference of a certain publication identified in this AD as of December 8, 2025.

The FAA must receive comments on this AD by January 5, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-4004; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-4004.

FOR FURTHER INFORMATION CONTACT:

William McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (404) 474-5548; email: william.mccully@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the **ADDRESSES** section. Include "Docket No. FAA-2025-4004; Project Identifier

MCAI-2025-01666-R" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to William McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued Emergency AD 2025-23-52, dated November 10, 2025 (also referred to as the emergency AD), to address an unsafe condition on Airbus Helicopters Model EC130B4 and EC130T2 helicopters. The FAA sent the emergency AD to all known U.S. owners and operators of these helicopters. The emergency AD requires replacing the center shaft assembly with a serviceable center shaft assembly (either a shaft with another P/N or the same P/N with lower hours TIS). The emergency AD

also prohibited installing a center shaft assembly that is not a serviceable center shaft assembly on any helicopter.

The emergency AD was prompted by EASA Emergency AD 2025–0249–E, dated November 7, 2025 (EASA Emergency AD 2025–0249–E) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition on Airbus Helicopters Model EC130B4 and EC130T2 helicopters. The MCAI states that fatigue testing revealed the service life limit of the center shaft assembly needs to be corrected because a crack could initiate on the center shaft assembly, P/N 350A34021401 (Manufacturer P/N 350A34–0214–01), in the riveted area and propagate until failure. The emergency AD was prompted by a determination that the service life limit of the center shaft assembly needs to be corrected because a crack could initiate on the center shaft assembly. The emergency AD is intended to address cracking on the center shaft assembly. This condition could result in structural failure of the tail rotor drive shaft with consequent loss of control of a helicopter.

The FAA is issuing this AD to address cracking on a center shaft assembly. The unsafe condition could result in structural failure of the tail rotor drive shaft with consequent loss of control of a helicopter.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA–2025–4004.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA Emergency AD 2025–0249–E, which specifies procedures for replacing the center shaft assembly with a serviceable center shaft assembly (either a shaft with another P/N or the same P/N with lower hours TIS). EASA Emergency AD 2025–0249–E also prohibits installing a center shaft assembly that is not a serviceable center shaft assembly on any helicopter.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

These products have been approved by the civil aviation authority (CAA) of another country and are approved for operation in the United States. Pursuant

to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in EASA Emergency AD 2025–0249–E, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some CAA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA Emergency AD 2025–0249–E is incorporated by reference in this AD. This AD requires compliance with EASA Emergency AD 2025–0249–E in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA Emergency AD 2025–0249–E does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled ‘Required Action(s) and Compliance Time(s)’ in EASA Emergency AD 2025–0249–E. Material required by EASA Emergency AD 2025–0249–E for compliance will be available at regulations.gov under Docket No. FAA–2025–4004 after this AD is published.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good

cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that required the immediate adoption of Emergency AD 2025–23–52, issued on November 10, 2025, to all known U.S. owners and operators of these helicopters. The FAA found that the risk to the flying public justified forgoing notice and comment prior to adoption of this rule because cracks in the center shaft assembly could already exist and if not immediately addressed could lead to structural failure of the tail rotor drive shaft with consequent loss of control of a helicopter. About 100 of the 304 helicopters on the U.S. Registry are over the fatigue threshold and will require replacement within 10 hours TIS, and about half of the affected helicopters operate 30 or more hours TIS per month and could require replacement within 10 days. These compliance times are shorter than the time necessary for the public to comment and for the publication of the final rule. These conditions still exist, therefore, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forego notice and comment.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Interim Action

The FAA considers that this AD is an interim action. If final action is later identified, the FAA might consider additional rulemaking.

Costs of Compliance

The FAA estimates that this AD affects 304 helicopters of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace the center shaft assembly	12 work-hours × \$85 per hour = \$1,020	\$26,890	\$27,910	\$8,484,640

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025-23-52 Airbus Helicopters:

Amendment 39-23195; Docket No. FAA-2025-4004; Project Identifier MCAI-2025-01666-R.

(a) Effective Date

The FAA issued Emergency Airworthiness Directive (AD) 2025-23-52 on November 10, 2025 (also referred to as the emergency AD), directly to affected owners and operators. As a result of such actual notice, that emergency AD was effective for those owners and operators on the date it was received. This AD contains the same requirements as the emergency AD and, for those who did not receive actual notice, is effective on December 8, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model EC130B4 and EC130T2 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6510, Tail Rotor Drive Shaft.

(e) Unsafe Condition

This AD was prompted by a determination that the service life limit of the center shaft assembly needs to be corrected because a crack could initiate on the center shaft assembly. The FAA is issuing this AD to address cracking on a center shaft assembly. The unsafe condition, if not addressed, could result in structural failure of the tail rotor drive shaft with consequent loss of control of a helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency Emergency AD 2025-0249-E, dated November 7, 2025 (EASA Emergency AD 2025-0249-E).

(h) Exceptions to EASA Emergency AD 2025-0249-E

(1) Where EASA Emergency AD 2025-0249-E refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA Emergency AD 2025-0249-E requires compliance in terms of flight

hours, this AD requires using hours time-in-service.

(3) This AD does not adopt the "Remarks" section of EASA Emergency AD 2025-0249-E.

(i) No Reporting and Return of Parts Requirements

Although the material referenced in EASA Emergency AD 2025-0249-E specifies to submit certain information to the manufacturer and to return the parts to the manufacturer, this AD does not require any of these actions.

(j) Special Flight Permits

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Additional Information

For more information about this AD, contact Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (404) 474-5548; email: william.mccully@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2025-0249-E, dated November 7, 2025.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information

on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on November 17, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-20575 Filed 11-20-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-4003; Project Identifier MCAI-2025-01205-E; Amendment 39-23194; AD 2025-23-10]

RIN 2120-AA64

Airworthiness Directives: Rolls-Royce Deutschland Ltd & Co KG Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Rolls-Royce Deutschland Ltd & Co KG (RRD) Model Trent 1000-A, Trent 1000-AE, Trent 1000-C, Trent 1000-CE, Trent 1000-D, Trent 1000-E, Trent 1000-G, Trent 1000-H, Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines. This AD was prompted by an investigation which revealed that certain low-pressure compressor (LPC) fan blades are at risk of cracking due to incorrect dressing. This AD requires inspecting the LPC fan blades for evidence of incorrect dressing, and replacement if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 8, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 8, 2025.

The FAA must receive comments on this AD by January 5, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to regulations.gov. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-4003; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-4003.

FOR FURTHER INFORMATION CONTACT:

Alexis Whitaker, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (516) 228-7309; email: alexis.j.whitaker@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-4003; Project Identifier MCAI-2025-01205-E” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the

following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Alexis Whitaker, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued European Union Aviation Safety Agency AD 2025-0143, dated July 08, 2025 (EASA AD 2025-0143) (also referred to as the MCAI), to correct an unsafe condition on all RRD Model Trent 1000-A, Trent 1000-AE, Trent 1000-C, Trent 1000-CE, Trent 1000-D, Trent 1000-E, Trent 1000-G, Trent 1000-H, Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines. The MCAI states that an investigation revealed that certain LPC fan blades are at risk of cracking due to incorrect dressing, which may have been performed on areas of low wall thickness and high localized internal stress levels. To address this unsafe condition, the manufacturer published service information that specifies procedures for inspection of affected LPC fan blades for evidence of incorrect dressing and replacement. This condition, if not addressed, could lead to fan blade failure and release of uncontained high-energy debris with