

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-19-01 Pacific Aerospace Corporation, Ltd: Amendment 39-15191; Docket No. FAA-2007-27865; Directorate Identifier 2007-CE-039-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 17, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model 750XL airplanes, all serial numbers, certificated in any category, that have not incorporated Pacific Aerospace Limited Service Letter PACSL/XL/07-1, dated April 18, 2007, with Pacific Aerospace LTD Drawing, 11-03129, Issue B or subsequent, in its entirety.

Subject

(d) Air Transport Association of America (ATA) Code 56: Windows.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

To prevent the cockpit door windows separating from their frames, * * * The MCAI requires you to inspect the windscreen and cockpit door windows for signs of disbonding of the adhesive between the transparency and the composite window frame. If disbonding is evident, you must do the required modification.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 50 hours time-in-service (TIS) after October 17, 2007 (the effective date of this AD) and thereafter at intervals not to exceed 50 hours TIS, inspect the windscreen and cockpit door windows for signs of disbonding of the adhesive between the transparency and the composite window frame following Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/024 (embodiment of modification PAC/XL/0276) and PAC Drawing No. 11-03137, both dated February 20, 2007 (undated). If you find disbanding during any inspection required by this AD, before further flight, modify the windscreen and cockpit windows to incorporate mechanical fasteners following Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/024 (embodiment of modification PAC/XL/0276) and PAC Drawing No. 11-03137 both dated February 20, 2007.

(2) Within the next 150 hours TIS after October 17, 2007 (the effective date of this AD) or within the next 6 months after October 17, 2007 (the effective date of this AD), whichever occurs first, modify the

windscreen and cockpit windows to incorporate mechanical fasteners following Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/024 (embodiment of modification PAC/XL/0276) and PAC Drawing No. 11-03137 both dated February 20, 2007. The requirement of paragraph (f)(1) of this AD to do repetitive inspections is no longer necessary when the modification of paragraph (f)(2) of this AD is done.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Civil Aviation Authority of New Zealand AD DCA/750XL/10, dated March 29, 2007; Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/024 (embodiment of modification PAC/XL/0276) and PAC Drawing No. 11-03137 both dated February 20, 2007; and Pacific Aerospace Limited Service Letter PACSL/XL/07-1, dated April 18, 2007, with Pacific Aerospace LTD Drawing, 11-03129, Issue B or subsequent, for related information.

Material Incorporated by Reference

(i) You must use Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/024 (embodiment of modification PAC/XL/0276) and PAC Drawing No. 11-03137 both dated February 20, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Pacific Aerospace Limited, Hamilton Airport, Private Bag, 3027 Hamilton, New Zealand; telephone: +64 7-843-6144; facsimile: +64 7-843-6134.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on September 4, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-17828 Filed 9-11-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26043; Directorate Identifier 2005-NM-010-AD; Amendment 39-15193; AD 2007-19-03]

RIN 2120-AA64**Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes**

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all McDonnell Douglas Model 717-200 airplanes. This AD requires inspecting the power conversion distribution unit (PCDU) to determine its part number, and modifying certain PCDUs. This AD results from reports of failed PCDUs, the loss of an electrical bus, and the presence of a strong electrical burning odor in the flight deck and forward cabin. We are issuing this AD to prevent the loss of an electrical bus due to PCDU failure, resulting in the loss of all flight displays for an unacceptable time period, and consequent emergency landing.

DATES: This AD becomes effective October 17, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of October 17, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building

Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Thomas Phan, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5342; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Operations office

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground floor of the West Building at the DOT street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all McDonnell Douglas Model 717-200 airplanes. That supplemental NPRM was published in the **Federal Register** on June 6, 2007 (72 FR 31206). That supplemental NPRM proposed to require inspecting the power conversion distribution unit (PCDU) to determine its part number, and modifying certain PCDUs. That supplemental NPRM also proposed to re-identify the part number reference for the proposed corrective action.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been received on the supplemental NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed in the supplemental NPRM.

Costs of Compliance

There are about 137 airplanes of the affected design in the worldwide fleet, of which about 108 airplanes are U.S. registered. The following tables provide the estimated costs for U.S. operators to comply with this AD. The total fleet cost could be as high as \$434,592.

ESTIMATED COSTS FOR PRIMARY ACTIONS

Primary actions	Work hours	Labor rate per hour	Parts cost	Cost per airplane
Part number identification	1	\$80	\$0	\$80
Modification (Boeing Alert Service Bulletin 717-24A0028)	12	80	0	960

ESTIMATED COSTS FOR CONCURRENT ACTIONS

Hamilton Sundstrand Service Bulletin	Work hours	Labor rate per hour	Parts cost	Cost per airplane
40EGS22P-24-3	6	\$80	\$154, per airplane	\$634.
40EGS22P-24-4	3	80	0	240.
40EGS22P-24-6	3	80	0	240.
40EGS22P-24-7	1 per PCDU, maximum 3 PCDUs per airplane.	80	10 per PCDU, maximum 3 PCDUs per airplane.	270 (maximum).
40EGS22P-24-8	10	80	0	800.
40EGS22P-24-9	10	80	0	800.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2007-19-03 McDonnell Douglas:
Amendment 39-15193. Docket No. FAA-2006-26043; Directorate Identifier 2005-NM-010-AD.

Effective Date

(a) This AD becomes effective October 17, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all McDonnell Douglas Model 717-200 airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from reports of failed power conversion distribution units (PCDUs), the loss of an electrical bus, and the presence of a strong electrical burning odor in the flight deck and forward cabin. We are issuing this AD to prevent the loss of an electrical bus due to PCPU failure, resulting in the loss of all flight displays for an unacceptable time period, and consequent emergency landing.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Identification of PCPU Part Number

(f) Within 20 months after the effective date of this AD, inspect the PCPU to determine its part number. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number can be conclusively determined from that review.

(1) If the part number is below 762904E, do the actions specified in paragraphs (g) and (h) of this AD.

(2) If the part number is 762904E or higher, no further work is required by this AD.

Modification

(g) Within 20 months after the effective date of this AD, modify the PCPU in accordance with Boeing Alert Service Bulletin 717-24A0028, Revision 1, dated December 20, 2005. A modification done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 717-24A0028, dated November 24, 2004, is acceptable for compliance with the requirements of this paragraph.

Note 1: Boeing Alert Service Bulletin 717-24A0028 refers to Hamilton Sundstrand Service Bulletin 40EGS22P-24-10, Revision 1, dated May 11, 2005, as an additional source of service information for the modification.

Concurrent Requirements

(h) Before or concurrently with the modification required by paragraph (g) of this AD, do the applicable actions specified in Table 1 of this AD.

TABLE 1.—CONCURRENT REQUIREMENTS

Do the following—	In accordance with Hamilton Sundstrand Service Bulletin—
Rework the transformer rectifier unit assembly (TRU)	40EGS22P-24-3, dated June 30, 2000.
Rework the W3 wiring harness assembly to install direct lead wires to the TRU	
Add a ground wire to the TRU transformer	
Add an insulated spacer to the PCPU top cover	
Install new PCPU 186 firmware	40EGS22P-24-4, Revision 1, dated January 2, 2002.
Install new PCPU 186 firmware	40EGS22P-24-6, dated July 25, 2002.
Modify the top cover of the PCPU	40EGS22P-24-7, dated September 3, 2003.
Modify printed wiring board (PWB) assemblies A4 and A5	40EGS22P-24-8, dated September 4, 2003.
Check and apply torque seal to fasteners on the TRU assembly and to PCPU internal fasteners, as applicable	
Modify PWB assembly A4	40EGS22P-24-9, dated November 19, 2003.

Credit for Accomplishment of Earlier Service Bulletin

(i) Installation of new PCPU 186 firmware before the effective date of this AD in accordance with Hamilton Sundstrand Service Bulletin 40EGS22P-24-4, dated April 26, 2001, is acceptable for compliance with the corresponding requirements of paragraph (h) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on

any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(k) You must use the service documents identified in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Service Bulletin	Revision level	Date
Boeing Alert Service Bulletin 717-24A0028	1	December 20, 2005.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-3	Original	June 30, 2000.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-4	1	January 2, 2002.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-6	Original	July 25, 2002.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-7	Original	September 3, 2003.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-8	Original	September 4, 2003.
Hamilton Sundstrand Service Bulletin 40EGS22P-24-9	Original	November 19, 2003.

Hamilton Sundstrand Service Bulletin 40EGS22P-24-4, Revision 1, dated January 2, 2002, has the following effective pages:

Page Nos.	Revision level shown on page	Date shown on page
1, 3, 4, 5, 6, 7, 8	1	January 2, 2002.
2	Original	April 26, 2001.

The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 4, 2007.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-17844 Filed 9-11-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Parts 738, 740, 745, 772, and 774

[Docket No. 070705267-7492-01]

RIN 0694-AE08

Implementation of the Understandings Reached at the June 2007 Australia Group (AG) Plenary Meeting; Addition to the List of States Parties to the Chemical Weapons Convention (CWC)

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Industry and Security (BIS) is publishing this final rule to amend the Export Administration Regulations (EAR) to implement the understandings reached at the June 2007 plenary meeting of the Australia Group (AG). This final rule amends the EAR to reflect changes to the AG "Control List of Biological Agents" that the countries participating in the AG adopted at the plenary meeting. Specifically, this rule revises the Commerce Control List (CCL) entry that controls animal pathogens on the

AG "Control List of Biological Agents" by revising the listing for mycoplasma mycoides to include only the specific subspecies and strains of mycoplasma mycoides that are of most concern as the causative agents of disease in animals, i.e., *Mycoplasma mycoides* subspecies mycoides SC (small colony) and *Mycoplasma capricolum* subspecies capripneumoniae ("strain F38"). In addition, this rule makes conforming changes to the CCL entry that controls certain select agents not included on any of the AG Common Control Lists.

This rule also amends the EAR to reflect the admission of Croatia to the Australia Group and updates the definition of "Australia Group" in the EAR by adding Croatia to the list of participating countries.

In addition to the AG plenary meeting changes described above, this rule amends the EAR by revising the CCL entry that controls certain equipment capable of being used in handling biological materials. This rule revises a Technical Note in the CCL entry by updating the edition of the World Health Organization (WHO) "Laboratory Biosafety Manual" referenced therein to identify the current edition of the manual. This WHO manual contains safety requirements for P3 or P4 (BL3, BL4, L3, L4) complete containment facilities.

Finally, this rule amends the list of countries that currently are States Parties to the Chemical Weapons Convention (CWC) by adding "Barbados," which recently became a State Party. As a result of this change, the CW (Chemical Weapons) license requirements and policies in the EAR that apply to Barbados now conform with those applicable to other CWC States Parties. This rule also clarifies the scope of the entry for "China" on the list of CWC States Parties by revising the footnote to this entry to indicate that, for CWC purposes only, China includes "Macau," as well as "Hong Kong."

DATES: This rule is effective September 12, 2007. Although there is no formal comment period, public comments on this regulation are welcome on a continuing basis.

ADDRESSES: You may submit comments, identified by RIN 0694-AE08, by any of the following methods:

- **E-mail:** publiccomments@bis.doc.gov. Include "RIN 0694-AE08" in the subject line of the message.
- **Fax:** (202) 482-3355. Please alert the Regulatory Policy Division, by calling (202) 482-2440, if you are faxing comments.
- **Mail or Hand Delivery/Courier:** Willard Fisher, U.S. Department of Commerce, Bureau of Industry and Security, Regulatory Policy Division, 14th St. & Pennsylvania Avenue, NW., Room 2705, Washington, DC 20230, ATTN: RIN 0694-AE08.

Send comments regarding this collection of information, including suggestions for reducing the burden, to David Rostker, Office of Management and Budget (OMB), by e-mail to David_Rostker@omb.eop.gov, or by fax to (202) 395-7285; and to the Regulatory Policy Division, Bureau of Industry and Security, Department of Commerce, P.O. Box 273, Washington, DC 20044. Comments on this collection of information should be submitted separately from comments on the final rule (i.e., RIN 0694-AE08)—all comments on the latter should be submitted by one of the three methods outlined above.

FOR FURTHER INFORMATION CONTACT: Elizabeth Scott, Director, Chemical and Biological Controls Division, Office of Nonproliferation and Treaty Compliance, Bureau of Industry and Security, Telephone: (202) 482-3343.

SUPPLEMENTARY INFORMATION:

Background

The Bureau of Industry and Security (BIS) is amending the Export Administration Regulations (EAR) to implement the understandings reached at the annual plenary meeting of the Australia Group (AG) that was held in Paris on June 4-7, 2007. The Australia Group is a multilateral forum, consisting of 40 participating countries, that maintains export controls on a list of chemicals, biological agents, and related equipment and technology that could be used in a chemical or biological weapons program. The AG periodically