

**§ 403.11 [Amended]**

■ 2. Section 403.11(b)(12) is amended by replacing the word “Criminal” with the phrase “National Security”.

**PART 407—REGULATIONS GOVERNING PUBLIC OBSERVATION OF EX-IM BANK MEETINGS**

■ 3. The authority citation for part 407 continues to read as follows:

**Authority:** Sec. (g) Government in the Sunshine Act, 5 U.S.C. 552b(g); secs. (b) through (f), 5 U.S.C. 552b.

■ 4. Amend § 407.1 as follows:

- a. Revise paragraph (b) to read as set forth below.
- b. In paragraph (c), remove “9:00” and add in its place “9:30”.

**§ 407.1 Purpose, scope and definitions.**

\* \* \* \* \*

(b) The term *meeting* means any meeting of the Board of Directors of Eximbank at which a quorum is present and where deliberations determine or result in the joint conduct or disposition of official Eximbank business.

\* \* \* \* \*

**§ 407.2 [Amended]**

■ 5. Amend § 407.2(a) introductory text by removing the phrase “or the Executive Committee”.

**§ 407.2 [Amended]**

- 6. Amend § 407.3 as follows:
  - a. In paragraph (a), remove the phrase “or the Executive Committee”, and remove “9:00” and add in its place “9:30”.
  - b. In paragraph (b), remove the phrase “or the Executive Committee”.

**§ 407.4 [Amended]**

■ 5. Amend § 407.4 by removing the phrase “or the Executive Committee” wherever it appears.

**§ 407.6 [Amended]**

- 6. Amend § 407.6 by removing the phrase “or the Executive Committee”.
- 7. Part 414 is added to read as follows:

**PART 414—CONFERENCE AND OTHER FEES**

**Authority:** 12 U.S.C. 635(a)(1), 5 U.S.C. 553.

**§ 414.1 Collection of conference and other fees.**

Ex-Im Bank may impose and collect reasonable fees to cover the costs of conferences and seminars sponsored by, and publications provided by Ex-Im Bank. Amounts received under the preceding sentence shall be credited to the fund which initially paid for such

activities and shall be offset against the expenses of Ex-Im Bank for such activities.

**Howard A. Schweitzer,**  
*General Counsel.*

[FR Doc. 07-5807 Filed 11-26-07; 8:45 am]

**BILLING CODE 6690-01-M**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. **FAA-2007-0247**; Directorate Identifier **2007-CE-083-AD**; Amendment **39-15278**; **AD 2007-24-12**]

**RIN 2120-AA64**

**Airworthiness Directives; Eclipse Aviation Corporation Model EA500 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Eclipse Aviation Corporation Model (Eclipse) EA500 airplanes. This AD requires you to inspect the fuel filler adapters for primer and/or paint in the surround and, if present, remove the primer and/or paint. This AD results from an observation during a factory walk-around that the fuel filler surround was primed instead of being bare metal. We are issuing this AD to inspect and, if necessary, remove any paint and/or primer to restore the fuel filler adapter lightning strike protection. A lightning strike on the filler cap with insulating primer on the surround could result in the strike not dissipating to the surround. This could lead to arcing and ignition of fuel vapor inside the fuel tank.

**DATES:** This AD becomes effective on November 27, 2007.

On November 27, 2007, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

We must receive any comments on this AD by January 28, 2008.

**ADDRESSES:** Use one of the following addresses to comment on this AD.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

To get the service information identified in this AD, contact Eclipse Aviation Corporation, 4100 Aerospace Parkway, Albuquerque, New Mexico 87121; phone (505) 245-7555; fax: (505) 241-8802; email: [customercare@EclipseAviation.com](mailto:customercare@EclipseAviation.com).

To view the comments to this AD, go to <http://www.regulations.gov>. The docket number is FAA-2007-0247; Directorate Identifier 2007-CE-083-AD.

**FOR FURTHER INFORMATION CONTACT:** Mitchell Soth, Flight Test Engineer, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone: (817) 222-5104; fax: (817) 222-5960.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

The aircraft type certification requires compliance to 14 CFR 23.954, Fuel system lightning protection. During the lightning protection testing of certain Eclipse Model EA500 airplanes, it was determined that the fuel filler surround required exposed bare metal to dissipate arc products when the fuel filler cap is struck by lightning. We were notified by Eclipse that, during a factory walk-around, they observed that the fuel filler surround was primed instead of being bare metal. The affected airplanes are only those with the extended tip tanks (ETT).

A lightning strike on the filler cap with insulating primer on the surround could result in the strike not dissipating to the surround. This could lead to arcing and ignition of fuel vapor inside the fuel tank.

**Relevant Service Information**

We reviewed Eclipse Aviation Corporation Alert Service Bulletin SB 500-57-007, Rev A, dated October 12, 2007, and Eclipse Aviation Corporation Alert Service Bulletin SB 500-57-007, Rev B, dated October 23, 2007. The service information describes procedures for inspecting the fuel filler fitting surround for primer and/or paint and removing the primer and/or paint if found.

**FAA’s Determination and Requirements of This AD**

We are issuing this AD because we evaluated all the information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design. This AD requires you to

inspect and if necessary restore the fuel filler adapter lightning strike protection by removing any primer and/or paint from the fuel filler adapter surround.

In preparing this rule, we contacted type clubs and aircraft operators to get technical information and information on operational and economic impacts. We did not receive any information through these contacts. If received, we would have included a discussion of any information that may have influenced this action in the rulemaking docket.

**FAA’s Determination of the Effective Date**

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule, because a lightning strike to the fuel filler cap might not properly dissipate to the surround and could cause arcing and ignition of fuel vapor inside the fuel tank. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

**Comments Invited**

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and an opportunity for public comment. We invite you to send any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number “FAA–2007–0247; Directorate Identifier 2007–CE–083–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive concerning this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

**Examining the AD Docket**

You may examine the AD docket that contains the AD, the regulatory evaluation, any comments received, and other information on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

The Docket Office (telephone (800) 647–5527) is located at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2007–24–12 Eclipse Aviation Corporation:**  
Amendment 39–15278; Docket No. FAA–2007–0247; Directorate Identifier 2007–CE–083–AD.

**Effective Date**

(a) This AD becomes effective on November 27, 2007.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Model EA500 airplanes, serial numbers 000039 through 000062, that are certificated in any category.

**Unsafe Condition**

(d) This AD results from an observation during a factory walk-around that the fuel filler surround was primed instead of being bare metal. We are issuing this AD to inspect and, if necessary, remove any paint and/or primer to restore the fuel filler adapter lightning strike protection. A lightning strike on the filler cap with insulating primer on the surround could result in the strike not dissipating to the surround. This could lead to arcing and ignition of fuel vapor inside the fuel tank.

**Compliance**

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) Inspect the right and left fuel filler adapters for application of primer and/or paint.	At whichever of the following occurs first: (i) Within 10 hours time-in-service (TIS) after November 27, 2007 (the effective date of this AD). (ii) Within 30 days after November 27, 2007 (the effective date of this AD).	Follow the procedures in Eclipse Aviation Corporation Alert Service Bulletin SB 500–57–007, Rev A, dated October 12, 2007, or Eclipse Aviation Corporation Alert Service Bulletin SB 500–57–007, Rev B, dated October 23, 2007.

Actions	Compliance	Procedures
(2) Remove any primer and/or paint from the fuel filler adapter surround.	Before further flight after the inspection required by paragraph (e)(1) of this AD where primer and/or paint was found on the fuel filler adapter surround.	Follow the procedures in Eclipse Aviation Corporation Alert Service Bulletin SB 500-57-007, Rev B, dated October 23, 2007.

### Special Flight Permit

(f) Under 14 CFR 39.23, we are limiting the special flight permits for this AD by allowing "Flight in Day Visual Flight Rules (VFR) Only."

### Alternative Methods of Compliance (AMOCs)

(g) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mitchell Soth, Flight Test Engineer, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone: (817) 222-5104; fax: (817) 222-5960. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

### Material Incorporated by Reference

(h) You must use Eclipse Aviation Corporation Alert Service Bulletin SB 500-57-007, Rev A, dated October 12, 2007 or Eclipse Aviation Corporation Alert Service Bulletin SB 500-57-007, Rev B, dated October 23, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Eclipse Aviation Corporation, 4100 Aerospace Parkway, Albuquerque, New Mexico 87121; phone (505) 245-7555; fax: (505) 241-8802; e-mail: [customer-care@EclipseAviation.com](mailto:customer-care@EclipseAviation.com).

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on November 20, 2007.

#### Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-23024 Filed 11-26-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 45

[Docket No. FAA-2007-27173; Amendment No. 45-25]

RIN 2120-AJ02

#### Nationality and Registration Marks; Non Fixed-Wing Aircraft

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Direct final rule confirmation of effective date.

**SUMMARY:** This action confirms the direct final rule issued on September 14, 2007, which became effective on November 13, 2007. The rule changes certain display requirements for nationality and registration marks for powered parachutes and weight-shift-control aircraft. No comments were received on this direct final rule.

**DATES:** The direct final rule published at 72 FR 52467 is confirmed effective November 13, 2007.

**ADDRESSES:** The complete docket for the direct final rule on nationality and registration marks; non fixed-wing aircraft, Docket ID FAA-2007-27173 may be examined at <http://www.regulations.gov> at any time or go to Docket Operations in Room W12-140 of the West Building, Ground Floor, at 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** Grant Schneemann, AIR-230, Airworthiness Branch, Production and Airworthiness Division, Aircraft Certification Service, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone (202) 267-8473.

#### SUPPLEMENTARY INFORMATION:

#### Background

On September 14, 2007, the FAA published a direct final rule (72 FR 52467) that permits operators of U.S. registered powered parachutes and weight-shift-control aircraft to display their nationality and registration marks in other than a horizontal orientation on the fuselage, a structural member, or a

component of the aircraft. The direct final rule also clarifies the size requirements for nationality and registration marks on U.S. registered powered parachutes and weight-shift-control aircraft.

#### Discussion of Comments

The FAA received no comments on the nationality and registration marks; non fixed-wing aircraft direct final rule.

#### Conclusion

In consideration that no comments were submitted in response to the direct final rule, the FAA has determined that no further rulemaking action is necessary. Amendment 45-25 remains in effect as adopted.

Issued in Washington, DC, on November 20, 2007.

**John Hickey,**

Director, Aircraft Certification Services.

[FR Doc. E7-23028 Filed 11-26-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### Food and Drug Administration

#### 21 CFR Part 558

#### New Animal Drugs For Use in Animal Feeds; Fenbendazole

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Final rule.

**SUMMARY:** The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of a supplemental new animal drug application (NADA) filed by Intervet Inc. The supplemental NADA provides for a revised food safety warning on labeling for fenbendazole Type A medicated article and Type B and Type C medicated horse feeds.

**DATES:** This rule is effective November 27, 2007.

**FOR FURTHER INFORMATION CONTACT:** Melanie R. Berson, Center for Veterinary Medicine (HFV-110), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-827-7540, e-mail: [melanie.berson@fda.hhs.gov](mailto:melanie.berson@fda.hhs.gov).

**SUPPLEMENTARY INFORMATION:** Intervet Inc., P.O. Box 318, 29160 Intervet Lane,