a parapet, such that the roofing material is *not* visible from the public right-of-way.
—Installation of gutter guards/covers over existing gutters in a manner that respects size and profile.
—Installation of protective roof coverings while working on other projects and stabilizing damaged roof areas before commencing maintenance or preservation work.
—Fastening roof elements using corrosion-resistant roof fasteners (nails and clips).
—Installation of photovoltaic equipment and supporting infrastructure on roof top when not visible from the public right-of-way.
—Skylights: maintenance, preservation and repair of skylights.
—Maintenance, preservation and repair of decorative features on roofs.
—Repair or replacement of existing rooftop-mounted equipment such as HVAC components, tie-offs, ductwork, window-washing equipment, and lightning protection equipment.

Windows and Doors

—Reglazing, caulking, weatherstripping, re-puttying windows and doors, and repairs to windows and doors, not including window or door replacement.
—Protecting wood or metal window frames and trim by cleaning, paint removal and reapplication of protective coating systems. Replacing broken or missing operable components.
—Installation of interior storm windows.

Curtain Walls

—Repairs and limited replacement of elements damaged or degraded beyond practicable repair of wall assemblies or exterior cladding when the color, size, reflectivity, materials, and visual patterns are unaltered.

Envelope

—Cleaning brick and stone (masonry) and stucco exteriors with low pressure wash (150–200 PSI), natural bristle brushes, and mild detergents.
—Re-pointing exterior masonry, ensuring correct mortar testing and match for composition, color, and appropriate compressive strength for the historic masonry assembly being repointed, and with appropriate means and tools.
—Masonry or stucco repairs.
—Refinishing and varnishing of exterior wood.
—Limited replacement of missing portions of exterior wood and consolidation of deteriorated portions of exterior wood with putties and repainting.
—Mothballing for a period no longer than ten (10) years.

Exterior Elements

—Repair of exterior metal elements including balconies and stair handrails.
—Rewiring and restoration of character defining ornamental lighting fixtures.
—Re-lamping light fixtures with energy-efficient lamps.
—Masonry repairs of stairs, wing walls, plazas, ramps, and site furniture.
—Cleaning and repointing of brick and stone (masonry) exterior elements as listed above in ''Envelope'' section.
—Repairs or limited replacements of character-defining decorative features.

Preservation—Interior Spaces, Features, Finishes

Windows and Doors

—Repair and replacement of missing or damaged window and door finish hardware.
—Replacement of removable interior window film and installation of solar screens.
—Installation and replacement of window treatments.

Finishes

—Plaster repair: repair of cracks, missing plastered areas, re-plastering of non-decorative walls that are plastered or were formerly plastered, which cannot be repaired in their present state.
—Select repair of small portions of decorative plaster elements where there are visible cracks or chips.
—Interior wood refinishing and revarnishing.
—Floor refinishing.
—Carpeting installation.
—Replacement of floors, walls, secondary stairs, ceilings and/or trim.
—Installation or replacement of non-character-defining lighting.
—Rewiring and preservation of character-defining, ornamental lighting fixtures.
—Re-lamping light fixtures with energy-efficient lamps.
—Removal and replacement of building contents including furniture, movable partitions, and cabinetry and equipment and any other non-character-defining moveable items.

(END OF DOCUMENT)

Authority: 36 CFR 800.14(c).

Dated: January 18, 2023.

Javier Marqués,

General Counsel.

[FR Doc. 2023–01188 Filed 1–20–23; 8:45 am]

BILLING CODE 4310–K6–P

DEPARTMENT OF THE INTERIOR

Bureau of Land Management

[BLM_WY_FRN_M04500169025]

Filing of Plats of Survey, Wyoming and Nebraska

AGENCY: Bureau of Land Management, Interior.

ACTION: Notice of official filing.

SUMMARY: The Bureau of Land Management (BLM) is scheduled to file plats of survey 30 calendar days from the date of this publication in the BLM Wyoming State Office, Cheyenne, Wyoming. These surveys, which were executed at the request of the U.S. Forest Service and the BLM are necessary for the management of these lands.

DATES: Protests must be received by the BLM prior to the scheduled date of official filing by February 22, 2023.

ADDRESSES: You may submit written protests to the Wyoming State Director at WY926, Bureau of Land Management, 5353 Yellowstone Road, Cheyenne, Wyoming 82009.

FOR FURTHER INFORMATION CONTACT: Sonja Sparks, BLM Wyoming Chief Cadastral Surveyor, by telephone at 307 775–6225 or by email at *s75spark@blm.gov.* Persons who use a telecommunications device for the deaf (TDD) may call the Federal Relay Service at 1–800–877–8339 to contact this office during normal business hours. The Service is available 24 hours a day, 7 days a week, to leave a message or question with this office. You will receive a reply during normal business hours.

SUPPLEMENTARY INFORMATION: The plats of survey of the following described lands are scheduled to be officially filed in the BLM Wyoming State Office, Cheyenne, Wyoming.

Sixth Principal Meridian, Wyoming

T. 49 N., R. 93 W., Group No. WY1036, dependent resurvey and survey, accepted October 14, 2022
T. 15 N., R. 75 W., Group No. WY1038, dependent resurvey and survey, accepted November 18, 2022
T. 42 N., R. 67 W., Group No. WY1039, dependent resurvey and survey, accepted November 18, 2022
T. 16 N., R. 80 W., Group No. WY1042, dependent resurvey, accepted January 4, 2023
T. 18 N., R. 80 W., Group No. WY1044, dependent resurvey and survey, accepted January 4, 2023

Sixth Principal Meridian, Nebraska

T. 30 N., R. 50 W., Group No. NE0191, dependent resurvey and survey,

accepted October 19, 2022
T. 31 N., R. 50 W., Group No. NE0191, dependent resurvey and survey, accepted October 19, 2022

A person or party who wishes to protest one or more plats of survey identified in this notice must file a written notice of protest within 30 calendar days from the date of this publication with the Wyoming State Director at the above address. Any notice of protest received after the scheduled date of official filing will be untimely and will not be considered. A written statement of reasons in support of a protest, if not filed with the notice of protest, must be filed with the State Director within 30 calendar days after the notice of protest is filed. If a notice of protest against a plat of survey is received prior to the scheduled date of official filing, the official filing of the plat of survey identified in the notice of protest will be stayed pending consideration of the protest. A plat of survey will not be officially filed until the next business day following dismissal or resolution of all protests of the plat.

Before including your address, phone number, email address, or other personal identifying information in your protest, you should be aware that your entire protest—including your personal identifying information—may be made publicly available at any time. While you can ask us to withhold your personal identifying information from public review, we cannot guarantee that we will be able to do so.

Copies of the preceding described plat and field notes are available to the public at a cost of $4.20 per plat and $0.15 per page of field notes. Requests can be made to *blm_wy_survey_records@blm.gov* or by telephone at 307–775–6222.

(Authority: 43 U.S.C., chapter 3)

Dated: January 12, 2023.

Sonja S. Sparks,

Chief Cadastral Surveyor of Wyoming and Nebraska.

[FR Doc. 2023–01165 Filed 1–20–23; 8:45 am]

BILLING CODE 4331–26–P

DEPARTMENT OF THE INTERIOR

National Park Service

[NPS–IMR–PETR–34690; PS.SIMLA0106.00.1]

Minor Boundary Revision at Petroglyph National Monument

AGENCY: National Park Service, Interior.

ACTION: Notification of boundary revision.

SUMMARY: The boundary of Petroglyph National Monument is modified to exclude four parcels of land from the monument boundary which contain private homes and property, totaling 8.37 acres and to include two parcels of land containing 3.78 acres, located in Bernalillo County, New Mexico. Upon publication of the Notice, the National Park Service will accept, by donation, a perpetual easement (3.47 acres) from Albuquerque Public Schools (APS). The other tract to be included in the boundary (0.31 acres) is already federally owned.

DATES: The effective date of this boundary revision is January 23, 2023.

ADDRESSES: The map depicting this boundary revision is available for inspection at the following locations: National Park Service, Interior Regions 6, 7, & 8, Land Resources Program Center, 12795 West Alameda Parkway, Denver, Colorado 80228 and National Park Service, Department of the Interior, 1849 C Street NW, Washington, DC 20240.

FOR FURTHER INFORMATION CONTACT: Regional Realty Officer William Morgan, National Park Service, Interior Regions 6, 7, & 8 Land Resources Program Center, 12795 West Alameda Parkway, Denver, Colorado 80228, telephone (303) 969–2610, *william_morgan@nps.gov.*

SUPPLEMENTARY INFORMATION: Notice is hereby given that, pursuant to Public Law 101–313, the boundary of Petroglyph National Monument is modified to exclude four (4) tracts totaling 8.37 acres of land and expanded to include two tracts (2) totaling approximately 3.78 acres of adjacent unimproved land. The boundary revision is depicted on Map No. 354/179645, dated September 2022.

Public Law 101–313 section 102(c) authorizes minor revisions of the boundary, after completion of the general management plan for the monument, by publishing a revised map or other boundary description in the **Federal Register**. The general management plan for Petroglyph National Monument was completed in 1996. This boundary revision will ensure the preservation and protection of the Monument's historic and cultural landscape resources and provide public access into the Petroglyph National Monument.

Katharine Hammond,

Regional Director (Acting), Interior Regions 6, 7, & 8.

[FR Doc. 2023–01106 Filed 1–20–23; 8:45 am]

BILLING CODE 4312–52–P

INTERNATIONAL TRADE COMMISSION

[Investigation No. 337–TA–1309]

Certain Core Orientation Systems, Products Containing Core Orientation Systems, Components Thereof, and Methods of Using the Same; Notice of a Commission Determination Not To Review an Initial Determination Terminating the Investigation Based on a Consent Order Stipulation; Issuance of a Consent Order; Termination of the Investigation

AGENCY: International Trade Commission.

ACTION: Notice.

SUMMARY: Notice is hereby given that the U.S. International Trade Commission has determined not to review an initial determination (''ID'') (Order No. 31) of the presiding administrative law judge (''ALJ'') granting a joint motion to terminate the investigation as to the remaining respondents based on a consent order stipulation. The Commission has entered a consent order against respondents Boart Longyear Group Ltd.; Boart Longyear Limited; Boart Longyear Company; Boart Longyear Manufacturing and Distribution Inc.; Longyear TM, Inc.; Globaltech Corporation Pty Ltd.; Globaltech Pty Ltd.; and International Directional Services LLC (collectively, ''Remaining Respondents''). The investigation is terminated in its entirety.

FOR FURTHER INFORMATION CONTACT: Cathy Chen, Office of the General Counsel, U.S. International Trade Commission, 500 E Street SW, Washington, DC 20436, telephone 202–205–2392. Copies of non-confidential documents filed in connection with this investigation may be viewed on the Commission's electronic docket (EDIS) at *https://edis.usitc.gov.* For help accessing EDIS, please email *EDIS3Help@usitc.gov.* General information concerning the Commission may also be obtained by accessing its internet server at *https://www.usitc.gov.* Hearing-impaired persons are advised that information on this matter can be obtained by contacting the Commission's TDD terminal on (202) 205–1810.

SUPPLEMENTARY INFORMATION: The Commission instituted this investigation on April 5, 2022, based on a complaint filed on behalf of Australian Mud Company Pty Ltd. of Australia and Reflex USA LLC of Chandler, AZ (collectively, ''Complainants''). 87 FR 19704 (Apr. 5, 2022). The complaint, as