

be made by the party in charge of operations.

(c) In the event of the incapacity or absence from the State of Oklahoma of such designated local or resident representative, Lessee shall appoint a substitute to serve in his stead. In the absence of such representative or appointed substitute, any employee of Lessee upon the leased premises or person in charge of drilling or related operations thereon shall be considered the representative of Lessee for the purpose of service of orders or notices as herein provided.

§ 226.32 Well records and reports.

(a) Lessee shall keep accurate and complete records of the drilling, re-drilling, deepening, repairing, treating, plugging, or abandonment of all wells. These records shall show all the formations penetrated, the content and character of oil, gas, or water in each formation, and the kind, weight, size, landed depth and cement record of casing used in drilling each well; the record of drill-stem and other bottom hole pressure or fluid sample surveys, temperature surveys, directional surveys, and the like; the materials and procedure used in the treating or plugging of wells or in preparing them for temporary abandonment; and any other information obtained in the course of well operation.

(b) Lessee shall take such samples and make such tests and surveys as may be required by the Superintendent to determine conditions in the well or producing reservoir and to obtain information concerning formations drilled, and shall furnish reports there-of as required by the Superintendent.

(c) Within 10 days after completion of operations on any well, Lessee shall transmit to the Superintendent the applicable information on forms furnished by the Superintendent; a copy of electrical, mechanical or radioactive log, or other types of survey of the well bore; and core analysis obtained from the well. Lessee shall also submit other reports and records of operations as may be required and in the manner and form prescribed by the Superintendent.

(d) Lessee shall measure production of oil, gas, and water from individual wells at reasonably frequent intervals

to the satisfaction of the Superintendent.

(e) Upon request and in the manner and form prescribed by the Superintendent, Lessee shall furnish a plat showing the location, designation, and status of all wells on the leased lands, together with such other pertinent information as the Superintendent may require.

§ 226.33 Line drilling.

Lessee shall not drill within 300 feet of boundary line of leased lands, nor locate any well or tank within 200 feet of any public highway, any established watering place, or any building used as a dwelling, granary, or barn, except with the written permission of the Superintendent. Failure to obtain advance written permission from the Superintendent shall subject lessee to cancellation of his/her lease and/or plugging of the well.

[39 FR 22254, June 21, 1974. Redesignated at 47 FR 13327, Mar. 30, 1982, as amended at 55 FR 33116, Aug. 14, 1990]

§ 226.34 Wells and tank batteries to be marked.

Lessee shall clearly and permanently mark all wells and tank batteries in a conspicuous place with number, legal description, operator, and telephone number, and shall take all necessary precautions to preserve these markings.

[55 FR 33116, Aug. 14, 1990]

§ 226.35 Formations to be protected.

Lessee shall, to the satisfaction of the Superintendent, take all proper precautions and measures to prevent damage or pollution of oil, gas, fresh water, or other mineral bearing formations.

§ 226.36 Control devices.

In drilling operations in fields where high pressures, lost circulation, or other conditions exist which could result in blowouts, lessee shall install an approved gate valve or other controlling device which is in proper working