

The FAA estimates that it would take approximately 1 work hour per airplane to accomplish the proposed visual inspections, at an average labor rate of \$60 per work hour. Based on these figures, the total cost impact of the proposed visual inspections on U.S. operators is estimated to be \$14,220, or \$60 per airplane, per inspection cycle.

The FAA estimates that it would take approximately 2 work hours per airplane to accomplish the proposed eddy current inspection, at an average labor rate of \$60 per work hour. Based on these figures, the total cost impact of the proposed eddy current inspection on U.S. operators is estimated to be \$28,440, or \$120 per airplane.

The FAA estimates that it would take approximately 6 work hours per airplane to accomplish the proposed replacement of the 12 attachments located at the banjo No. 4 fitting, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$250 per airplane. Based on these figures, the total cost impact of the proposed replacement on U.S. operators is estimated to be \$144,570, or \$610 per airplane.

The total cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 95-NM-48-AD.

Applicability: Model DC-10-10, -15, -30, -40 series airplanes and KC-10A (military) airplanes; as listed in McDonnell Douglas Service Bulletin 55-23, Revision 1, dated December 17, 1993; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of fail safe capability of the vertical stabilizer due to cracking of its attachments, accomplish the following:

(a) Within one year after the effective date of this AD, perform a visual inspection, using a minimum 5X power magnifying glass, to detect failure of the 12 attachments located in the banjo No. 4 fitting of the vertical stabilizer (as depicted in McDonnell Douglas Service Bulletin 55-23, Revision 1, dated December 17, 1993). Perform this inspection in accordance with procedures specified in McDonnell Douglas Nondestructive Testing Manual Chapter 20-10-00 or McDonnell Douglas Nondestructive Testing Standard Practice Manual, Part 09.

(1) If no failure is detected, repeat the visual inspection thereafter at intervals not to

exceed one year until the requirements of paragraph (b) of this AD are accomplished.

(2) If any failure is detected, prior to further flight, accomplish the requirements of paragraph (b) of this AD.

(b) Except as required by paragraph (a)(2) of this AD: Within 5 years after the effective date of this AD, perform an eddy current inspection to detect cracking of the forward and aft flanges and bolt holes of the banjo No. 4 fitting and the pylon carry-through cap, in accordance with McDonnell Douglas Service Bulletin 55-23, Revision 1, dated December 17, 1993.

(1) If no cracking is detected, prior to further flight, replace the 12 attachments located on the banjo No. 4 fitting in accordance with the service bulletin. Accomplishment of this replacement terminates the requirements of this AD.

(2) If any cracking is detected, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office, (ACO), FAA, Transport Airplane Directorate.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 12, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-17550 Filed 7-17-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 95-AWP-6]

Proposed Realignment of V-485; CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would alter VOR Federal Airway V-485 from the Priest, CA, Very High Frequency Omnidirectional Range/Tactical Air Navigation (VORTAC) to the San Jose, CA, Very High Frequency Omnidirectional Range/Distance Measuring Equipment (VOR/DME). This action would collocate V-485 with the San Jose VOR/DME Runway 30L approach and utilize the San Jose VOR/

DME instead of the Sausalito VORTAC. This action would enhance safety while accommodating the concerns of the airspace users.

DATES: Comments must be received on or before August 23, 1995.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Air Traffic Division, AWP-500, Docket No. 95-AWP-6, Federal Aviation Administration, P. O. Box 92007, Worldway Postal Center, Los Angeles, CA 90009.

The official docket may be examined in the Rules Docket, Office of the Chief Counsel, Room 916, 800 Independence Avenue, SW., Washington, DC, weekdays, except Federal holidays, between 8:30 a.m. and 5:00 p.m.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division.

FOR FURTHER INFORMATION CONTACT: Norman W. Thomas, Airspace and Obstruction Evaluation Branch (ATP-240), Airspace-Rules and Aeronautical Information Division, Air Traffic Rules and Procedures Service, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-9230.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 95-AWP-6." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments

submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-220, 800 Independence Avenue SW., Washington, DC 20591, or by calling (202) 267-3485. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to alter VOR Federal Airway V-485 from the Priest, CA, VORTAC to the San Jose, CA, VOR/DME. This action would collocate V-485 with the San Jose VOR/DME Runway 30L approach and utilize the San Jose VOR/DME instead of the Sausalito VORTAC. This action would enhance safety while accommodating the concerns of the airspace users. Domestic VOR Federal airways are published in paragraph 6010(a) of FAA Order 7400.9B dated July 18, 1994, and effective September 16, 1994, which is incorporated by reference in 14 CFR 71.1. The airway listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—[AMENDED]

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 49 U.S.C. 106(g); 14 CFR 11.69.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9B, Airspace Designations and Reporting Points, dated July 18, 1994, and effective September 16, 1994, is amended as follows:

Paragraph 6010(a)—Domestic VOR Federal Airways

* * * * *

V-485 [Revised]

From Ventura, CA; Fellows, CA; Priest, CA; to San Jose, CA. The airspace within W-289, the airspace within R-2519 more than 3-statute miles W of the airway centerline and the airspace within R-2519 below 5,000 feet MSL is excluded.

* * * * *

Issued in Washington, DC, on July 6, 1995.

Nancy B. Kalinowski,

Acting Manager, Airspace-Rules and Aeronautical Information Division.

[FR Doc. 95-17586 Filed 7-17-95; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 35

[Docket Nos. RM95-8-000 and RM94-7-001]

Promoting Wholesale Competition Through Open Access Non-discriminatory Transmission Services by Public Utilities; Recovery of Stranded Costs by Public Utilities and Transmitting Utilities; Notice of Intent to Prepare an Environmental Impact Statement for the Notice of Proposed Rulemaking and Request for Comments on Environmental Issues

July 12, 1995.

AGENCY: Federal Energy Regulatory Commission, DOE.