

influenza and Newcastle viruses still pose a threat in Mexico, and that these viruses could be present in improperly or inadequately dressed birds. Commenters also stated that wild turkeys killed by hunters could have internal or external fecal contamination as a result of damage caused by a bullet or an arrow passing through the bird, and pointed out that fecal shed of the avian influenza and Newcastle viruses has been documented. One commenter also suggested that the proposed change would encourage hunters to field dress their own game, rather than having the game dressed, cooked, and sealed by commercial services in the foreign country, which would increase the potential for contamination of the hunter's clothing and equipment with exotic disease agents.

After considering all the comments we received, we have concluded that it is necessary to reexamine the disease risk issues associated with the importation into the United States of wild turkey carcasses. Therefore, we are withdrawing the February 21, 1995, proposed rule referenced above. The concerns and recommendations of all the commenters will be considered if any new proposed regulations regarding the importation of wild turkey carcasses are developed.

Authority: 7 U.S.C. 147a, 150ee, 161, 162, and 450; 19 U.S.C. 1306; 21 U.S.C. 111, 114a, 134a, 134b, 134c, 134f, 136, and 136a; 31 U.S.C. 9701; 42 U.S.C. 4331, and 4332; 7 CFR 2.17, 2.51, and 371.2(d).

Done in Washington, DC, this 3rd day of October 1995.

Terry L. Medley,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 95-25014 Filed 10-6-95; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 95-ANE-44]

Airworthiness Directives; CFM International CFM56-3C Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to CFM International (CFMI) CFM56-3C series turbofan engines. This proposal would

require a reduction of the low cycle fatigue (LCF) retirement lives for certain fan disks. This proposal is prompted by the results of a refined life analysis performed by the manufacturer which revealed minimum calculated LCF lives significantly lower than published LCF retirement lives. The actions specified by the proposed AD are intended to prevent a LCF failure of the fan disk, which could result in an uncontained engine failure and damage to the aircraft.

DATES: Comments must be received by December 11, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-ANE-44, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Robert J. Ganley, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (617) 238-7138; fax (617) 238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following

statement is made: "Comments to Docket Number 95-ANE-44." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-ANE-44, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

This proposed airworthiness directive (AD) is applicable to CFM International (CFMI) CFM56-3C series turbofan engines. A study performed by the manufacturer using updated lifting analyses revealed that certain fan disks have minimum calculated low cycle fatigue (LCF) lives which are significantly lower than published LCF retirement lives. This condition, if not corrected, could result in a LCF failure of the fan disk, which could result in an uncontained engine failure and damage to the aircraft.

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require a reduction of the LCF retirement lives for certain fan disks.

The FAA estimates that 33 engines installed on aircraft of U.S. registry would be affected by this proposed AD, and that it would not take any additional work hours per engine to accomplish the proposed actions. Assuming that the parts cost is proportional to the reduction of the LCF retirement lives, the required parts would cost approximately \$17,275 per engine. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$570,075.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

CFM International: Docket No. 95-ANE-44.

Applicability: CFM International (CFMI) CFM56-3C series turbofan engines installed on, but not limited to Boeing 737 series aircraft.

Note: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) to request approval from the Federal Aviation Administration (FAA). This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any engine from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent a low cycle fatigue (LCF) failure of the fan disk, which could result in an uncontained engine failure and damage to the aircraft, accomplish the following:

(a) Remove from service CFM56-3C fan disks, Part Numbers 335-014-509-0 and 335-014-511-0, prior to accumulating the equivalent of 20,100 cycles at the Category C thrust rating.

(b) This action establishes the new LCF retirement life of 20,100 cycles noted in paragraph (a) of this AD, which is published in Chapter 05 of CFM56 Engine Shop Manual, CFMI-TP.SM.5.

(c) For the purpose of this AD, Category C thrust rating is defined as operation at CFM56-3C-1 engine nameplate model thrust levels.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on September 27, 1995.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 95-25033 Filed 10-6-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 95-AWP-23]

Proposed Establishment of Class E Airspace; Springerville, AZ

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish a Class E airspace area at Springerville/Babbitt Field Airport, Springerville, AZ. The development of a Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 21 has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Springerville/Babbitt Field Airport, Springerville, AZ.

DATES: Comments must be received on or before November 15, 1995.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, System Management Branch, AWP-530, Docket No. 95-AWP-23, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009.

The official docket may be examined in the Office of the Assistant Chief Counsel, Western Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California 90261.

An informal docket may also be examined during normal business at the Office of the Manager, System Management Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Speer, Airspace Specialist, System Management Branch, AWP-530, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725-6533.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire.

Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 95-AWP-23." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the System Management Branch, Air Traffic Division, at 15000 Aviation Boulevard, Lawndale, California 90261, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, System