

List of Subjects in 49 CFR Part 571

Imports, Motor vehicle safety, Motor vehicles.

In consideration of the foregoing, 49 CFR Part 571 is amended as follows:

PART 571—FEDERAL MOTOR VEHICLE SAFETY STANDARDS

1. The authority citation for Part 571 of Title 49 continues to read as follows:

Authority: 49 U.S.C. 322, 30111, 30115, 30117, and 30166; delegation of authority at 49 CFR 1.50.

2. Section 571.208 is amended by revising section S4.5.1(b)(1) to read as follows:

§ 571.208 Standard No. 208, Occupant Crash Protection

* * * * *

S4.5.1 Labeling and owner's manual information.

* * * * *

(b) Label on sun visor above front outboard seating positions equipped with inflatable restraint.

(1) Each vehicle manufactured on or after September 1, 1994, shall comply with either S4.5.1(b)(1)(i) or S4.5.1(b)(1)(ii), except that the word "WARNING" may be used instead of "CAUTION".

(i) Each front outboard seating position that provides an inflatable restraint shall have a label permanently affixed to the sun visor for such seating position on either side of the sun visor, at the manufacturer's option. Except as provided in S5.4.1(b)(1) and S4.5.1(b)(3), this label shall read:

CAUTION

TO AVOID SERIOUS INJURY:

For maximum safety protection in all types of crashes, you must always wear your safety belt.

Do not install rearward-facing child seats in any front passenger seat position.

Do not sit or lean unnecessarily close to the air bag.

Do not place any objects over the air bag or between the air bag and yourself.

See the owner's manual for further information and explanations.

(ii) If the vehicle is equipped with a cutoff device permitted by S4.5.4 of this standard, each front outboard seating position that provides an inflatable

restraint shall have a label permanently affixed to the sun visor for such seating position on either side of the sun visor, at the manufacturer's option. Except as provided in S5.4.1(b)(1), this label shall read:

CAUTION

TO AVOID SERIOUS INJURY:

For maximum safety protection in all types of crashes, you must always wear your safety belt.

Do not install rearward-facing child seats in any front passenger seat position, unless the air bag is off.

Do not sit or lean unnecessarily close to the air bag.

Do not place any objects over the air bag or between the air bag and yourself.

See the owner's manual for further information and explanations.

* * * * *

Issued on: March 18, 1996.

Barry Felrice,

Associate Administrator for Safety Performance Standards.

[FR Doc. 96-6965 Filed 3-25-96; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF COMMERCE

National Oceanic and Atmospheric Administration

50 CFR Part 675

[Docket No. 960129019-6019-01; I.D. 032096A]

Groundfish of the Bering Sea and Aleutian Islands Area; Yellowfin Sole by Vessels Using Trawl Gear in Bycatch Limitation Zone 1

AGENCY: National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

ACTION: Closure.

SUMMARY: NMFS is closing the directed fishery for yellowfin sole by vessels using trawl gear in Bycatch Limitation Zone 1 (Zone 1) of the Bering Sea and Aleutian Islands management area (BSAI). This action is necessary to prevent exceeding the first seasonal apportionment of the prohibited species catch (PSC) allowance of *C. bairdi* Tanner crab apportioned to the trawl

yellowfin sole fishery category in Zone 1.

EFFECTIVE DATE: 12 noon, Alaska local time (A.l.t.), March 20, 1996, until 12 noon, A.l.t., April 1, 1996.

FOR FURTHER INFORMATION CONTACT: Andrew N. Smoker, 907-586-7228.

SUPPLEMENTARY INFORMATION: The groundfish fishery in the BSAI exclusive economic zone is managed by NMFS according to the Fishery Management Plan for the Groundfish Fishery of the Bering Sea and Aleutian Islands Area (FMP) prepared by the North Pacific Fishery Management Council under authority of the Magnuson Fishery Conservation and Management Act. Fishing by U.S. vessels is governed by regulations implementing the FMP at 50 CFR parts 620 and 675.

The 1996 PSC allowance of *C. bairdi* Tanner crab in Zone 1 for the trawl yellowfin sole fishery category, which is defined at § 675.21(b)(1)(iii)(B)(1), was established by the Final 1996 Harvest Specifications of Groundfish (61 FR 4311, February 5, 1996) as 250,000 crab. The first seasonal bycatch apportionment of that allowance is 50,000 crab.

The Director, Alaska Region, NMFS, has determined, in accordance with § 675.21(c)(1)(i), that the first seasonal apportionment of the PSC allowance of *C. bairdi* Tanner crab for the trawl yellowfin sole fishery in Zone 1 has been reached. Therefore, NMFS is prohibiting directed fishing for yellowfin sole by vessels using trawl gear in Zone 1 of the BSAI.

Maximum retainable bycatch amounts for applicable gear types may be found in the regulations at § 675.20(h).

Classification

This action is taken under § 675.21 and is exempt from review under E.O. 12866.

Authority: 16 U.S.C. 1801 *et seq.*

Dated: March 20, 1996.

Richard W. Surdi,

Acting Director, Office of Fisheries Conservation and Management, National Marine Fisheries Service.

[FR Doc. 96-7182 Filed 3-20-96; 3:57 pm]

BILLING CODE 3510-22-F