

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 of the Federal Aviation Regulations as follows:

1. The authority citation for part 39 continues to read as follows:

PART 39—AIRWORTHINESS DIRECTIVES

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Airworthiness Directive (AD), 75-24-07 R1, Amendment 39-4571, and by adding a new AD to read as follows:

Pilatus Britten-Norman: Docket No. 96-CE-24-AD; Supersedes AD 75-24-07 R1, Amendment 39-4571.

Applicability: BN-2A and BN-2A Mk 111 airplanes (all serial numbers), certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated after the effective date of this AD, unless already accomplished. For operators who have not kept records of the landings of the airplane, use 3 landings per 1 hour time-in-service (TIS).

To prevent failure of the left-hand (LH) rudder bar assembly, which, if not detected and corrected, could result in loss of control of the airplane, accomplish the following:

(a) Within the next 500 landings after the effective date of this AD, inspect the LH

rudder bar unit for cracks (using a dye penetrant method), and measure the thickness/gauge of the LH slider tube in accordance with paragraph 1. of the ACTION Inspection section of Pilatus Britten-Norman (PBN) Service Bulletin (SB) No. BN-2/SB.111, Issue 1, dated October 25, 1977 or paragraphs 1 through 3 in the ACTION section of PBN BN-2/SB.56, Issue 2, dated February 13, 1978.

(1) If no cracks are visible, accomplish the following in accordance with paragraph 3a. and 3b. of the ACTION Inspection section of PBN SB No. BN-2/SB.111, dated October 25, 1977:

(i) For airplanes that have slider tubes with 17 gauge metal (.056-inch thick), continue to inspect the LH rudder bar assembly for cracks every 500 landings and,

(ii) Upon the total accumulation of 5,000 landings or within the next 500 landings after the effective date of this AD, whichever occurs later, accomplish Modification NB/M/948 by installing a new, strengthened slider tube unit, part number (P/N) NB-45-A1-2975, in accordance with the ACTION Rectification section of PBN SB BN-2/SB.111, dated October 25, 1977.

(iii) For airplanes that have slider tubes with 20 gauge metal (.036-inch) continue to inspect the LH rudder bar assembly for cracks every 250 landings and,

(iv) Upon the total accumulation of 2,500 landings or within the next 500 landings after the effective date of this AD, whichever occurs later, accomplish Modification NB/M/948 by installing a new, strengthened slider tube unit, part number (P/N) NB-45-A1-2975, in accordance with the ACTION Rectification section of PBN SB BN-2/SB.111, dated October 25, 1977.

(2) If cracks are visible during any inspection required by this AD, prior to further flight, accomplish Modification NB/M/948 in accordance with the ACTION Rectification section of PBN SB BN-2/SB.111, dated October 25, 1977.

(b) Accomplishing Modification NB/M/948 using P/N NB-45-A1-2975 at any time prior to the required number of accumulated landings in paragraphs (a)(1)(ii) and (iv) of this AD is terminating action for the repetitive inspections.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Division, FAA, Europe, Africa, and Middle East Office, c/o American Embassy, B-1000 Brussels, Belgium; or the Manager, Small Airplane Directorate, Aircraft Certification Service, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels Aircraft Certification Division or the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of

compliance with this AD, if any, may be obtained from the Brussels Aircraft Certification Division or the Small Airplane Directorate.

(e) All persons affected by this directive may obtain copies of the document referred to herein upon request to Pilatus Britten-Norman Ltd., Bembridge, Isle of Wight, United Kingdom PO35 5PR; telephone 44-1983 872511; facsimile 44-1983 873246; or may examine this document at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(f) This amendment supersedes AD 75-24-07 R1, Amendment 39-4571.

Issued in Kansas City, Missouri, on February 24, 1997.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-5157 Filed 2-28-97; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 97-AEA-04]

Proposed Establishment of Class E Airspace; Warren, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would establish Class E airspace at Warren, PA. The development of a new Standard Instrument Approach Procedure (SIAP), Helicopter Point In Space Approach, based on the Global Positioning System (GPS) and serving Warren General Hospital Heliport has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations to the heliport. The area would be depicted on aeronautical charts for pilot reference.

DATES: Comments must be received on or before April 10, 1997.

ADDRESSES: Send comments on the proposed rule in triplicate to: Manager, Operations Branch, AEA-530, Docket No. 97-AEA-04, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy Int'l Airport, Jamaica, NY 11430. The official docket may be examined in the Office of the Assistant Chief Counsel, AEA-7, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430.

An informal docket may also be examined during normal business hours in the Operations Branch, AEA-530, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, NY 11430.

FOR FURTHER INFORMATION CONTACT:

Mr. Francis T. Jordan, Jr., Airspace Specialist, Operations Branch, AEA-530, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430; telephone (718) 553-4521.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 97-AEA-04". The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in the light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with the FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Office of the Assistant Chief Counsel, AEA-7, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, NY 11430.

Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) to

establish Class E airspace extending upward from 700 feet above the surface (AGL) at Warren, PA. A GPS 314 Point in Space SIAP has been developed to serve Warren General Hospital Heliport. Additional controlled airspace extending upward from 700 feet above the surface (AGL) is needed to accommodate this SIAP and for IFR operations at the heliport. The area would be depicted on appropriate aeronautical charts. Class E airspace designations for airspace extending upward from 700 feet above the surface are published in Paragraph 6005 of FAA Order 7400.9D, dated September 4, 1996, and effective September 16, 1996, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that would only affect air traffic procedures and air navigation, it is certified that this proposed rule would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—[AMENDED]

1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 14 CFR 11.69

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9D, dated September 4, 1996, and effective September 16, 1996, is proposed to be amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AEA PA E5 Warren, PA [New]

Warren General Hospital Heliport, PA
Point In Space Coordinates

(Lat. 41°50'03" N., long. 79°08'11" W.)

That airspace extending upward from 700 feet above the surface within a 6-mile radius of the Point In Space serving Warren General Hospital Heliport.

* * * * *

Issued in Jamaica, New York, on February 20, 1997.

James K. Buckles,

Acting Manager, Air Traffic Division, Eastern Region.

[FR Doc. 97-5051 Filed 2-28-97; 8:45 am]

BILLING CODE 4910-13-M

14 CFR Part 71

[Airspace Docket No. 97-AEA-07]

Proposed Establishment of Class E Airspace; Frostburg, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would establish Class E airspace at Frostburg, PA. The development of a new Standard Instrument Approach Procedure (SIAP), Helicopter Point In Space Approach based on the Global Positioning System (GPS), and Serving Punxsutawney Area Hospital Heliport, has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations to the heliport. The area would be depicted on aeronautical charts for pilot reference.

DATES: Comments must be received on or before April 15, 1997.

ADDRESSES: Send comments on the proposed rule in triplicate to: Manager, Operations Branch, AEA-530, Docket No. 97-AEA-07, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy Int'l Airport, Jamaica, NY 11430. The official docket may be examined in the Office of the Assistant Chief Counsel, AEA-7, F.A.A. Eastern Region, Federal Building, #111, John F. Kennedy International Airport, Jamaica, New York 11430.

An informal docket may also be examined during normal business hours in the Operations Branch, AEA-530, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, NY 11430.

FOR FURTHER INFORMATION CONTACT: Mr. Francis T. Jordan, Jr., Airspace