

(1) Prior to further flight, remove the defective aileron, and replace it with a new or serviceable aileron. And

(2) Within 10 days after accomplishing the inspection required by paragraph (a) of this AD, submit a report of any findings of ailerons specified in paragraph (a) of this AD to the Manager, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2028; fax (425) 227-1181.

Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(c) As of the effective date of this AD, no person shall install on any airplane an aileron having any serial number and correlating part number identified in paragraph (a) of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) This amendment becomes effective on February 17, 1998.

Issued in Renton, Washington, on January 27, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 98-2528 Filed 1-30-98; 8:45 am]
BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-ASW-22]

Revision of Class D and E Airspace; McKinney, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This notice confirms the effective date of a direct final rule which revises Class D and E airspace at McKinney, TX.

EFFECTIVE DATE: The direct final rule published at 62 FR 62516 is effective 0901 UTC, February 26, 1998.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone: 817-222-5593.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on November 24, 1997 (62 FR 62516). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on February 26, 1998. No adverse comments were received, and thus this action confirms that this direct final rule will be effective on that date.

Issued in Fort Worth, TX, on January 21, 1998.

Albert L. Viselli,

Acting Manager, Air Traffic Division, Southwest Region.
[FR Doc. 98-2403 Filed 1-30-98; 8:45 am]
BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-ASW-21]

Revision of Class E Airspace; New Braunfels Municipal, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This notice confirms the effective date of a direct final rule which revises Class E airspace at New Braunfels Municipal Airport, New Braunfels, TX.

EFFECTIVE DATE: The direct final rule published at 62 FR 64269 is effective 0901 UTC, February 26, 1998.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone: 817-222-5593.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on December 5, 1997 (62 FR 64269). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on February 26, 1998. No adverse comments were received, and thus this action confirms that this direct final rule will be effective on that date.

Issued in Fort Worth, TX, on January 21, 1998.

Albert L. Viselli,

Acting Manager, Air Traffic Division, Southwest Region.
[FR Doc. 98-2404 Filed 1-30-98; 8:45 am]
BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-ASW-20]

Revision of Class E Airspace; Camden, AR

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This notice confirms the effective date of a direct final rule which revises Class E airspace at Camden, AR.

EFFECTIVE DATE: The direct final rule published at 62 FR 64271 is effective 0901 UTC, February 26, 1998.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air