

072215 (adding two half-shells on the spar) has been accomplished.

(2) If Modification 072214 has not been installed, comply with paragraphs 2.A., 2.B.1), 2.B.2(a), and 2.B.2(b) of the Accomplishment Instructions of Eurocopter France Service Bulletin No. 55.10, Revision 2, dated April 25, 1997 (service bulletin). If the fit and dimensions of the components specified in paragraph 2.B.2(a) exceed the tolerances in the applicable structural repair manual, replace with airworthy parts.

(3) If Modification 072215 has not been installed, first comply with paragraphs 2.A., 2.B.1), and 2.B.3), and then comply with paragraph 2.B.2(c) of the Accomplishment Instructions of the service bulletin.

Note 2: Modification kit P/N 315A-07-0221571 contains the necessary materials to accomplish this modification.

(b) Before the first flight of each day:

(1) Visually inspect the installation of the half-shells, the horizontal stabilizer supports, and the horizontal stabilizer for corrosion or cracks. Repair any corroded parts in accordance with the applicable maintenance manual. Replace any cracked components with airworthy parts before further flight.

(2) Confirm that there is no play in the horizontal stabilizer supports by lightly shaking the horizontal stabilizer. If play is detected, comply with paragraphs 2.A. and 2.B.2(a) of the service bulletin. If the fit and dimensions of the components specified in paragraph 2.B.2(a) exceed the tolerances in the applicable structural repair manual, replace with airworthy parts before further flight.

(c) At intervals not to exceed 400 hours time-in-service (TIS) or four calendar months, whichever occurs first, inspect and lubricate the spar tube attachment bolts.

(d) For stabilizers, P/N 3130-35-60-000, 3130-35-60-000-1, 3130-35-60-000-2, or 3130-35-60-000-3, within 90 calendar days and thereafter at intervals not to exceed 18 calendar months, visually inspect the inside of the horizontal spar tube in accordance with paragraph 2.A. and 2.B.1) of the service bulletin.

(1) If corrosion is found inside the tube, other than in the half-shell area, replace the tube with an airworthy tube within the next 500 hours TIS or 24 calendar months, whichever occurs first.

(2) If corrosion is found inside the tube in the half-shell area, apply a protective treatment as described in paragraph 2.B.1)b) of the service bulletin.

(e) For stabilizers, P/N 3130-35-60-000-4 or higher dash numbers, accomplish the following:

(1) At or before the next major inspection, 3200 hours total TIS, or 12 calendar years total TIS, whichever occurs first, and thereafter at each major inspection, visually inspect the inside of the horizontal spar tube in accordance with paragraph 2.A. and 2.B.1) of the service bulletin.

(2) If corrosion is found inside the tube, other than in the half-shell area, replace the tube with an airworthy tube within the next 500 hours TIS or 18 calendar months, whichever occurs first. If corrosion is found inside the tube in the half-shell area, apply a protective treatment as described in paragraph 2.B.1)b) of the service bulletin.

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Standards Staff, FAA, Rotorcraft Directorate. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Standards Staff.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Standards Staff.

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(h) The modification shall be done in accordance with Eurocopter France Service Bulletin No. 55.10, Revision 2, dated April 25, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) This amendment becomes effective on July 14, 1998.

Note 4: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 96-278-054(B)R1, dated May 21, 1997.

Issued in Fort Worth, Texas, on June 2, 1998.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 98-15198 Filed 6-8-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-ASW-24]

Revision of Class E Airspace; Intracoastal City, LA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This amendment revises the Class E airspace at Intracoastal City, LA. The development of four global positioning system (GPS) standard instrument approach procedures (SIAP), helicopter point-in-space approaches, to heliports in the Intracoastal City, LA, area has made this rule necessary. This

action is intended to provide adequate controlled airspace extending upward from 700 feet or more above the surface for instrument flight rules (IFR) operations to the heliports.

DATES: Effective 0901 UTC, October 8, 1998.

Comments must be received on or before July 24, 1998.

ADDRESSES: Send comments on the rule in triplicate to Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Docket No. 98-ASW-24, Fort Worth, TX 76193-0520. The official docket may be examined in the Office of the Regional Counsel, Southwest Region, Federal Aviation Administration, 2601 Meacham Boulevard, Room 663, Fort Worth, TX, between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the Airspace Branch, Traffic Division, Federal Aviation Administration, Southwest Region, Room 414, Fort Worth, TX.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone 817-222-5593.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR part 71 revises the Class E airspace at Intracoastal City, LA. The development of four GPS SIAP's helicopter point-in-space approaches, to heliports in the Intracoastal City, LA, area has made this rule necessary. This action is intended to provide adequate controlled airspace extending upward from 700 feet or more above the surface for IFR operations to the heliports.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.9E, dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the order.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in any adverse or negative comment and therefore is issuing it as a direct final rule. A substantial number of previous opportunities provided to the public to comment on substantially identical actions have resulted in negligible adverse comments or objections. Unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment, is

received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a final rule and was not preceded by a notice of proposed rulemaking, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action is needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA public contact concerned with the substance of this action will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-ASW-24." The postcard will be date stamped and returned to the commenter.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the states, on the relationship between the national government and the states, or on the distribution of power and

responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federal Assessment.

Further, the FAA has determined that this regulation is noncontroversial and unlikely to result in adverse or negative comments and only involves an established body of technical regulations that require frequent and routine amendments to keep them operationally current. Therefore, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Analysis because the anticipated impact is so minimal.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9E, *Airspace Designations and Reporting Points*, dated September 10, 1997, and effective September 16, 1997, is amended as follows:

Paragraph 6005: Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ASW LA E5 Intracostal City, LA [Revised]

Point In Space Coordinates
(Lat. 29°46'57" N., long. 92°08'42" W.)

That airspace extending upward from 700 feet above the surface within a 10-mile radius of the Point In Space serving Intracostal City heliports, excluding the airspace within the Lafayette, LA, Class E Airspace.

* * * * *

Issued in Fort Worth, TX, on May 22, 1998.

Albert L. Viselli,

*Acting Manager, Air Traffic Division,
Southwest Region.*

[FR Doc. 98-15313 Filed 6-8-98; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-ASW-25]

Revision of Class E Airspace; Venice, LA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This amendment revises the Class E airspace at Venice, LA. The development of two global positioning system (GPS) standard instrument approach procedures (SIAP), helicopter point-in-space approaches, to heliports in the Venice, LA, area has made this rule necessary. This action is intended to provide adequate controlled airspace extending upward from 700 feet or more above the surface from instrument flight rules (IFR) operations to the heliports.

DATES: Effective 0901 UTC, October 8, 1998.

Comments must be received on or before July 24, 1998.

ADDRESSES: Send comments on the rule in triplicate to Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Docket No. 98-ASW-25, Fort Worth, TX 76193-0520.

The official docket may be examined in the Office of the Regional Counsel, Southwest Region, Federal Aviation Administration, 2601 Meacham Boulevard, Room 663, Fort Worth, TX, between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Room 414, Fort Worth, TX.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort