

Washington, DC 20591; phone (202) 267-8844; fax (202) 267-5115; e-mail russell.unangst@faa.gov. The letter should describe interests in the tasks and state the experience and qualification he or she would bring to the committee. Each person submitting a letter of interest will be advised whether or not his or her request can be accommodated. To the extent possible, the composition of the advisory committee and working groups will be balanced among the aviation interests selected to participate.

Requests for appointment as a member of the advisory committee should be submitted on or before September 25, 2000.

The Secretary of Transportation has determined that the formation and use of advisory committees are necessary and in the public interest in connection with the performance of duties imposed on the FAA by law. Meetings of the Aircraft Repair and Maintenance Advisory Committee will be open to the public. Meetings of the working groups will not be open to the public, except to the extent that individuals or organizations with an interest and expertise are selected to participate. No public announcement of working group meetings will be made.

Issued in Washington, DC, on July 24, 2000.

**Angela B. Elgee,**

*Manager, Continuous Airworthiness Maintenance Division.*

[FR Doc. 00-18993 Filed 7-26-00; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### Notice of Intent To Rule on Application To Use the Revenue from a Passenger Facility Charge (PFC) at San Angelo Regional Airport, San Angelo, TX

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of intent to rule on application.

**SUMMARY:** The FAA proposes to rule and invites public comment on the application to use the revenue from a PFC at San Angelo Regional Airport under the provisions of the Aviation Safety and Capacity Expansion Act of 1990 (Title IX of the Omnibus Budget Reconciliation Act of 1990) (Public Law 101-508) and Part 158 of the Federal Aviation Regulations (14 CFR part 158).

**DATES:** Comments must be received on or before August 28, 2000.

**ADDRESSES:** Comments on this application may be mailed or delivered in triplicate copies to the FAA at the following address: Mr. G. Thomas Wade, Federal Aviation Administration, Southwest Region, Airports Division, Planning and Programming Branch, ASW-611, Fort Worth, Texas 76193-0610.

In addition, one copy of any comments submitted to the FAA must be mailed or delivered to Mr. Arboth A. Rylant, Manager of San Angelo Regional Airport at the following address: Mr. Arboth A. Rylant, Airport Director, San Angelo Regional Airport, 8618 Terminal Circle, Suite 101, San Angelo, TX 76904.

Air carriers and foreign air carriers may submit copies of the written comments previously provided to the Airport under section 158.23 of part 158.

**FOR FURTHER INFORMATION CONTACT:** Mr. G. Thomas Wade, Federal Aviation Administration, Southwest Region, Airports Division, Planning and Programming Branch, ASW-611, Fort Worth, Texas 76193-0610, (817) 222-5613.

The application may be reviewed in person at this same location.

**SUPPLEMENTARY INFORMATION:** The FAA proposes to rule and invites public comment on the application to use the revenue from a PFC at San Angelo Regional Airport under the provisions of the Aviation Safety and Capacity Expansion Act of 1990 (Title IX of the Omnibus Budget Reconciliation Act of 1990) (Public Law 101-508) and part 158 of the Federal Aviation Regulations (14 CFR part 158).

On July 11, 2000 the FAA determined that the application to impose and use the revenue from a PFC submitted by the Airport was substantially complete within the requirements of section 158.25 of part 158. The FAA will approve or disapprove the application, in whole or in part, no later than November 2, 2000.

The following is a brief overview of the application.

*Total estimated PFC revenue: \$96,410.  
PFC application number: 00-04-00-SJT.*

*Brief description of proposed project(s):*

#### Projects To Impose and Use PFC's

1. Acquire Ramp/Runway Sweeper
  2. Construct Replacement Aircraft Rescue and Fire Fighting Facility
- Any person may inspect the application in person at the FAA office listed above under **FOR FURTHER INFORMATION CONTACT** and at the FAA

regional Airports office located at: Federal Aviation Administration, Southwest Region, Airports Division, Planning and Programming Branch, ASW-610, 2601 Meacham Blvd., Fort Worth, Texas 76137-4298.

In addition, any person may, upon request, inspect the application, notice and other documents germane to the application in person at San Angelo Regional Airport.

Issued in Fort Worth, Texas on July 11, 2000.

**Naomi L. Saunders,**

*Manager, Airports Division.*

[FR Doc. 00-18992 Filed 7-26-00; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### Guidance for Demonstrating Compliance With Seat Dynamic Testing for Plinths and Pallets

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of interim means of compliance.

**SUMMARY:** This notice provides clarification of acceptable interim means for demonstrating compliance with the airworthiness standards for seats mounted on adapter plates of transport category airplanes. It is necessary to give the public guidance in this area and is intended to be used as a means of compliance until the FAA publishes superseding document(s).

**FOR FURTHER INFORMATION CONTACT:** Federal Aviation Administration, Attention: Jeff Gardlin, Airframe/Cabin Safety Branch, ANM-115, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue SW., Renton, WA 98055-4056; telephone (425) 227-2136, facsimile (425) 227-1320.

**SUPPLEMENTARY INFORMATION:** The information contained in this notice was taken directly from FAA Memorandum No. 00-115-7, dated May 1, 2000.

"The purpose of this memorandum is to transmit acceptable interim means to demonstrate compliance with § 25.562 of the FAR [Federal Aviation Regulations] for seats installed on adapter plates, sometimes referred to as "plinths" or "pallets".

"The attachment addressed a specific type of installation, for which the guidance contained in Advisory Circular (AC) 25.562-1A [Dynamic Evaluation of Seat Restraint Systems & Occupant Protection on Transport Airplanes], as clarified by Memorandum No. 00-115-3, may not provide sufficient information. Recent installations of multiple single-place seats into adapter plates, with