

Issued in Renton, Washington, on February 7, 2001.

Donald L. Rigglin,

Acting Manager, Transport Airplane
Directorate, Aircraft Certification Service.

[FR Doc. 01-3672 Filed 2-14-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-279-AD; Amendment 39-12117; AD 2001-03-13]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 707 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 707 series airplanes, that requires modification of certain areas of the upper skin of the wing. This amendment is necessary to prevent cracking of the upper skin of the wing, which could result in reduced structural integrity of the wing. This action is intended to address the identified unsafe condition.

DATES: Effective March 22, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: James Rehr, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2783; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 707 series airplanes was published in the **Federal Register** on November 28, 2000 (65 FR 70819). That action proposed to require modification of certain areas of the upper skin of the wing.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 5 airplanes of the affected design in the worldwide fleet. The FAA estimates that 1 airplane of U.S. registry will be affected by this AD, that it will take approximately 8 work hours to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on the single U.S. operator is estimated to be \$480.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules

Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-03-13 Boeing: Amendment 39-12117. Docket 2000-NM-279-AD.

Applicability: Model 707 series airplanes; as listed in Boeing Service Bulletin 2378, Revision 1, dated June 30, 1967; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent cracking of the upper skin of the wing, which could result in reduced structural integrity of the wing, accomplish the following:

Modification

(a) Prior to the accumulation of 20,000 total flight hours, or within 24 months after the effective date of this AD, whichever occurs later, modify the upper skin of the wing at wing stringers 10A and 11A on both the left- and right-hand wings of the airplane, in accordance with Boeing Service Bulletin 2378, Revision 1, dated June 30, 1967.

(b) During the high frequency eddy current inspection included as part of the modification required by paragraph (a) of this AD, if any crack is found, prior to further flight, repair in accordance with the applicable section of the Boeing 707 Structural Repair Manual.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Effective Date

(e) This amendment becomes effective on March 22, 2001.

Issued in Renton, Washington, on February 8, 2001.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 01-3695 Filed 2-14-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2000-8460; Notice No. 01-02]

RIN 2120-AH17

Airworthiness Directives

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); extension of comment period.

SUMMARY: This action extends the comment period for an NPRM that was published on January 12, 2001. In that document, the FAA proposed to move several standard provisions currently found in every airworthiness directive into its regulations pertaining to airworthiness directives. This extension is a result of a request from Helicopter Association International to extend the comment period to the proposal.

DATES: Comments must be received on or before March 29, 2001.

ADDRESSES: Address your comments to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2000-

8460 at the beginning of your comments, and you should submit two copies of your comments. If you wish to receive confirmation that FAA received your comments, include a self-addressed, stamped postcard.

You may also submit comments through the Internet to <http://dms.dot.gov>. You may review the public docket containing comments to these proposed regulations in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Dockets Office is on the plaza level of the NASSIF Building at the Department of Transportation at the above address. Also, you may review public dockets on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Donald Byrne, Assistant Chief Counsel, Regulations Division, AGC-200, Federal Aviation Administration, 800 Independence Ave., SW., Washington, DC 20591; telephone (202) 267-3073.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed action by submitting such written data, views, or arguments as they may desire. Comments relating to the environmental, energy, federalism, or economic impact that might result from adopting the proposals in this document also are invited. Substantive comments should be accompanied by cost estimates. Comments must identify the regulatory docket or notice number and be submitted in duplicate to the DOT Rules Docket address specified above.

All comments received, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking, will be filed in the docket. The docket is available for public inspection before and after the comment closing date.

All comments received on or before the closing date will be considered by the Administrator before taking action on this proposed rulemaking. Comments filed late will be considered as far as possible without incurring expense or delay. The proposals in this document may be changed in light of the comments received.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this document must include a pre-addressed, stamped postcard with those comments on which the following statement is made: "Comments to Docket No. FAA-2000-8460." The postcard will be date stamped and mailed to the commenter.

Availability of NPRMs

An electronic copy is available on the Internet by taking the following steps:

(1) Go to the search function of the Department of Transportation's electronic Docket Management System (DMS) Web page (<http://dms.dot.gov/search>).

(2) On the search page type in the last four digits of the Docket number shown at the beginning of this notice. Click on "search."

(3) On the next page, which contains the Docket summary information for the docket selected, click on the proposed rule.

An electronic copy is also available on the Internet through FAA's web page at <http://www.faa.gov/avr/arm/nprm/nprm.htm> or the **Federal Register's** web page at http://www.access.gpo.gov/su_docs/aces/aces140.html.

Further, a copy may be obtained by submitting a written request to the Federal Aviation Administration, Office of Rulemaking, ARM-1, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-9680. Make sure to identify the notice number or docket number of this proposed rule.

Background

On November 29, 2000, the Federal Aviation Administration (FAA) issued Notice No. 00-15, Airworthiness Directives (66 FR 3382, January 12, 2001). Comments to that document were to be received on or before February 12, 2001.

By letter dated January 31, 2001, Helicopter Association International requested that the FAA extend the comment period for Notice No. 00-15 until March 14, 2001, to allow HAI to comment on the proposed revisions to part 39. Although HAI requests only a 30 day extension of the comment period, the FAA believes a 45 day extension would be adequate for HAI and other interested persons to provide comment to Notice No. 00-15.

Extension of Comment Period

In accordance with § 11.47 of Title 14, Code of Federal Regulations, the FAA has reviewed the petition made by HAI for extension of the comment period to Notice No. 00-15. HAI has shown an interest in the proposed rule and good cause for the extension. The FAA also has determined that extension of the comment period is in the public interest, and that good cause exists for taking this action.