

operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Short Brothers PLC:** Docket 2001–NM–113–AD.

**Applicability:** All Model SD3–SHERPA, SD3–60, and SD3–60 SHERPA series airplanes; and Model SD3–30 series airplanes having PT6A–45R series engines; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the engines to reach adequate reserve takeoff power (RTOP) boost during takeoff, which could result in reduced controllability of the airplane, accomplish the following:

#### Repetitive Inspections/Corrective Action

(a) Within 100 flight cycles or 90 days after the effective date of this AD, whichever comes later: Do a test (check) of the power lever movement of the fuel control unit (FCU) lever to ensure the lever is contacting the maximum stop, and adjustment of the FCU rigging if the lever is not contacting the stop; an engine ground run for correct gas generator rotational speed, and a static reduced power check on each engine to ensure correct operation of the RTOP system; per Shorts Service Bulletin SD3 SHERPA–71–2, SD360 SHERPA–71–2, SD360–71–19, or SD330–71–24; all dated February 5, 2001; as applicable. Before further flight, do any follow-on actions necessary (includes a functional check of the RTOP solenoid, replacement of any defective RTOP solenoid with a new solenoid, adjustment of the RTOP system if system fails to provide adequate boost, adjustment to the torque of the FCU Ng servo valve, test for leakage or restrictions of the FCU pneumatic system, or overhaul of the FCU), per the applicable service bulletin. Repeat the tests (checks) after that at intervals not to exceed 90 days.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in British airworthiness directives 002–02–2001, 003–02–2001, 004–02–2001, and 005–02–2001.

Issued in Renton, Washington, on August 21, 2001.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01–21630 Filed 8–27–01; 8:45 am]

**BILLING CODE 4910–13–U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 01–AEA–22]

#### Proposed Amendment to Class E Airspace; Easton Memorial Hospital Heliport, Easton, MD

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This action proposes to establish Class E airspace at Easton, MD. The development of a Standard Instrument Approach Procedure (SIAP) based on the Global Positioning System (GPS) Helicopter Point in Space approach at Easton Memorial Hospital Heliport, Easton, MD has made this proposal necessary. Sufficient controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to contain aircraft executing an instrument approach. The area would be depicted on aeronautical charts for pilot reference.

**DATE:** Comments must be received on or before September 27, 2001.

**ADDRESSES:** Send comments on the proposal in triplicate to: Manager, Airspace Branch, AEA–520, Docket No. 01–AEA–22, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809.

The official docket may be examined in the Office of the Regional Counsel, AEA–7, F.A.A. Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809. An informal docket may be examined during normal business hours in the Airspace Branch, AEA–520, F.A.A. Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809.

**FOR FURTHER INFORMATION CONTACT:** Mr. Francis T. Jordan, Jr., Airspace 11434–4809; telephone: (718) 553–4521.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 01-AEA-22." The postcard will be date/time stamped and returned to the commenters. All communications received on or before the closing date for comments will be considered for taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with the FAA personnel concerned with this rulemaking will be filed in the docket.

**Availability of NPRMs**

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Office of the Regional Counsel, AEA-7, F.A.A. Eastern Region, 1 Aviation Plaza, Jamaica, NY, 11434-4809. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

**The Proposal**

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR Part 71) to establish Class E airspace area at Easton Memorial Hospital Heliport. Class E airspace designations for airspace areas extending upward from 700 feet AGL are published in Paragraph 6005 of FAA Order 7400.9H, dated September 1, 2000, and effective September 16, 2000, which is incorporated by reference in 14

CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

**The Rule**

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979) and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that would only affect air traffic procedures and air navigation, it is certified that this proposed rule would not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**The Proposed Amendment**

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

**PART 71—[AMENDED]**

1. The authority citation for CFR Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

**§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9H, Airspace Designations and Reporting Point, dated September 1, 2000, and effective September 16, 2000, is proposed to be amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

**AEA MD E5, Easton, MD [NEW]**

Easton Memorial Hospital Heliport,  
(Lat 38°46'08" N.; long 76°04'22" W.)  
Point in Space Coordinates  
(Lat 38°46'18" N.; long 76°06'10" W.)

That airspace extending upward from 700 feet above the surface within a 6 mile radius of the point in space for the SIAP to the

Easton Memorial Hospital Heliport, Easton, MD.

\* \* \* \* \*

Dated: Issued in Jamaica, New York on August 13, 2001.

**Richard J. Ducharme,**

*Acting Assistant Manager, Air Traffic Division, Eastern Region.*

[FR Doc. 01-21611 Filed 8-27-01; 8:45 am]

**BILLING CODE 4910-13-M**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71]**

**[Airspace Docket No. 01-AEA-23**

**Proposed Amendment to Class E Airspace; Peninsula Regional Medical Center Heliport, White Marsh, MD**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This action proposed to establish Class E airspace at White Marsh, MD. The development of an Area Navigation (RNAV), Standard Instrument Approach Procedure (SIAP) Helicopter Point in Space approach at Peninsula Regional Medical Center Heliport, White Marsh, MD has made this proposal necessary. Sufficient controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to contain aircraft executing an instrument approach. The area would be depicted on aeronautical charts for pilot reference.

**DATES:** Comments must be received on or before September 27, 2001.

**ADDRESSES:** Send comments on the proposal in triplicate to: Manager, Airspace Branch, AEA-520, Docket No. 01-AEA-23, Eastern Region, 1 Aviation Plaza, Jamaica NY 11434-4809.

The official docket may be examined in the Office of the Regional Counsel, AEA-7, F.A.A. Eastern Region, 1 Aviation Plaza, Jamaica NY 11434-4809. An informal docket may also be examined during normal business hours in the Airspace Branch, AEA-520, F.A.A. Eastern Region, 1 Aviation Plaza, Jamaica NY 11434-4809.

**FOR FURTHER INFORMATION CONTACT:** Mr. Francis T. Jordan, Jr., Airspace specialist, Airspace Branch, AEA-520, Eastern Region, 1 Aviation Plaza, Jamaica NY 11434-4809; telephone: (718-553-4521).

**SUPPLEMENTARY INFORMATION:**