

Titeflex Corporation: Docket No. 2000-NE-57-AD.

Applicability

This airworthiness directive (AD) is applicable to certain part number (P/N) Titeflex Corporation high- and medium-pressure hoses that were fabricated at the Titeflex Springfield, MA, facility from January 1996 through June 2000. These hoses are installed on Airbus A300, A310, A340, Boeing, 737, 777, Cessna 650, Bombardier CL-600, BAE Avro 146 and Bae 146, McDonnell Douglas Corporation DC8 series airplanes, General Electric CF6-80C and CFM-56 series, and Honeywell International Inc. ALF502 and LF507 series turbofan engines.

Note 1: This AD applies to each engine and airplane identified in the preceding

applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines or airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner or operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required within 48 months after the effective date of this AD, unless already done.

To prevent failure of a hose when exposed to fire, do the following:

(a) Inspect all high-pressure and medium-pressure hoses, with a P/N specified in paragraph 1.A. of Titeflex Corporation service bulletin (SB) 73-2.

(b) If the hose has a brown, integral firesleeve, no further action is required. If the hose has an orange, slip-on firesleeve, then inspect the metal tag for the assembly location.

(1) If the assembly location on the metal tag is TITFLEX/API, TITFLEX/API LGB, TITFLEX E, TITFLEX EUROPE, or SHAC 1S353, no further action is required.

(2) If the assembly location on the metal tag is TITFLEX, inspect for a date and disposition as specified in the following Table:

If the hose is	And the date is	Then
(i) High-pressure,	(A) Before January 1996 or after June 2000, (B) January 1996 through June 2000,	No further action is required. Replace hose with a serviceable part.
(ii) Medium-pressure,	(A) Before February 2000 or after May 2000, (B) February 2000 through May 2000,	No further action is required. Replace hose with a serviceable part.

Definition of a Serviceable Hose

(c) For the purposes of this AD, a serviceable hose is defined as a hose that has an assembly location listed in paragraph (b)(1) of this AD, that has an integral brown firesleeve, as a high-pressure hose that was fabricated before January 1996 or after June 2000, and as a medium-pressure hose that was fabricated before February 2000 or after May 2000.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office (ACO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Boston ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Boston ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Issued in Burlington, Massachusetts on May 24, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-13766 Filed 5-31-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-125626-01]

RIN 1545-BA25

Unit Livestock Price Method; Hearing Cancellation

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Cancellation of notice of public hearing on proposed rulemaking.

SUMMARY: This document provides notice of cancellation of a public hearing on proposed regulations under section 471 of the Internal Revenue Code.

DATES: The public hearing originally scheduled for June 12, 2002, at 10 a.m., is cancelled.

FOR FURTHER INFORMATION CONTACT: Treena Garrett of the Regulations Unit, Associate Chief Counsel (Income Tax and Accounting), (202) 622-7180 (not a toll-free number).

SUPPLEMENTARY INFORMATION: A notice of proposed rulemaking and notice of public hearing that appeared in the **Federal Register** on February 4, 2002, (67 FR 5074), announced that a public hearing was scheduled for June 12, 2002, at 10 a.m., in room 4716, Internal Revenue Service Building, 1111 Constitution Avenue, NW, Washington,

DC. The subject of the public hearing is proposed regulations under section 471 of the Internal Revenue Code. The public comment period for these proposed regulations expired on May 6, 2002.

The notice of proposed rulemaking and notice of public hearing, instructed those interested in testifying at the public hearing to submit a request to speak and an outline of the topics to be addressed. As of May 22, 2002, no one has requested to speak. Therefore, the public hearing scheduled for June 12, 2002, is cancelled.

Cynthia E. Grigsby,

Chief, Regulations Unit, Associate Chief Counsel, (Income Tax and Accounting).

[FR Doc. 02-13847 Filed 5-31-02; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-248110-96]

RIN 1545-AY48

Guidance Under Section 817A Regarding Modified Guaranteed Contracts

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking and notice of public hearing.