

FMC affected	Applicable service bulletin
FMC-4200	Rockwell Collins Service Bulletin 502 (FMC-3000/4200-34-502), dated February 17, 2000, or Rockwell Collins Service Bulletin 504, Revision No. 1 (FMC-4200/6000-34-504), dated March 26, 2001.
FMC-5000	Rockwell Collins Service Bulletin 15, Revision No. 1 (FMC-4200/5000/6000-34-15), dated November 15, 2000.
FMC-6000	Rockwell Collins Service Bulletin 504, Revision No. 1 (FMC-4200/6000-34-504), dated March 26, 2001, or Rockwell Collins Service Bulletin 507 (FMC-6000-34-507), dated April 4, 2001.

(f) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and
 (2) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) *Where can I get information about any already-approved alternative methods of compliance?* Contact Roger A. Souter, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Rm 100, Wichita, Kansas 67209; telephone: (316) 946-4134; facsimile: (316) 946-4407. E-mail address: Roger.Souter@faa.gov.

(h) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) *How do I get copies of the documents referenced in this AD?* You may get copies of the documents referenced in this AD from Rockwell Collins, Business and Regional Systems, 400 Collins Road Northeast, Cedar Rapids, Iowa 52498. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on July 3, 2002.

Dorenda D. Baker,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-17307 Filed 7-9-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NE-11-AD]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney JT8D-200 Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The Federal Aviation Administration (FAA) proposes to adopt a new airworthiness directive (AD) that is applicable to certain Pratt & Whitney (PW) JT8D-200 series turbofan engines. This proposal would require the installation of stops on the fan exit guide vane case. This proposal is prompted by reports of the flange between the fan duct case and the fan exit guide vane case separating due to a fan blade fracture event. The actions specified by the proposed AD are intended to prevent the flange between the fan duct case and the fan exit guide vane case from separating due to a fan blade failure. Separations of that flange could result in damage to the airplane.

DATES: Comments must be received by September 9, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-NE-11-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may be inspected at this location, by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line.

The service information referenced in the proposed rule may be obtained from Pratt & Whitney, 400 Main St., East

Hartford, CT 06108; telephone (860) 565-6600, fax (860) 565-4503. This information may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT:

Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7175, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NE-11-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the

FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-NE-11-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

The FAA has received reports of the flange between the fan duct case and the fan exit guide vane case separating due to fan blade fracture events on PW JT8D-209, -217, -217A, -217C, and “219 series turbofan engines. This proposal would require a one-time installation of stops on engines that do not incorporate a fan exit guide vane case and fan duct assembly with improved durability and impact resistance, part number 805919 or 815377. This proposal is prompted by a number of reports of fan case flange separation, one of which occurred in July 2001 when a JT8D powered MD-80 was required to make an emergency landing after experiencing a fan blade fracture, resulting in fan case flange separation and high aircraft vibrations. The actions specified by the proposed AD are intended to prevent the flange between the fan duct case and the fan exit guide vane case from separating due to a fan blade failure. This condition, if not corrected, could result in damage to the airplane.

Manufacturer's Service Information

The FAA has reviewed and approved the technical contents of PW JT8D-200 Series Service Bulletin No. 6100, Revision 2 dated December 9, 1998. That SB describes the procedures for installing stops on the fan exit guide vane case, to restrict axial separation of the case in the event of a case fracture.

FAA's Determination of an Unsafe Condition and Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other PW JT8D-209, -217, -217A, -217C, and “219 series turbofan engines, the proposed AD would require installation of stops on the fan exit guide vane case at the next shop visit in accordance with PW SB No. 6100, Revision 2, dated December 9, 1998.

Economic Analysis

There are approximately 1,346 PW JT8D-200 series engines of the affected design in the worldwide fleet. The FAA estimates that 821 engines installed on airplanes of U.S. registry would be affected by this proposed AD. The FAA also estimates that it would take approximately 1.5 work hours per engine to perform the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost

approximately \$5,200 per engine. Based on these figures, the total cost of the proposed AD to U.S. operators is estimated to be \$4,343,090.

Regulatory Analysis

This proposed rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposed rule.

For the reasons discussed above, I certify that this proposed regulation (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Pratt & Whitney: Docket No. 2002-NE-11-AD.

Applicability

This airworthiness directive (AD) is applicable to Pratt & Whitney (PW) JT8D-209, -217, -217A, -217C, and -219 series turbofan engines that do not incorporate the fan exit guide vane case and fan duct assembly with improved durability and

impact resistance, part numbers 805919 or 815377. These engines are installed on, but not limited to McDonnell Douglas MD-80 and series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required, unless already done.

To prevent the flange between the fan duct and the fan exit guide vane from separating due to a fan blade failure, which could result in damage to the airplane, do the following:

Installation of Hardware

(a) At the next shop visit after the effective date of this AD, install stops on the fan exit guide vane case in accordance with paragraphs 2.A. through 2.C.(1) of the Accomplishment Instructions of PW JT8D-200 Series SB No. 6100, Revision 2, dated December 9, 1998.

Definitions

(b) For the purposes of this AD, a shop visit is defined as an engine removal, where engine maintenance entails separation of pairs of major mating engine flanges or the removal of a disk, hub, or spool at a maintenance facility that is capable of compliance with the instructions of this AD, regardless of other planned maintenance.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Issued in Burlington, Massachusetts, on July 1, 2002.

Jay J. Pardee,
Manager, Engine and Propeller Directorate,
Aircraft Certification Service.
[FR Doc. 02-17296 Filed 7-9-02; 8:45 am]
BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 02-AGL-08]

Proposed Modification of Class E Airspace; Circleville, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes to modify Class E airspace at Circleville, OH. An Area Navigation (RNAV) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 23, has been developed for Ross County Airport. Controlled airspace extending upward from 700 feet above the surface of the earth is needed to contain aircraft executing this approach. This action would increase the area of the existing controlled airspace at Pickaway County Memorial Airport, by adding a radius of controlled airspace around Ross County Airport.

DATES: Comments must be received on or before August 24, 2002.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Regional Counsel, AGL-7, Rules Docket No. 02-AGL-08, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Regional Counsel, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Airspace Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT: Denis C. Burke, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views,

or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this document must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 02-AGL-08." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this document may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Regional Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-230, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-3484. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class E airspace at Circleville, OH, by adding a radius of controlled airspace around the Ross County Airport, thus increasing the existing Class E airspace area for Pickaway County Memorial Airport. Controlled airspace extending upward from 700 feet above the surface of the earth is needed to contain aircraft executing instrument approach

procedures. The area would be depicted on appropriate aeronautical charts. Class E airspace areas extending upward from 700 feet or more above the surface are published in paragraph 6005 of FAA Order 7400.9J dated August 31, 2001, and effective September 16, 2001, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an establishment body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore this, proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9J, Airspace Designations and Reporting Points, dated August 31, 2001, and effective September 16, 2001, is amended as follows:

* * * * *

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *