

Proposed Rules

Federal Register

Vol. 68, No. 174

Tuesday, September 9, 2003

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

OFFICE OF PERSONNEL MANAGEMENT

5 CFR Part 300

RIN 3206-AK05

Employment (General)

AGENCY: Office of Personnel Management.

ACTION: Proposed rule.

SUMMARY: The Office of Personnel Management (OPM) is issuing a proposed regulation regarding the detail of executive branch employees to the legislative branch. The purpose of the revision is to set forth guidelines for executive branch detailees to the legislative branch.

DATES: Comments must be received on or before October 24, 2003.

ADDRESSES: Send or deliver comments to Ms. Leah M. Meisel, Deputy Associate Director for Talent and Capacity Policy, Office of Personnel Management, 1900 E Street, NW., Room 6551, Washington, DC 20415-9700; e-mail employ@opm.gov; fax: (202) 606-2329.

FOR FURTHER INFORMATION CONTACT: Mr. Michael J. Mahoney by telephone on 202-606-0960, by FAX 202-606-2329, or by TDD on 202-418-3134, e-mail mjmahone@opm.gov.

SUPPLEMENTARY INFORMATION: OPM is issuing proposed regulations under 5 U.S.C. 1103, setting forth guidelines for executive branch detailees to the legislative branch. The purpose of this proposed regulation is to maintain the separation of powers under the Constitution and prevent conflicts of interest among the branches and individuals involved.

Regulatory Flexibility Act

I certify that these regulations would not have a significant economic impact on a substantial number of small entities because they would apply only to Federal agencies and employees.

List of Subjects in 5 CFR Part 300

Freedom of information, Government employees, Reporting and recordkeeping requirements, Selective Service System.

Office of Personnel Management.

Kay Coles James,

Director.

Accordingly, OPM is proposing to amend part 300 of Title 5 of the Code of Federal Regulations as follows:

PART 300—EMPLOYMENT (GENERAL)

1. The authority citation is revised to read as follows:

Authority: 5 U.S.C. 552, 3301, and 3302; E.O. 10577, 3 CFR 1954-1958 Comp., page 218, unless otherwise noted.

Secs. 300.101 through 300.104 also issued under 5 U.S.C. 7201, 7204, and 7701; E.O. 11478, 3 CFR 1966-1970 Comp., page 803.

Secs. 300.311 through 300.316 also issued under 5 U.S.C. 1103.

Secs. 300.401 through 300.408 also issued under 5 U.S.C. 1302(c), 2301, and 2302. Secs. 300.501 through 300.507 also issued under 5 U.S.C. 1103(a)(5).

Sec. 300.603 also issued under 5 U.S.C. 1104.

2. Amend part 300 by adding §§ 300.311 through 300.316 and a new center heading to read as follows:

Detail of Government Employees From the Executive Branch to the Legislative Branch

§ 300.311 Definitions.

In this part: *Agency* means a military department and an executive agency as defined in this section;

Employee has the same meaning as in 5 U.S.C. 2105 and a member of the uniformed services as defined in this section;

Executive agency has the same meaning as in 5 U.S.C. 105, exclusive of the General Accounting Office;

Military department has the same meaning as in 5 U.S.C. 102;

OPM means The United States Office of Personnel Management;

Uniformed Services has the same meaning as in 10 U.S.C. 101.

§ 300.312 Detail of executive branch employees to the legislative branch.

No executive agency (agency) shall detail, assign, or otherwise make available an employee of such agency for the performance of functions within or under the supervision of the

legislative branch, without the approval of the Director of the Office of Personnel Management ("Director of OPM"). The Director of OPM shall not approve such detail, assignment, or making available for a period exceeding 180 days, except that, upon request from the office of the legislative branch to which the employee is detailed, assigned, or made available, the Director of OPM may approve one additional period not to exceed 180 days.

§ 300.313 Approval of Details.

The Director of OPM shall not give approval with respect to an employee under § 300.312 unless:

(a) The functions to be performed by the employees within or under the supervision of the legislative branch:

(1) Will not involve;

(i) A conflict with respect to present or potential differing interests of the executive branch and the legislative branch; or

(ii) Any breach of applicable rules of professional conduct, including those governing the conduct of attorneys; and

(2) Will not involve disclosure, or any significant risk of disclosure, of information within the constitutional authority of the Executive to withhold because disclosure could impair foreign relations, the national security, the deliberative processes of the Executive, or the performance of the Executive's constitutional duties; and

(b) The detail, assignment, or making available is consistent with applicable law, including section 1301(a) of title 31, United States Code.

§ 300.314 Termination.

The Director of OPM may direct the head of an agency to, and upon such direction, the head of such agency shall, terminate the detail, assignment, or making available of an employee of such agency for the performance of functions within or under the supervision of the legislative branch, whether made before or after the publication of this regulation in the **Federal Register**, when, in the Director's judgment after consultation with the head of the agency, the continuation of such detail, assignment, or making available would not be consistent with the criteria for approval set forth in § 300.313.

§ 300.315 Reporting.

On a semi-annual basis, heads of agencies shall file a written report with

the Director of OPM describing each detail, assignment, or making available of an agency employee for the performance of functions within or under the supervision of the legislative branch.

§ 300.316 Effect on existing details.

Any detail, assignment, or making available of an employee of an agency for the performance of functions within or under the supervision of the legislative branch that is in effect immediately prior to the publication of this regulation in the **Federal Register** shall terminate not later than January 2, 2004, unless approved by the Director of OPM prior to that date under § 300.313.

[FR Doc. 03-22904 Filed 9-8-03; 8:45 am]

BILLING CODE 6325-38-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-89-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 777-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 777-200 and -300 series airplanes. For all airplanes, this proposal would require installation of a placard that advises of weight limits for a certain electrical rack, accomplishment of a one-time inspection and records check to determine the amount of weight currently installed in that rack, and removal of equipment from that rack if necessary. For certain airplanes, this proposal also would require a one-time inspection of the clevis end of the vertical tie rods that support the center stowage bins to measure the exposed thread, installation of placards that advise of weight limits for certain other electrical racks, a one-time inspection and records check to determine the amount of weight currently installed in certain other electrical racks, corrective actions, and replacement of the vertical tie rods for the center stowage bins or electrical racks with new improved tie rods, as applicable. This action is necessary to prevent failure of the tie

rods supporting certain electrical racks and the center stowage bins, which could cause the racks or stowage bins to fall onto passenger seats below during an emergency landing, impeding an emergency evacuation or injuring passengers. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by October 24, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-89-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-89-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Robert Kaufman, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6433; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-89-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-89-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report indicating that, under certain conditions on Boeing Model 777-200 and -300 series airplanes, the vertical tie rods that attach the center stowage bins and electrical racks to the airplane structure can break. Multiple broken tie rods could allow the center stowage bins and electrical racks to fall onto the passenger seats below during an emergency landing. This condition, if not corrected, could impede an emergency evacuation or result in injury to passengers.

Explanation of Relevant Service Information

We have reviewed and approved Boeing Service Bulletin 777-25-0144, Revision 1, dated January 10, 2002. For all airplanes, the service bulletin describes procedures for installing a placard showing weight limits for electrical rack E7. For certain airplanes, the service bulletin also describes procedures for additional actions, as follows:

- A one-time inspection of the clevis end of the vertical tie rods that support