

human resources to adequately inspect foreign air carriers for AWA compliance. We believe that by being able to conduct inspections and to impose penalties and/or fines on any air carrier that does not comply with the AWA regulations for animals in transit, we can encourage most air carriers to place greater emphasis on ensuring that animals are transported humanely.

Therefore, for the reasons given in our earlier determination to regulate and in this document, we are confirming April 7, 2004, as the date we intend to begin applying the AWA regulations and standards for the humane transportation of animals in commerce to all foreign air carriers operating to or from any point within the United States, its territories, possessions, or the District of Columbia.

Paperwork Reduction Act

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 *et seq.*), the information collection or recordkeeping requirements included in this determination to regulate have been approved by the Office of Management and Budget (OMB) under OMB control number 0579-0247.

Government Paperwork Elimination Act Compliance

The Animal and Plant Health Inspection Service is committed to compliance with the Government Paperwork Elimination Act (GPEA), which requires Government agencies in general to provide the public the option of submitting information or transacting business electronically to the maximum extent possible. For information pertinent to GPEA compliance related to this determination to regulate, please contact Mrs. Celeste Sickles, APHIS' Information Collection Coordinator, at (301) 734-7477.

Authority: 7 U.S.C. 2131-2159; 7 CFR 2.22, 2.80, and 371.7.

Done in Washington, DC, this 1st day of April, 2004.

Peter Fernandez,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 04-7738 Filed 4-5-04; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-SW-45-AD; Amendment 39-13471; AD 2004-03-27]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model AS332C, L, and L1 Helicopters; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects Airworthiness Directive (AD) 2004-03-27 for the Eurocopter France Model AS332C, L, and L1 helicopters that was published in the *Federal Register* on February 13, 2004 (69 FR 7113). The AD contains an incorrect AD number. In all other respects, the original document remains the same.

DATES: Effective March 19, 2004.

FOR FURTHER INFORMATION CONTACT:

Uday Garadi, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Safety Management Group, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: The FAA issued a final rule AD 2004-03-27, on January 30, 2004 (69 FR 7113, February 13, 2004). The following correction is needed:

The AD number on page 7114 is incorrectly listed as 2002-SW-45-AD, which is the AD Docket Number; the correct AD number is 2004-03-27. Therefore, the AD number needs correcting.

Since no other part of the regulatory information has been revised, the final rule is not being republished.

Correction of the Publication

■ Accordingly, the publication on February 13, 2004 of the final rule (AD 2004-03-27), which was the subject of FR Doc. 04-2782, is corrected as follows:

§ 39.13 [Corrected]

■ On page 7114, in the second column, the AD number listed as "2002-SW-45-AD" that appears in bold text just before "Eurocopter France," the manufacturer name, is corrected to read "2004-03-27."

Issued in Fort Worth, Texas, on March 29, 2004.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-7618 Filed 4-5-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-226-AD; Amendment 39-13556; AD 2004-07-12]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-90-30 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD-90-30 airplanes. For some airplanes, this action requires replacing one 3-phase limiter block assembly, 6 current limiters, and hardware for 9 electrical cables with new parts. For other airplanes, this action requires inspecting 6 current limiters and 3 spare current limiters and replacing any defective current limiters with new current limiters. This action is necessary to prevent overheating of the terminal studs on the 3-phase limiter blocks and associated current limiters, which could cause a fire in the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective May 11, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 11, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.