

A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the

Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2003–NM–221–AD.

Applicability: This AD applies to the airplanes listed in Table 1 of this AD, certificated in any category:

TABLE 1.—APPLICABILITY

Table with 2 columns: Boeing model, As listed in. Rows include Model 737-300, -400, and -500 series airplanes and Model 757-200 and -200CB series airplanes.

Compliance: Required as indicated, unless accomplished previously.

To prevent loosened or disconnected overhead ducts from causing ceiling panels to drop below the minimum height of the evacuation zone for the passenger cabin, which could result in inadequate height for safe exit in the event of an emergency evacuation, accomplish the following:

Service Bulletin References

(a) The term "service bulletin," as used in this AD, means the applicable service bulletins listed in Table 1 of this AD.

Inspection and Related Investigative/Corrective Actions

(b) For Model 737-300, -400, and -500 series airplanes, do the actions required in paragraphs (b)(1) and (b)(2) of this AD at the specified compliance times, in accordance with the Accomplishment Instructions of the service bulletin.

(1) Within 60 months after the effective date of this AD, do a general visual inspection at the applicable body station frames for open body station frames; and, before further flight, do all the related investigative/corrective actions, as applicable; by accomplishing all of the actions in paragraph 3.B. of the service bulletin.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(2) Within 60 months after the effective date of this AD, do the actions required in paragraph (b)(2)(i) or (b)(2)(ii) of this AD, as applicable.

(i) For Groups 1 and 3 airplanes identified in the service bulletin: Install the lanyard hook brackets and each lanyard assembly under the air conditioning (AC) overhead ducts in accordance with paragraph 3.C. of the service bulletin.

(ii) For Group 2 airplanes identified in the service bulletin: Install the lanyard hook brackets and the lanyard assemblies under the AC overhead ducts by accomplishing all of the actions in paragraph 3.D. of the service bulletin.

(c) For Model 757-200 and -200CB series airplanes: Within 60 months after the effective date of this AD, do a general visual inspection of the applicable body station frames for open body station frames; and, before further flight, do all the corrective actions, as applicable; by accomplishing all of the actions in the Accomplishment Instructions of the service bulletin.

Credit for Actions Accomplished per Previous Service Bulletins

(d) Actions accomplished before the effective date of this AD per Boeing Special Attention Service Bulletin 737-21-1131, original release, dated December 20, 2001; or Revision 1, dated January 25, 2002; are acceptable for compliance with the requirements of paragraph (b) of this AD.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Issued in Renton, Washington, on April 29, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-10695 Filed 5-10-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2004-17597 Airspace Docket No. 04-AEA-07]

Proposed Amendment to Class E Airspace; Richmond, VA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area in the Richmond, VA metropolitan area. The development of multiple area navigation (RNAV) Standard Instrument Approach Procedures (SIAP) for numerous airports within the Richmond, VA metropolitan area with approved Instrument Flight Rules (IFR) operations and the resulting overlap of designated Class Instrument Flight Rules (IFR) operations and the resulting overlap of designated Class E-5 airspace have made this proposal necessary. The proposal would consolidate the Class E-5 airspace designations for five airports and result in the rescission of four separate Class E-5 descriptions through separate rulemaking action. The area would be depicted on aeronautical charts for pilot reference.

DATES: Comments must be received on or before June 10, 2004.

ADDRESSES: Send comments on the proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2004-17597/ Airspace Docket No. 04-AEA-07 at the beginning of your comments. You may

also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809.

**FOR FURTHER INFORMATION CONTACT:** Mr. Francis T. Jordan, Jr., Airspace Specialist, Airspace Branch, AEA-520, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809, telephone: (718) 553-4521.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. FAA-2004-17597/Airspace Docket No. 04-AEA-07." The postcard will be date/time stamped and returned to the commenter.

##### Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at <http://www.faa.gov>. or the Superintendent of Documents web page at <http://www.access.gpo.gov/nara>. Additionally, any person may obtain a copy of this notice by submitting a request to the Office of Air Traffic Airspace Management, ATA-400, 800

Independence Avenue, SW., Washington, DC 20591 or by calling (202) 267-8783.

Communications must identify both the docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677 to request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

##### The Proposal

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR Part 71) to amend the Class E airspace within the Richmond, VA metropolitan area. The proposal would consolidate the following airport Class E-5 airspace designations into the Richmond, VA designation: Richmond International Airport (RIC), Richmond, VA; New Kent County Airport (W96), Quinton, VA; Chesterfield County Airport (FCI), Richmond, VA; Hanover County Municipal Airport (OFP), Richmond, VA; Dinwiddie County Airport (PTB), Petersburg, VA. This action would result in the rescission of four Class E-5 designations under a separate docket. The affected airspace would subsequently be incorporated into the Richmond, VA description. The airspace will be defined to accommodate the approaches and contain IFR operations to and from those airports. This change would have no impact on aircraft operations since the type of airspace designation is not changing. Furthermore, the IFR approach procedures for the individual airports within the area would not be affected. Class E airspace designation for airspace areas extending upward from 700 ft or more above the surface are published in Paragraph 6005 of FAA Order 7400.9L, dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a

routine matter that would only affect air traffic procedures and air navigation, it is certified that this proposed rule would not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

##### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

##### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

##### PART 71—[AMENDED]

1. The authority citation for 14 CFR Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

##### § 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9L, dated September 2, 2003, and effective September 16, 2003, is proposed to be amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

##### AEA VA E5 Richmond, VA (Revised)

That airspace extending upward from 700 feet above the surface within an area bounded by a line beginning at lat. 37°03'52" N., long. 77°47'45" W., to lat. 37°11'51" N., long. 77°41'25" W., to lat. 37°27'45" N., long. 77°41'44" W., to lat. 37°49'25" N., long. 77°32'39" W., to lat. 37°49'28" N., long. 77°19'42" W., to lat. 37°34'38" N., long. 76°56'19" W., to lat. 37°26'41" N., long. 76°55'56" W., to lat. 36°55'48" N., long. 77°37'56" W., to the point of beginning.

\* \* \* \* \*

Issued in Jamaica, New York, on May 4, 2004.

**John G. McCartney,**

*Assistant Manager, Air Traffic Division, Eastern Region.*

[FR Doc. 04-10691 Filed 5-10-04; 8:45 am]

**BILLING CODE 4910-13-M**