

order demonstrate compliance with the requirements of §§ 25.785(b) and (d).

DATES: The final policy was issued by the Transport Airplane Directorate on May 9, 2005.

ADDRESSES: Address your comments to the individual identified under **FOR FURTHER INFORMATION CONTACT**.

FOR FURTHER INFORMATION CONTACT: Jeff Gardlin, Federal Aviation Administration, Transport Airplane Directorate, Transport Standards Staff, Airframe and Cabin Safety Branch, ANM-115, 1601 Lind Avenue SW., Renton, WA 98055-4056; telephone (425) 227-2136; fax (425) 227-1320; e-mail: jeff.gardlin@faa.gov.

SUPPLEMENTARY INFORMATION: A notice of proposed policy was published in the **Federal Register** on July 22, 2003 (68 FR 43418). A notice reopening the comment period for an additional amount of time was published in the **Federal Register** on September 15, 2003 (68 FR 54042). Three (3) commenters responded to these requests for comments.

Background

The final policy provides FAA certification policy on conducting component level tests in order to demonstrate compliance with the requirements of §§ 25.785(b) and (d).

Injurious item located within the headstrike zone can be assessed for occupant injury potential. These test methods are the product of an Aviation Rulemaking Advisory Committee recommendation and are harmonized with the Joint Aviation Authorities (JAA) and Transport Canada.

The final policy as well as the disposition of comments received is available on the Internet at the following address: <http://www.airweb.faa.gov/rgl>. If you do not have access to the Internet, you can obtain a copy of the policy by contacting the person listed under **FOR FURTHER INFORMATION CONTACT**.

Issued in Renton, Washington, on May 9, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-10134 Filed 5-19-05; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Galley Carts and Containers

AGENCY: Federal Aviation Administration (FAA), (DOT).

ACTION: Notice of availability and request for public comment.

SUMMARY: This notice announces the availability of, and requests comment on proposed Technical Standard Order (TSO) C-175, Galley Carts and Containers. This proposed TSO tells persons seeking TSO authorization or letter of design approval what minimum performance standards (MPS) their galley carts and containers must meet to be identified with the appropriate TSO making.

DATES: Comments must be received on or before July 19, 2005.

ADDRESSES: Send all comments on this proposed TSO to: Federal Aviation Administration (FAA), Aircraft Certification Service, Aircraft Engineering Division, Technical Programs and Continued Airworthiness Branch (AIR-120), 800 Independence Avenue SW., Washington DC 20591. ATTN: Mr. Dave Rich. Or, you may deliver comments to: Federal Aviation Administration, Room 815, 800 Independence Avenue SW., Washington, DC 20591.

FOR FURTHER INFORMATION CONTACT: Mr. Dave Rich, AIR-120, Room 815, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591. Telephone (412) 262-9034, ext. 292, fax (412) 264-9302.

SUPPLEMENTARY INFORMATION:

Comments Invited

You are invited to comment on the proposed TSO by submitting written data, views, or arguments to the above address. Comments received may be examined, both before and after the closing date, in room 815 at the above address, weekdays except Federal holidays, between 8:30 a.m. and 4:30 p.m. The Director, Aircraft Certification Service, will consider all comments received on or before the closing date before issuing the final TSO.

Background

In November 2004, the SAE International organization published the Aerospace Standard (AS) 8056, Minimum Design and Performance of Airplane Galley In-Flight Carts, Containers, and Associated Components, that prescribes the minimum design and performance requirements for equipment used in aircraft for the housing of beverages, meals, and waste. As such, the FAA elects to adopt with minor modifications, the standards prescribed in AS 8056 as the minimum performance standards a manufacturer of galley carts and containers must first

meet in order for their product to be identified with TSO-C175 markings.

How To Obtain Copies

You can view or download the proposed TSO from its online location at: <http://www.airweb.faa.gov/rgl>. At this Web page, select "Technical Standard Orders." At the TSO page, select "Proposed TSOs." For a paper copy, contact the person listed in **FOR FURTHER INFORMATION CONTACT**.

Note: SAE International documents are copyrighted and may not be reproduced without the written consent of SAE International. You may purchase copies of SAE International documents from: SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001, or directly from their Web site: <http://www.sae.org/>.

Issued in Washington, DC, on May 16, 2005.

Susan J.M. Cabler,

Assistant Manager, Aircraft Engineering Division, Aircraft Certification Service.

[FR Doc. 05-10135 Filed 5-19-05; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

Environmental Impact Statement: Nueces County, TX

AGENCY: Federal Highway Administration (FHWA), DOT.

ACTION: Notice of intent.

SUMMARY: The FHWA is issuing this notice to advise the public that an environmental impact statement (EIS) will be prepared for the proposed U.S. Highway (US) 181 Harbor Bridge replacement highway project in Nueces County, Texas.

FOR FURTHER INFORMATION CONTACT: John R. Mack, P.E. District Engineer, Federal Highway Administration—Texas Division, 300 East 8th Street, Austin, Texas 78701. Telephone: 512-536-5960.

SUPPLEMENTARY INFORMATION: The FHWA, in cooperation with the Texas Department of Transportation (TxDOT), will prepare an environmental impact statement (EIS) for a proposal to replace the existing US 181 Harbor Bridge in Nueces County, Texas. The proposed improvement would involve replacement of the existing Harbor Bridge and approaches where US 181 crosses the Corpus Christi Ship Channel, a roadway distance of approximately 2.25 miles.

The need for the proposed bridge improvements is based on a number of identified deficiencies in the existing structure, including high maintenance