

Social Security Administration
Room 625, JFK Federal Building
Boston, MA 02203-0002.

Office of the Regional Chief Counsel,
Region II
Social Security Administration
26 Federal Plaza, Room 3904
New York, NY 10278-0004.

Office of the Regional Chief Counsel,
Region III
Social Security Administration
P.O. Box 41777
Philadelphia, PA 19101-1777.

Office of the Regional Chief Counsel,
Region IV
Social Security Administration
Atlanta Federal Center
61 Forsyth Street, SW., Suite 20T45
Atlanta, GA 30303-8920.

Office of the Regional Chief Counsel,
Region V
Social Security Administration
200 W. Adams Street, 30th Floor
Chicago, IL 60606-5208.

Office of the Regional Chief Counsel,
Region VI
Social Security Administration
1301 Young Street, Room 430
Dallas, TX 75202-5433.

Office of the Regional Chief Counsel,
Region VII
Social Security Administration
601 East 12th Street, Room 535
Federal Office Building
Kansas City, MO 64106-2898.

Office of the Regional Chief Counsel,
Region VIII
Social Security Administration
1961 Stout Street
Byron G. Rogers Federal Office
Building, Suite 1001-A
Denver, CO 80294-3538.

Office of the Regional Chief Counsel,
Region IX
Social Security Administration
333 Market Street, Suite 1500,
San Francisco, CA 94105-2102.

Office of the Regional Chief Counsel,
Region X
Social Security Administration
701 Fifth Avenue, Suite 2900 M/S 901
Seattle, WA 98104-7075.

Dated: December 5, 2005.

Jo Anne B. Barnhart,

Commissioner of Social Security.

[FR Doc. 05-23837 Filed 12-8-05; 8:45 am]

BILLING CODE 4191-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Aircraft Authentication Status

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice.

SUMMARY: The Federal Aviation Administration (FAA) in concert with the Transportation Security Administration (TSA) will revitalize and refocus our airspace monitoring capabilities to ensure that each aircraft operating within the National Airspace System (NAS) has met all statutory, regulatory and certification requirements.

DATES: *Effective Date:* February 1, 2006.

FOR FURTHER INFORMATION CONTACT: Douglas Gould, Manager, Strategic Operations Security (AJR-22) Federal Aviation Administration, 800 Independence Ave., SW., Washington, DC 20591. Telephone (202) 267-7683.

SUPPLEMENTARY INFORMATION: 14 CFR part 47 of the Federal Aviation Regulations defines the requirements and outlines the circumstances necessary for aircraft registration. The FAA and TSA believe that it is in the interests of national security and aviation safety to ensure that only properly registered aircraft operate within the National Airspace System (NAS).

On June 23, 2003, the Federal Aviation (FAA) published a notice in the **Federal Register** (FR Doc. 03-15673) stating that the FAA's Aircraft Registration System would be augmented to reflect the observed status of an aircraft's certificate of registration. As of June 20, 2003 those aircraft records containing information that would render a certificate of registration ineffective, if true, were changed to reflect a status of "In Question."

On May 17, 2004 the Federal Aviation Administration issued a press release emphasizing the need for aircraft owners to update their aircraft registration in order that both the FAA and aircraft manufacturers may be able to notify owners of safety and maintenance-related information.

The FAA has provided numerous other notices requesting aircraft owners register their aircraft and to provide updated address information, mainly in an effort to update the aircraft owner database and to assist local law enforcement agencies and FAA Flight Services Stations in the event of a downed or overdue aircraft. This current notice represents the latest action the FAA is taking to ensure that only properly registered aircraft operate within the NAS.

On the effective date stated herein, operators of identified aircraft with questionable registrations and or no TSA required security measures/waivers will be: (1) Notified of the deficiency,

(2) a pilot deviation will be filed on the operator, (3) operator may be denied access to the NAS. In the event the operator is not the owner, the operator and owner will be notified of the deficiency and both will be subject to any action deemed warranted by the agency in accordance with local, state and federal regulations.

The U.S. Civil Aviation Registry provides means to search and update aircraft owner information.

Issued in Washington, DC on December 1, 2005.

Douglas Gould,

Manager, Strategic Operations Security.

[FR Doc. 05-23852 Filed 12-8-05; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2005-23171; Notice 1]

Bridgestone Firestone North America Tire, LLC, Receipt of Petition for Decision of Inconsequential Noncompliance

Bridgestone Firestone North America Tire, LLC (Bridgestone Firestone) has determined that certain tires it produced in 2005 do not comply with S4.3.2 of 49 CFR 571.109, Federal Motor Vehicle Safety Standard (FMVSS) No. 109, "New pneumatic tires." Bridgestone Firestone has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), Bridgestone Firestone has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Bridgestone Firestone's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

Affected are a total of approximately 50 P205/70R15 Le Mans Champion SE tires produced in 2005. S4.3.2 of FMVSS No. 109 refers to 49 CFR 575.4, section (d) which requires that the sidewall stamping include the date of manufacture. The noncompliant tires are stamped HYMOLCM, while the correct stamping including the date of manufacture should be HYMOLCM2705.

Bridgestone Firestone believes that the noncompliance is inconsequential to motor vehicle safety and that no