

the United States in a manner that will prevent pest infestation.

(2) The fragrant pears may be imported only under a permit issued by APHIS in accordance with § 319.56-4.

(3) Each shipment of pears must be accompanied by a phytosanitary certificate issued by the national plant protection organization of China stating that the conditions of this section have been met and that the shipment has been inspected and found free of the pests listed in this section.

(Approved by the Office of Management and Budget under control number 0579-0227)

Done in Washington, DC, this 19th day of December 2005.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 05-24423 Filed 12-22-05; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2005-21381; Airspace Docket No. 05-ASW-2]

RIN 2120-AA66

Establishment of Area Navigation Routes; Southwestern and South Central United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects an error in the legal description of an Area Navigation (RNAV) route listed in a final rule published in the **Federal Register** on December 15, 2005 (70 FR 74197), Airspace Docket No. 05-ASW-2.

EFFECTIVE DATE: 0901 UTC, February 16, 2006.

FOR FURTHER INFORMATION CONTACT: Steve Rohring, Airspace and Rules, Office of System Operations Airspace and AIM, Federal Aviation

Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

History

On December 15, 2005, a final rule for Airspace Docket No. 05-ASW-2 was published in the **Federal Register** (70 FR 74197). This rule established three RNAV routes (Q-20, Q-22, and Q-24) over the Southwestern and South Central United States. In the description for Q-20, the latitude for the HONDS fix was inadvertently listed as lat. 33°33'60" N. rather than lat. 33°34'00" N. This action corrects that error.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the legal description for Q-20 as published in the **Federal Register** on December 15, 2005 (70 FR 74197), and incorporated by reference in 14 CFR 71.1, are corrected as follows:

PART 71—[AMENDED]

§ 71.1 [Amended]

* * * * *

Q-20 CNX TO JCT [CORRECTED]

CNX	VORTAC	(lat. 34°22'01" N., long. 105°40'41" W.)
HONDS	FIX	(lat. 33°34'00" N., long. 104°51'12" W.)
UNNOS	WP	(lat. 32°57'00" N., long. 103°56'00" W.)
FUSCO	WP	(lat. 31°11'02" N., long. 101°19'30" W.)
JCT	VORTAC	(lat. 30°35'53" N., long. 099°49'03" W.)

* * * * *

Issued in Washington, DC, on December 19, 2005.

Edith V. Parish,

Manager, Airspace and Rules.

[FR Doc. 05-24432 Filed 12-22-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2005-20700; Airspace Docket No. 04-AWA-8]

RIN 2120-AA66

Establishment of Class C Airspace and Revocation of Class D Airspace, Orlando Sanford International Airport, FL; and Modification of the Orlando International Airport Class B Airspace Area, FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class C airspace at the Orlando Sanford International Airport (SFB), FL; revokes the existing Sanford, FL, Class D airspace area and its associated Class E airspace extension; and modifies the existing Orlando International Airport (MCO), FL, Class B airspace area. The FAA is taking this action to improve the flow of air traffic, enhance safety, and reduce the potential for midair collision in the Orlando, FL, terminal area.

EFFECTIVE DATE: 0901 UTC, February 16, 2006.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace and Rules, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

On August 8, 2005, the FAA published in the **Federal Register** a

notice of proposed rulemaking to modify the Orlando International Airport, FL, Class B airspace area, establish the Orlando Sanford International Airport Class C airspace, and revoke the existing Sanford Airport Class D airspace (70 FR 45599). The FAA proposed to realign the MCO Class B airspace area (within the existing lateral boundaries) due to the commissioning of runway 17L/35R; to ensure that MCO arrivals and departures are retained within Class B airspace; and adjust the configuration of the Class B airspace area to accommodate the Orlando Sanford International Airport Class C airspace area. The FAA proposed to establish the SFB Class C airspace area to enhance safety and improve the management of air traffic in the terminal area.

Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. In response to the NPRM, the FAA received 20 written comments. Many of the commenters identified themselves as pilots who operate