

is a need to require the servo actuator leakage rate inspections and replacing each affected servo actuator with a servo actuator containing a newly re-designed servo actuator piston to prevent degraded servo actuator performance as a result of piston head seal leakage and plasma spray flaking.

Since this proposal changes the scope and the requirements of the originally proposed rule, we have determined that it is necessary to reopen the comment period to provide additional opportunity for public comment.

We estimate that this proposed AD would affect 300 helicopters (900 servo actuators) of U.S. registry. We also estimate that the leakage rate inspection would take about 1 work hour per servo actuator at an average labor rate of \$80 per work hour, and the two leakage rate inspections on 900 servo actuators would cost about \$144,000. We estimate that 6 servo actuators, Sikorsky P/N 76650-09805-109 or -110, would need to be replaced with servo actuators, Sikorsky P/N 76650-09805-111.

Assuming an estimated 8 work hours per servo actuator for installation and a cost of \$57,000 per servo actuator, the total cost of installing these servo actuators would be \$345,840. We estimate that the cost of replacing the pistons in the remaining 894 servo actuators would cost \$7,259,280, assuming 14 work hours to replace the pistons and install the servo actuator, and a cost of \$3,500 per piston (2 pistons per servo). Therefore, the total estimated cost of this proposal is \$7,749,120.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. Additionally, this proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a draft economic evaluation of the estimated costs to comply with this proposed AD. See the

AD docket to examine the draft economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Sikorsky Aircraft Corporation: Docket No. FAA-2006-24587; Directorate Identifier 2006-SW-05-AD.

Applicability: Model S-76A, B, and C helicopters, with a main rotor servo actuator (servo actuator), Sikorsky part number (P/N) 76650-09805-109 or -110 (also marked as HR Textron P/N 3006760-109 or -110), installed, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect leaking in a servo actuator, which could lead to degraded servo actuator performance and subsequent loss of control of the helicopter, do the following:

(a) For a servo actuator with 1,500 or less hours time-in-service (TIS) since new (TSN) or TIS since overhaul (TSO), determine the leakage rate on or before reaching 1,500 hours TSN or TSO.

(b) For a servo actuator with 2,250 or less hours TSN or TSO, but more than 1,500 hours TSN or TSO, determine the leakage rate on or before reaching 2,250 hours TSN or TSO.

(c) If the leakage rate in any servo actuator exceeds 700 cc per minute when performing the leakage rate inspection specified in paragraph (a) or (b) of this AD, then:

(1) Replace that servo actuator piston, HR Textron P/N 41004321, with a servo actuator piston, P/N 41012001 or P/N 41012001-001, and re-identify the servo actuator on the servo actuator data plate as Sikorsky P/N "76650-09805-111" and HR Textron P/N "3006760-111" using a metal stamp method; or

(2) Replace the servo actuator with an airworthy servo actuator, Sikorsky P/N 76650-09805-111, HR Textron P/N 3006760-111.

(d) On or before 3,000 hours TSN or TSO, whichever occurs first, replace each servo actuator piston and re-identify the servo actuator as specified in paragraph (c)(1) of this AD or replace each servo actuator as specified in paragraph (c)(2) of this AD.

(e) Modifying and re-identifying each servo actuator as specified in paragraph (c)(1) of this AD or replacing each servo actuator as specified in paragraph (c)(2) of this AD is terminating action for the requirements of this AD for the modified and re-identified or replaced servo actuator.

(f) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Boston Aircraft Certification Office, FAA, ATTN: Terry Fahr, Aviation Safety Engineer, 12 New England Executive Park, Burlington, MA 01803, telephone (781) 238-7155, fax (781) 238-7170, for information about previously approved alternative methods of compliance.

Issued in Fort Worth, Texas, on January 16, 2009.

Mark R. Schilling,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E9-1688 Filed 2-10-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT

24 CFR Parts 5, 92, and 908

[Docket No. FR-4998-N-03]

RIN 2501-AD16

Refinement of Income and Rent Determination Requirements in Public and Assisted Housing Programs: Proposed Delay of Effective Date

AGENCY: Office of the Secretary, HUD.

ACTION: Notice of proposed delay of effective date.

SUMMARY: In accordance with the memorandum of January 20, 2009, from the assistant to the President and Chief

of Staff, entitled "Regulatory Review," published in the **Federal Register** on January 26, 2009 (74 FR 4435), HUD is seeking public comment on a contemplated delay of 60 days in the effective date of the rule entitled "Refinement of Income and Rent Determination Requirements in Public and Assisted Housing Programs" published in the **Federal Register** on January 27, 2009 (74 FR 4832). This final rule revises HUD's public and assisted housing program regulations to implement the upfront income verification process for program participants and to require the use of HUD's Enterprise Income Verification (EIV) system by public housing agencies and owners and management agents. HUD is considering a temporary 60-day delay in the effective date to allow HUD officials the opportunity for further review and consideration of new regulations, consistent with the Chief of Staff memorandum of January 20, 2009.

In addition, HUD takes this opportunity to address questions received subsequent to publication of the January 27, 2009, final rule pertaining to the provisions requiring the use of Social Security Numbers for determining program eligibility. HUD wishes to clarify that these requirements are not intended to apply to individuals, in mixed families, who do not contend eligible immigration status under HUD's noncitizens regulations, nor does it interfere with existing requirements relative to proration of assistance or screening for such families, or authorize their eviction or denial of admission on the basis of the new requirements pertaining to obtaining social security numbers.

HUD solicits comments specifically on the contemplated delay in effective date, but also generally on the rule entitled "Refinement of Income and Rent Determination Requirements in Public and Assisted Housing Programs."

DATES: Comments must be received on or before March 13, 2009.

ADDRESSES: Interested persons are invited to submit comments. There are two methods for submitting public comments. All submissions must refer to the above docket number and title.

1. Submission of Comments by Mail. Comments may be submitted by mail to the Regulations Division, Office of General Counsel, Department of Housing and Urban Development, 451 Seventh Street, SW., Room 10276, Washington, DC 20410-0500.

2. Electronic Submission of Comments. Interested persons may submit comments electronically through the Federal eRulemaking Portal at

www.regulations.gov. HUD strongly encourages commenters to submit comments electronically. Electronic submission of comments allows the commenter maximum time to prepare and submit a comment, ensures timely receipt by HUD, and enables HUD to make them immediately available to the public. Comments submitted electronically through the www.regulations.gov Web site can be viewed by other commenters and interested members of the public. Commenters should follow the instructions provided on that site to submit comments electronically.

Note: To receive consideration as public comments, comments must be submitted through one of the two methods specified above. Again, all submissions must refer to the docket number and title of the rule.

No Facsimile Comments. Facsimile (FAX) comments are not acceptable.

Public Inspection of Public Comments. All properly submitted comments and communications submitted to HUD will be available for public inspection and copying between 8 a.m. and 5 p.m. weekdays at the above address. Due to security measures at the HUD Headquarters building, an appointment to review the public comments must be scheduled in advance by calling the Regulations Division at 202-708-3055 (this is not a toll-free number). Individuals with speech or hearing impairments may access this number via TTY by calling the Federal Information Relay Service at 800-877-8339. Copies of all comments submitted are available for inspection and downloading at www.regulations.gov.

FOR FURTHER INFORMATION CONTACT: For Office of Public and Indian Housing programs, contact Nicole Faison, Director of the Office of Public Housing Programs, Department of Housing and Urban Development, 451 Seventh Street, SW., Room 4226, Washington, DC 20410, telephone number 202-708-0744. For Office of Housing Programs, contact Gail Williamson, Director of the Housing Assistance Policy Division, Department of Housing and Urban Development, 451 Seventh Street, SW., Room 6138, Washington, DC 20410, telephone number 202-402-2473. (These are not toll-free numbers.) Persons with hearing or speech impairments may access these numbers through TTY by calling the toll-free Federal Information Relay Service at 800-877-8339.

Dated: February 6, 2009.

Paula O. Blunt,

General Deputy Assistant Secretary for Public and Indian Housing.

[FR Doc. E9-3004 Filed 2-9-09; 4:15 pm]

BILLING CODE 4210-67-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-147636-08]

RIN 1545-BI41

Application of Section 367 to a Section 351 Exchange Resulting From a Transaction Described in Section 304(a)(1); Treatment of Gain Recognized Under Section 301(c)(3) for Purposes of Section 1248

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking by cross-reference to temporary regulations.

SUMMARY: In the Rules and Regulations section of this issue of the **Federal Register**, the IRS and Treasury Department are issuing temporary regulations under sections 304 and 1248 of the Internal Revenue Code (Code). The temporary regulations provide rules under section 367(a) and (b) that apply to certain transfers of stock by a United States person to a foreign corporation described in section 304(a)(1). The temporary regulations under section 1248(a) provide that, for purposes of section 1248(a), gain recognized by a shareholder under section 301(c)(3) in connection with the receipt of a distribution of property from a foreign corporation with respect to its stock shall be treated as gain from the sale or exchange of the stock of such foreign corporation. The temporary regulations affect certain shareholders that transfer stock in a corporation to a foreign corporation in a transaction to which section 304(a)(1) applies, or that receive a distribution from a foreign corporation described in section 301(c)(3). The text of the temporary regulations also serves as the text of these proposed regulations. The preamble to the temporary regulations explains the temporary regulations and these proposed regulations.

DATES: Written or electronic comments and requests for a public hearing must be received by May 12, 2009.

ADDRESSES: Send submissions to: CC:PA:LPD:PR (REG-147636-08), room 5205, Internal Revenue Service, P.O.