

provided that no elevator having a part number (P/N) specified in table 1 to paragraph (g) of this AD has been installed on that airplane since the airplane's first flight.

(h) Compliance Time for the Actions Specified in Paragraph (g) of This AD

(1) For an elevator for which, as of the effective date of this AD, the records show that no maintenance actions have been performed since first installation of the elevator on an airplane, which might have increased its weight: Within 72 months after the effective date of this AD.

(2) For elevators other than those identified in paragraph (h)(1) of this AD: Within 48 months after the effective date of this AD.

(i) Corrective Actions

If the elevator weight, determined as required by paragraph (g) of this AD, exceeds the weight limit specified in the Accomplishment Instructions of Airbus Service Bulletin A320-55-1034, including Appendices 1 and 2, dated August 19, 2011: Before further flight, do the applicable corrective actions followed by a new weight check of the elevator, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-55-1034, including Appendices 1 and 2, dated August 19, 2011. If the elevator weight, determined as required by the new weight check, exceeds the weight limit specified in the Accomplishment Instructions of Airbus Service Bulletin A320-55-1034, including Appendices 1 and 2, dated August 19, 2011: Before further flight, repair the elevator using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent).

(j) Elevator Re-Identification

If the elevator weight, determined by the weight check specified in paragraph (g) or (i) of this AD, does not exceed the weight limit specified in the Accomplishment Instructions of Airbus Service Bulletin A320-55-1034, including Appendices 1 and 2, dated August 19, 2011: Within 72 months after the effective date of this AD, record the elevator weight and re-identify the elevator, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-55-1042, Revision 01, dated June 29, 2012.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-55-1042, dated August 19, 2011, which is not incorporated by reference in this AD.

(l) Parts Installation Limitation

As of the effective date of this AD, no person may install on any airplane an elevator with a part number listed in table 1 to paragraph (g) of this AD, unless that elevator is in compliance with the requirements of this AD.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1405; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2012-0221, dated October 23, 2012, and the Airbus service information specified in paragraphs (n)(1)(i) and (n)(1)(ii) of this AD; for related information.

(i) Airbus Service Bulletin A320-55-1034, including Appendices 1 and 2, dated August 19, 2011.

(ii) Airbus Service Bulletin A320-55-1042, Revision 01, dated June 29, 2012.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on March 1, 2013.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-05563 Filed 3-8-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Parts 1 and 301

[REG-148873-09]

RIN 1545-BJ16

IRS Truncated Taxpayer Identification Numbers; Hearing Cancellation

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Cancellation of a notice of public hearing on proposed rulemaking.

SUMMARY: This document cancels a public hearing on proposed regulations under the Internal Revenue Code. The proposed regulations provide guidance for creating a new taxpayer identifying number known as an IRS truncated taxpayer identification number, a T TIN.

DATES: The public hearing, originally scheduled for March 12, 2013 at 10 a.m. is cancelled.

FOR FURTHER INFORMATION CONTACT: Oluwafunmilayo Taylor of the Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration) at (202) 622-7180 (not a toll-free number).

SUPPLEMENTARY INFORMATION: A notice of proposed rulemaking and a notice of public hearing that appeared in the **Federal Register** on Monday, January 7, 2013 (78 FR 913) announced that a public hearing was scheduled for March 12, 2013, at 10 a.m. in the IRS Auditorium, Internal Revenue Building, 1111 Constitution Avenue NW, Washington, DC. The subject of the public hearing was under sections 6042, 6043, 6044, 6045, 6049, and 6050 of the Internal Revenue Code.

The public comment period for these regulations expired on February 20, 2013. The notice of proposed rulemaking and notice of public hearing instructed those interested in testifying at the public hearing to submit a request to speak and an outline of topics to be addressed. The agency received one request. As of Monday, March 5, 2013 that request was withdrawn. The public hearing scheduled for March 12, 2013, is cancelled.

LaNita VanDyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 2013-05516 Filed 3-8-13; 8:45 am]

BILLING CODE 4830-01-P