

association intends to present no matters other than:

(A) The election of directors;

(B) The election, approval or ratification of accountants;

(C) A Security holder proposal included pursuant to SEC Rule 14(a)-8 (17 CFR 240.14a-8); and

(D) The approval or ratification of a plan as defined in paragraph (a)(7)(ii) of Item 402 of SEC Regulation S-K (17 CFR 229.402(a)(7)(ii)) or amendments to such a plan; and

(ii) The bank or State savings association does not comment upon or refer to a solicitation in opposition (as defined in 17 CFR 240.14a-6) in connection with the meeting in its proxy material.

\* \* \* \* \*

(f) \* \* \*

(2) The FDIC may, upon the written request of the bank or State savings association, and where consistent with the protection of investors, permit the omission of one or more of the statements or disclosures herein required, or the filing in substitution therefor of appropriate statements or disclosures of comparable character.

\* \* \* \* \*

#### § 335.901 [Removed]

■ 8. Remove § 335.901.

### PART 390—REGULATIONS TRANSFERRED FROM THE OFFICE OF THRIFT SUPERVISION

■ 9. The authority citation for part 390 is revised to read as follows:

**Authority:** 12 U.S.C. 1819.

Subpart A also issued under 12 U.S.C. 1820.

Subpart B also issued under 12 U.S.C. 1818.

Subpart C also issued under 5 U.S.C. 504; 554-557; 12 U.S.C. 1464; 1467; 1468; 1817; 1818; 1820; 1829; 3349, 4717; 15 U.S.C. 78l; 78o-5; 78u-2; 28 U.S.C. 2461 note; 31 U.S.C. 5321; 42 U.S.C. 4012a.

Subpart D also issued under 12 U.S.C. 1817; 1818; 1820; 15 U.S.C. 78l.

Subpart E also issued under 12 U.S.C. 1813; 1831m; 15 U.S.C. 78.

Subpart F also issued under 5 U.S.C. 552; 559; 12 U.S.C. 2901 *et seq.*

Subpart G also issued under 12 U.S.C. 2810 *et seq.*, 2901 *et seq.*; 15 U.S.C. 1691; 42 U.S.C. 1981, 1982, 3601-3619.

Subpart I also issued under 12 U.S.C. 1831x.

Subpart J also issued under 12 U.S.C. 1831p-1.

Subpart K also issued under 12 U.S.C. 1817; 1818; 15 U.S.C. 78c; 78l.

Subpart L also issued under 12 U.S.C. 1831p-1.

Subpart M also issued under 12 U.S.C. 1818.

Subpart N also issued under 12 U.S.C. 1821.

Subpart O also issued under 12 U.S.C. 1828.

Subpart P also issued under 12 U.S.C. 1470; 1831e; 1831n; 1831p-1; 3339.

Subpart Q also issued under 12 U.S.C. 1462; 1462a; 1463; 1464.

Subpart R also issued under 12 U.S.C. 1463; 1464; 1831m; 1831n; 1831p-1.

Subpart S also issued under 12 U.S.C. 1462; 1462a; 1463; 1464; 1468a; 1817; 1820; 1828; 1831e; 1831o; 1831p-1; 1881-1884; 3207; 3339; 15 U.S.C. 78b; 78l; 78m; 78n; 78p; 78q; 78w; 31 U.S.C. 5318; 42 U.S.C. 4106.

Subpart T also issued under 12 U.S.C. 1462a; 1463; 1464; 15 U.S.C. 78c; 78l; 78m; 78n; 78w.

Subpart V also issued under 12 U.S.C. 3201-3208.

Subpart W also issued under 12 U.S.C. 1462a; 1463; 1464; 15 U.S.C. 78c; 78l; 78m; 78n; 78p; 78w.

Subpart X also issued under 12 U.S.C. 1462; 1462a; 1463; 1464; 1828; 3331 *et seq.*

Subpart Y also issued under 12 U.S.C. 1831o.

Subpart Z also issued under 12 U.S.C. 1462; 1462a; 1463; 1464; 1828 (note).

### PART 390 Subpart U—[Removed and Reserved]

■ 10. Remove and reserve part 390 subpart U, consisting of §§ 390.390 through 390.395.

■ 11. In § 390.321, revise paragraph (b)(2) to read as follows:

#### § 390.321 Regulatory reports.

\* \* \* \* \*

(b) \* \* \*

(2) *Exceptions.* Regulatory reporting requirements that are not consistent with GAAP, if any, are not required to be reflected in the audited financial statements, including financial statements contained in securities filings submitted to the FDIC pursuant to the Securities Exchange Act of 1934 or subpart W and 12 CFR part 192.

\* \* \* \* \*

#### § 390.380 [Amended]

■ 12. In § 390.380, remove paragraph (a)(3).

Dated at Washington, DC, this 8th day of April 2014.

By order of the Board of Directors.

Federal Deposit Insurance Corporation.

**Robert E. Feldman,**

*Executive Secretary.*

[FR Doc. 2014-08261 Filed 4-18-14; 8:45 am]

**BILLING CODE 6714-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2014-0250; Directorate Identifier 2013-NM-165-AD]

RIN 2120-AA64

### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. This proposed AD was prompted by reports of in-flight uncommanded rudder movements. This proposed AD would require revising the airplane flight manual (AFM) to incorporate an uncommanded yaw motion procedure. We are proposing this AD to prevent in-flight uncommanded rudder movements, which could lead to structural failure and subsequent loss of the airplane.

**DATES:** We must receive comments on this proposed AD by June 5, 2014.

**ADDRESSES:** You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://>

[www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA–2014–0250; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:**

Luke Walker, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE–171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7363; fax 516–794–5531.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2014–0250; Directorate Identifier 2013–NM–165–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF–2013–22, dated August 12, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL–600–2B16 (CL–604 Variant) airplanes. The MCAI states:

There have been several reported incidents where Bombardier Regional Jet aeroplanes experienced in-flight uncommanded rudder movements. Investigation revealed that a failure of the voltage regulator inside the yaw damper actuator could lead to uncommanded yaw movement. If not corrected, this condition could lead to structural failure and the subsequent loss of the aeroplane.

Since the Challenger 604 aeroplanes have the same system, and can also experience a similar problem of uncommanded yaw movement, Transport Canada is issuing this [Canadian] AD that mandates the introduction of an emergency procedure to the Aeroplane Flight Manual (AFM) to address the above-mentioned unsafe condition.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–0250.

**Relevant Service Information**

Bombardier, Inc. has issued emergency procedures for the applicable AFMs:

- For Model CL–600–2B16 (CL–604 Variant) airplanes having serial numbers (S/Ns) 5301 through 5665 inclusive: Procedure 1.C., Uncommanded Yaw Motion, of Section 03–06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL–604 AFM, PSP 604–1, Revision 89, dated July 8, 2013; and

- For Model CL–600–2B16 (CL–604 Variant) airplanes having S/Ns 5701 and subsequent: Procedure 1.C., Uncommanded Yaw Motion, of Section 03–06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL–605 AFM, PSP 605–1, Revision 25, dated July 8, 2013.

The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

**FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

**Costs of Compliance**

We estimate that this proposed AD affects 116 airplanes of U.S. registry.

We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product.

Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$9,860, or \$85 per product.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. FAA–2014–0250; Directorate Identifier 2013–NM–165–AD.

#### (a) Comments Due Date

We must receive comments by June 5, 2014.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. Model CL–600–2B16 (CL–604 Variants) airplanes, certificated in any category, serial numbers (S/Ns) 5301 through 5665 inclusive, and 5701 and subsequent.

#### (d) Subject

Air Transport Association (ATA) of America Code 22, Autopilot System; and Code 27, Rudder Actuator.

#### (e) Reason

This AD was prompted by reports of in-flight uncommanded rudder movements. We are issuing this AD to prevent in-flight uncommanded rudder movements, which could lead to structural failure and subsequent loss of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD, revise the Emergency Procedures Section of the applicable Bombardier AFM to incorporate the uncommanded yaw motion procedure specified in paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) For Model CL–600–2B16 (CL–604 Variant) airplanes having S/Ns 5301 through 5665 inclusive: Procedure 1.C., Uncommanded Yaw Motion, of Section 03–06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL–604 AFM, PSP 604–1, Revision 89, dated July 8, 2013.

(2) For Model CL–600–2B16 (CL–604 Variant) airplanes having S/Ns 5701 and subsequent: Procedure 1.C., Uncommanded Yaw Motion, of Section 03–06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL–605 AFM, PSP 605–1, Revision 25, dated July 8, 2013.

#### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, FAA, New York

Aircraft Certification Office (ACO), ANE–170, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or the Design Approval Holder with a State of Design Authority's design organization approval, as applicable). You are required to ensure the product is airworthy before it is returned to service.

#### (i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2013–22, dated August 12, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–0250.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on April 14, 2014.

**Jeffrey E. Duven,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014–08986 Filed 4–18–14; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 1

[Docket No. USCG–2008–1259]

RIN 1625–AB32

### Assessment Framework and Organizational Restatement Regarding Preemption for Certain Regulations Issued by the Coast Guard

**AGENCY:** Coast Guard, DHS.

**ACTION:** Proposed rule; notice of public meetings; request for comments.

**SUMMARY:** The Coast Guard announces two public meetings to receive comments on a notice of proposed rulemaking addressing the Coast Guard's assessment framework for, and restating its position regarding, the federalism implications of regulations issued under the authority of various statutes within Titles 33 and 46 of the United States Code. The meetings will be held in two locations in order to allow for greater public involvement.

**DATES:** The public meetings will be held on the following dates:

- Arlington, VA [Washington, DC-area], May 13, 2014, from 12:30 p.m. to 3 p.m.
- Seattle, WA, May 16, 2014, from 12:30 p.m. to 3 p.m.

The meetings may conclude before the allotted time if all matters for discussion have been addressed. Written comments and related material may also be submitted to Coast Guard personnel specified at that meeting.

Those who plan to attend should notify the Coast Guard of their plans by May 6, 2014, using the contact information in the **FOR FURTHER INFORMATION CONTACT** section of this notice.

The comment period for the proposed rule closes May 26, 2014. All comments and related material submitted after the meeting must either be submitted to our online docket via <http://www.regulations.gov> on or before May 26, 2014, or reach the Docket Management Facility by that date.

**ADDRESSES:** The public meetings will be held at the following locations:

- Arlington, VA [Washington, DC-area]—U.S. Coast Guard Personnel Service Center (PSC), 4200 Wilson Boulevard, Alexander Hamilton Room, 9th floor, Arlington, VA 20598–7200
- Seattle, WA—Henry M. Jackson Federal Building, 915 Second Avenue, North Auditorium, Room 3448, Seattle, WA 98174–1067