

(e) Unsafe Condition

This AD was prompted by reports of fuselage skin cracks at the lower forward corner of the main entry door (MED) 1 cutout. We are issuing this AD to detect and correct skin cracking, which can become large and could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections and Corrective Actions

Except as specified in paragraph (j)(1) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014: Do a detailed inspection and a surface high frequency eddy current inspection for cracking of the fuselage skin at the applicable MED 1 cutout, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014. Do all applicable corrective actions before further flight. Repeat the inspections of the applicable MED 1 cutout thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014. Accomplishing the corrective actions required by this paragraph terminates the repetitive inspection requirements of this paragraph.

(h) Optional Terminating Action

For airplanes on which no crack is found during the initial inspections required by paragraph (g) of this AD: Installing the preventive modification in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014, terminates the repetitive inspections required by paragraph (g) of this AD.

(i) Post-Repair or Post-Modification Repetitive Inspections and Corrective Actions

For airplanes on which the corrective actions required by paragraph (g) of this AD have been done, or airplanes that have installed the preventive modification specified in paragraph (h) of this AD: At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014, do a detailed inspection for cracking of the fuselage skin at the applicable MED 1 cutout, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014, except as specified in paragraph (j)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspection of the fuselage skin at the applicable MED 1 cutout thereafter at the intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014.

(j) Exceptions to Service Information

(1) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014, specifies a compliance time "after the Original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) If any cracking is found during any inspection required by this AD, and Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014, specifies to contact Boeing for appropriate action: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: Nathan.P.Weigand@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-53A2863, dated March 11, 2014.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 2, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-02689 Filed 2-17-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE**Bureau of Industry and Security****15 CFR Parts 730 and 744**

[Docket No. 150123073-5073-01]

RIN 0694-AG48

Updated Statements of Legal Authority for the Export Administration Regulations To Include Presidential Notice of January 21, 2015

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: This rule updates the Code of Federal Regulations (CFR) legal authority paragraphs in the Export Administration Regulations (EAR) to cite a Presidential notice that extended an emergency declared pursuant to the International Emergency Economic Powers Act. This is a procedural rule that only updates authority paragraphs of the EAR. It does not alter any right, obligation or prohibition that applies to any person under the EAR.

DATES: The rule is effective February 18, 2015.

FOR FURTHER INFORMATION CONTACT:

William Arvin, Regulatory Policy Division, Bureau of Industry and Security, Email william.arvin@bis.doc.gov, Telephone: (202) 482-2440.

SUPPLEMENTARY INFORMATION:**Background**

The authority for parts 730 and 744 of the EAR (15 CFR parts 730 and 744) rests, in part, on Executive Order 12947 of January 23, 1995—Prohibiting Transactions With Respect to Terrorists Who Threaten To Disrupt the Middle East Peace Process (60 FR 5079, 3 CFR, 1995 Comp., p. 356) and on annual notices by the President continuing the emergency declared in that order. This rule updates the authority paragraphs in 15 CFR parts 730 and 744 to cite the Notice of January 21, 2015, 80 FR 3461 (January 22, 2015), which is the most

recent notice continuing that emergency.

This rule is purely procedural and makes no changes other than to revise CFR authority paragraphs for the purpose of making the authority citations current. It does not change the text of any section of the EAR, nor does it alter any right, obligation or prohibition that applies to any person under the EAR.

Export Administration Act

Although the Export Administration Act expired on August 20, 2001, the President, through Executive Order 13222 of August 17, 2001, 3 CFR, 2001 Comp., p. 783 (2002), as amended by Executive Order 13637 of March 8, 2013, 78 FR 16129 (March 13, 2013) and as extended by the Notice of August 7, 2014, 79 FR 46959 (August 11, 2014), has continued the Export Administration Regulations in effect under the International Emergency Economic Powers Act (50 U.S.C. 1701). BIS continues to carry out the provisions of the Export Administration Act, as appropriate and to the extent permitted by law, pursuant to Executive Order 13222 as amended by Executive Order 13637.

Rulemaking Requirements

1. Executive Orders 13563 and 12866 direct agencies to assess all costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits (including potential economic, environmental, public health and safety effects, distributive impacts, and equity). This rule does not impose any regulatory burden on the public and is consistent with the goals of Executive Order 13563. This rule has been determined not to be significant for purposes of Executive Order 12866.

2. Notwithstanding any other provision of law, no person is required to respond to, nor shall any person be subject to a penalty for failure to comply with, a collection of information subject to the requirements of the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 *et seq.*) (PRA), unless that collection of information displays a currently valid Office of Management and Budget (OMB) Control Number. This rule does not involve any collection of information.

3. This rule does not contain policies with Federalism implications as that term is defined under Executive Order 13132.

4. The Department finds that there is good cause under 5 U.S.C. 553(b)(3)(B) to waive the provisions of the

Administrative Procedure Act requiring prior notice and the opportunity for public comment because they are unnecessary. This rule only updates legal authority citations. It clarifies information and is non-discretionary. This rule does not alter any right, obligation or prohibition that applies to any person under the EAR. Because these revisions are not substantive changes, it is unnecessary to provide notice and opportunity for public comment. In addition, the 30-day delay in effectiveness required by 5 U.S.C. 553(d) is not applicable because this rule is not a substantive rule. Because neither the Administrative Procedure Act nor any other law requires that notice of proposed rulemaking and an opportunity for public comment be given for this rule, the analytical requirements of the Regulatory Flexibility Act (5 U.S.C. 601 *et seq.*) are not applicable.

List of Subjects

15 CFR Part 730

Administrative practice and procedure, Advisory committees, Exports, Reporting and recordkeeping requirements, Strategic and critical materials.

15 CFR Part 744

Exports, Reporting and recordkeeping requirements, Terrorism.

Accordingly, parts 730 and 744 of the EAR (15 CFR parts 730–774) are amended as follows:

PART 730—[AMENDED]

■ 1. The authority citation for 15 CFR part 730 is revised to read as follows:

Authority: 50 U.S.C. app. 2401 *et seq.*; 50 U.S.C. 1701 *et seq.*; 10 U.S.C. 7420; 10 U.S.C. 7430(e); 22 U.S.C. 287c; 22 U.S.C. 2151 note; 22 U.S.C. 3201 *et seq.*; 22 U.S.C. 6004; 30 U.S.C. 185(s), 185(u); 42 U.S.C. 2139a; 42 U.S.C. 6212; 43 U.S.C. 1354; 15 U.S.C. 1824a; 50 U.S.C. app. 5; 22 U.S.C. 7201 *et seq.*; 22 U.S.C. 7210; E.O. 11912, 41 FR 15825, 3 CFR, 1976 Comp., p. 114; E.O. 12002, 42 FR 35623, 3 CFR, 1977 Comp., p. 133; E.O. 12058, 43 FR 20947, 3 CFR, 1978 Comp., p. 179; E.O. 12214, 45 FR 29783, 3 CFR, 1980 Comp., p. 256; E.O. 12851, 58 FR 33181, 3 CFR, 1993 Comp., p. 608; E.O. 12854, 58 FR 36587, 3 CFR, 1993 Comp., p. 179; E.O. 12918, 59 FR 28205, 3 CFR, 1994 Comp., p. 899; E.O. 12938, 59 FR 59099, 3 CFR, 1994 Comp., p. 950; E.O. 12947, 60 FR 5079, 3 CFR, 1995 Comp., p. 356; E.O. 12981, 60 FR 62981, 3 CFR, 1995 Comp., p. 419; E.O. 13020, 61 FR 54079, 3 CFR, 1996 Comp., p. 219; E.O. 13026, 61 FR 58767, 3 CFR, 1996 Comp., p. 228; E.O. 13099, 63 FR 45167, 3 CFR, 1998 Comp., p. 208; E.O. 13222, 66 FR 44025, 3 CFR, 2001 Comp., p. 783; E.O. 13224, 66 FR 49079, 3 CFR, 2001 Comp., p. 786; E.O. 13338, 69 FR 26751, 3 CFR, 2004 Comp., p.

168; E.O. 13637 of March 8, 2013, 78 FR 16129 (March 13, 2013); Notice of May 7, 2014, 79 FR 26589 (May 9, 2014); Notice of August 7, 2014, 79 FR 46959 (August 11, 2014); Notice of September 17, 2014, 79 FR 56475 (September 19, 2014); Notice of November 7, 2014, 79 FR 67035 (November 12, 2014); Notice of January 21, 2015, 80 FR 3461 (January 22, 2015).

PART 744—[AMENDED]

■ 2. The authority citation for 15 CFR part 744 is revised to read as follows:

Authority: 50 U.S.C. app. 2401 *et seq.*; 50 U.S.C. 1701 *et seq.*; 22 U.S.C. 3201 *et seq.*; 42 U.S.C. 2139a; 22 U.S.C. 7201 *et seq.*; 22 U.S.C. 7210; E.O. 12058, 43 FR 20947, 3 CFR, 1978 Comp., p. 179; E.O. 12851, 58 FR 33181, 3 CFR, 1993 Comp., p. 608; E.O. 12938, 59 FR 59099, 3 CFR, 1994 Comp., p. 950; E.O. 12947, 60 FR 5079, 3 CFR, 1995 Comp., p. 356; E.O. 13026, 61 FR 58767, 3 CFR, 1996 Comp., p. 228; E.O. 13099, 63 FR 45167, 3 CFR, 1998 Comp., p. 208; E.O. 13222, 66 FR 44025, 3 CFR, 2001 Comp., p. 783; E.O. 13224, 66 FR 49079, 3 CFR, 2001 Comp., p. 786; Notice of January 21, 2014, 79 FR 3721 (January 22, 2014); Notice of August 7, 2014, 79 FR 46959 (August 11, 2014); Notice of September 17, 2014, 79 FR 56475 (September 19, 2014); Notice of January 21, 2015, 80 FR 3461 (January 22, 2015).

Dated: February 9, 2015.

Matthew S. Borman,

Deputy Assistant Secretary for Export Administration.

[FR Doc. 2015-03318 Filed 2-17-15; 8:45 am]

BILLING CODE 3510-33-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Parts 740 and 742

[Docket No. 140812661–4661–01]

RIN 0694–AG24

Revisions to License Exception Availability for Consumer Communications Devices and Licensing Policy for Civil Telecommunications-Related Items Such as Infrastructure Regarding Sudan

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: This rule amends the Export Administration Regulations to revise the general licensing policy of denial to one of case-by-case licensing for exports and reexports to Sudan of telecommunications equipment and associated computers, software, and technology for civil end use, including items useful for the development of civil telecommunications network