

Rules and Regulations

Federal Register

Vol. 80, No. 166

Thursday, August 27, 2015

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0625; Directorate Identifier 2015-NE-09-AD; Amendment 39-18253; AD 2015-17-20]

RIN 2120-AA64

Airworthiness Directives; GE Aviation Czech s.r.o. Turboprop Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain serial number (S/N) GE Aviation Czech s.r.o. M601E-11, M601E-11A, and M601F turboprop engines with certain part number (P/N) gas generator turbine (GGT) blades, installed. This AD requires removing from service any affected engine with certain GGT blades installed. This AD was prompted by the determination that certain GGT blades are susceptible to blade failure. We are issuing this AD to prevent GGT blade failure, which could lead to engine failure and loss of the airplane.

DATES: This AD becomes effective October 1, 2015.

ADDRESSES: See the **FOR FURTHER INFORMATION CONTACT** section.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0625; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other

information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to the specified products. The NPRM was published in the **Federal Register** on April 21, 2015 (80 FR 22136). The NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been demonstrated that non-shot peened Gas Generator Turbine (GGT) blades are susceptible to blade separation in the shank area due to their reduced fatigue life.

This condition, if not corrected, could lead to an in-flight engine shutdown and, consequently, reduced control of the aeroplane.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (80 FR 22136, April 21, 2015).

In our review of the NPRM, we found that we had included an S/N from the MCAI that was in error. We corrected the error by removing S/N 961001 from paragraph (c)(2) of this AD.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting this AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Costs of Compliance

We estimate that this AD affects one engine installed on an airplane of U.S. registry. We also estimate that it would take about 64 hours per engine to comply with this AD. The average labor

rate is \$85 per hour. Required parts cost about \$28,765 per engine. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$34,205.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2015–17–20 GE Aviation Czech s.r.o. (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.): Amendment 39–18253; Docket No. FAA–2015–0625; Directorate Identifier 2015–NE–09–AD.

(a) Effective Date

This AD becomes effective October 1, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to certain serial number (S/N) GE Aviation Czech s.r.o. M601E–11, M601E–11A, and M601F turboprop engine models, with gas generator turbine (GGT) blade, part number (P/N) M601–3372.6 or M601–3372.51, installed, as follows:

(1) Model M601E–11: S/Ns 862001, 863008, 894018, 034005, 034006, 034007, 034008, 041003, and 042002.

(2) Model M601E–11A: S/Ns 042003, 042004, 044001, and 044002.

(3) Model M601F: S/Ns 024001, 002001, 003001, 934001, 934002, 961001.

(d) Reason

This AD was prompted by the determination that certain GGT blades are susceptible to blade failure. These blades are identified as blade P/Ns M601–3372.6 and M601–3372.51, and are installed on an engine S/N identified in paragraph (c) of this AD. We are issuing this AD to prevent GGT blade failure, which could lead to engine failure and loss of the airplane.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done. After the effective date of this AD:

(1) Do not return to service any affected engine with GGT blade, P/N M601–3372.6 or M601–3372.51, installed, after 300 hours time in service or six months, whichever occurs first, after the effective date of this AD.

(2) If the affected engines are subsequently disassembled or overhauled, the non-shot peened GGT blades, P/N M601–3372.6 or M601–3372.51, are not eligible for installation in any other engine after removal.

(f) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(g) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7754; fax: 781–238–7199; email: robert.green@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2015–0015, dated January 30, 2015, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in <http://www.regulations.gov/#/documentDetail;D=FAA-2015-0625-0002>.

(h) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on August 20, 2015.

Colleen M. D'Alessandro,

Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2015–21119 Filed 8–26–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2015–3375; Amendment No. 71–47]

RIN 2120–AA66

Airspace Designations; Incorporation by Reference

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 relating to airspace designations to reflect the approval by the Director of the Federal Register of the incorporation by reference of FAA Order 7400.9Z, Airspace Designations and Reporting Points. This action also explains the procedures the FAA will use to amend the listings of Class A, B, C, D, and E airspace areas; air traffic service routes; and reporting points incorporated by reference.

DATES: These regulations are effective September 15, 2015, through September 15, 2016. The incorporation by reference of FAA Order 7400.9Z is approved by the Director of the Federal Register as of

September 15, 2015, through September 15, 2016.

ADDRESSES: FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at <http://www.faa.gov/airtraffic/publications/>. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to http://www.archives.gov/federal-register/code_of_federal-regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT:

Sarah A. Combs, Airspace Policy and Regulations Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

History

FAA Order 7400.9Y, Airspace Designations and Reporting Points, effective September 15, 2014, listed Class A, B, C, D and E airspace areas; air traffic service routes; and reporting points. Due to the length of these descriptions, the FAA requested approval from the Office of the Federal Register to incorporate the material by reference in the Federal Aviation Regulations section 71.1, effective September 15, 2014, through September 15, 2015. During the incorporation by reference period, the FAA processed all proposed changes of the airspace listings in FAA Order 7400.9Y in full text as proposed rule documents in the **Federal Register**. Likewise, all amendments of these listings were published in full text as final rules in the **Federal Register**. This rule reflects the periodic integration of these final rule amendments into a revised edition of Order 7400.9Z, Airspace Designations and Reporting Points. The Director of the Federal Register has approved the incorporation by reference of FAA Order 7400.9Z in section 71.1, as of September 15, 2015, through September 15, 2016. This rule also explains the procedures the FAA will use to amend the airspace designations incorporated by reference in part 71. Sections 71.5,