

this AD, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(h) Definition of Detailed Inspection

For the purposes of this AD, a detailed inspection is an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as a mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(i) Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g)(1) of this AD to Serge KIYMAZ, Structure Engineer, Structure Engineering—SEES1 CUSTOMER SERVICES, Phone: +33(0)5 82 05 10 33, Fax: +33(0)5 61 93 36 14, email: serge.kiymaz@airbus.com, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the information identified in Airbus AOT A52L010-14, dated September 30, 2014.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Parts Installation Limitation

As of the effective date of this AD, installation of a forward cargo door having any part number specified in paragraphs (g)(1)(i) through (g)(1)(xii) of this AD is permitted on any airplane, provided that prior to installation, the door is inspected and, depending on the findings, corrected, in accordance with Airbus AOT A52L010-14, dated September 30, 2014, except as required by paragraph (k) of this AD.

(k) Exception to the Service Information

On page 1 of Airbus AOT A52L010-14, dated September 30, 2014, at section "2. Referenced Documentation," "Ref. 5" specifies page block "PB.801," which is incorrect. This page block should be "PB.401" instead.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM 116, Transport Airplane Directorate, FAA, 1601 Lind

Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES 200.

(m) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0228, dated October 20, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0675-0002>.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A52L010-14, dated September 30, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 25, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-30820 Filed 12-21-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2015-7213; Airspace Docket No. 15-ASO-12]

RIN 2120-AA66

Amendment of Restricted Areas R-2932, R-2933, R-2934 and R-2935; Cape Canaveral, FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action updates the using agency information for restricted areas R-2932, R-2933, R-2934 and R-2935; Cape Canaveral, FL. This is an administrative change to reflect the current organization tasked with using agency responsibilities for the restricted areas. It does not affect the boundaries, designated altitudes, time of designation or activities conducted within the restricted areas.

DATES: Effective date: 0901 UTC, March 31, 2016.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to

assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it updates the using agency for restricted areas R-2932, R-2933, R-2934 and R-2935; Cape Canaveral, FL to reflect the current organization responsible for the restricted areas.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 73 by updating the using agency name for restricted areas R-2932, R-2933, R-2934 and R-2935; Cape Canaveral, FL, to Commander, 45th Space Wing, Patrick AFB, FL. The name change reflects the current organization assigned using agency responsibilities for the restricted areas. This is an administrative change that does not affect the boundaries, designated altitudes, or activities conducted within the restricted areas; therefore, notice and public procedure under 5 U.S.C. 553(b) are unnecessary.

Regulatory Notices and Analyses

The FAA has determined that this action only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5.d. This airspace action is an administrative change to the description of restricted areas R-2932, R-2933, R-2934 and R-2935; Cape Canaveral, FL, to update the using agency name. It does not alter the dimensions, altitudes, time of designation, or use of the airspace; therefore, it is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exists that warrant

preparation of an environmental assessment.

List of Subjects in 14 CFR Part 73

Airspace, Prohibited areas, Restricted areas.

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 73, as follows:

PART 73—SPECIAL USE AIRSPACE

- 1. The authority citation for part 73 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 73.29 [Amended]

- 2. § 73.29 is amended as follows:

* * * * *

R-2932 Cape Canaveral, FL [Amended]

By removing the words "Using agency. Commander, 1st Range Operations Squadron, Cape Canaveral AFS, FL" and inserting in their place "Using agency. Commander, 45th Space Wing, Patrick AFB, FL."

R-2933 Cape Canaveral, FL [Amended]

By removing the words "Using agency. Commander, 1st Range Operations Squadron, Cape Canaveral AFS, FL" and inserting in their place "Using agency. Commander, 45th Space Wing, Patrick AFB, FL."

R-2934 Cape Canaveral, FL [Amended]

By removing the words "Using agency. Commander, 1st Range Operations Squadron, Cape Canaveral AFS, FL" and inserting in their place "Using agency. Commander, 45th Space Wing, Patrick AFB, FL."

R-2935 Cape Canaveral, FL [Amended]

By removing the words "Using agency. Commander, 1st Range Operations Squadron, Cape Canaveral AFS, FL" and inserting in their place "Using agency. Commander, 45th Space Wing, Patrick AFB, FL."

* * * * *

Issued in Washington, DC, on December 14, 2015.

Leslie M. Swann,

Acting Manager, Airspace Policy Group.

[FR Doc. 2015-32159 Filed 12-21-15; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Parts 200, 227, 232, 239, 240, 249, 269, and 274

[Release Nos. 33-9974A; 34-76324A; File No. S7-09-13]

RIN 3235-AL37

Crowdfunding; Correction

AGENCY: Securities and Exchange Commission.

ACTION: Final rule; correction.

SUMMARY: The Securities and Exchange Commission published in the **Federal Register** of November 16, 2015, the final rule, Regulation Crowdfunding, under the Securities Act of 1933 and the Securities Exchange Act of 1934 to implement the requirements of Title III of the Jumpstart Our Business Startups Act of 2012. The effective date for subpart U, which adds Form Funding Portal, was inadvertently omitted in the **DATES** section of the **Federal Register**. This correction adds the effective date for subpart U, Form Funding Portal.

DATES: Effective December 22, 2015.

FOR FURTHER INFORMATION CONTACT: Timothy White or Erin Galipeau, Division of Trading and Markets, at (202) 551-5550, Securities and Exchange Commission, 100 F Street NE., Washington, DC 20549.

SUPPLEMENTARY INFORMATION:

Correction

In rule FR Doc. 2015-28220 published on November 16, 2015, (80 FR 71388) make the following correction:

On page 71388, in the first column, the **DATES** section is revised to read as follows:

“**DATES:** The final rules and forms are effective May 16, 2016, except for instruction 3 adding part 227, instruction 12 adding subpart U to part 249, and instruction 15 amending Form ID, which are effective January 29, 2016.”

Dated: December 17, 2015.

Brent J. Fields,

Secretary.

[FR Doc. 2015-32106 Filed 12-21-15; 8:45 am]

BILLING CODE 8011-01-P