

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2017-10-11 Stemme AG: Amendment 39-18885; Docket No. FAA-2017-0451; Directorate Identifier 2017-CE-015-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective June 15, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Stemme AG Model S10-VT gliders (type certificate previously held by Stemme GmbH & Co. KG), all serial numbers, that are:

(1) Equipped with a front gearbox, part number (P/N) 11AG, with a serial number listed in table 1 to paragraph (c) of this AD; and

(2) are certificated in any category.

TABLE 1 TO PARAGRAPH (c) OF THIS AD—AFFECTED P/N 11AG (FRONT GEARBOX) S/NS

80058/0814	80065/0616
80059/0915	80066/0716
80060/0915	80067/0916
80061/1115	80068/1016
80062/1215	80069/0117
80063/0116	80070/0217
80064/0416	80071/0217

Note 1 to paragraph (c) of this AD: Page 2 of Stemme AG Service Bulletin No. P062-980010, dated April 21, 2017, provides a pictorial of where the serial number of the affected gearboxes are located.

(d) Subject

Air Transport Association of America (ATA) Code 61: Propellers/Propulsors.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as certain propeller front transmission gear wheels having insufficient material strength because of improper heat treatment during manufacturing. We are issuing this AD to prevent failure of the propeller front transmission gear wheels. This failure could cause loss of power between the engine and the propeller, which could result in reduced control.

(f) Actions and Compliance

Unless already done, do the following actions.

(1) Before further flight after June 15, 2017 (the effective date of this AD), replace the front gearbox following a method approved specifically for this AD by the FAA, Small Airplane Directorate. Contact the FAA using the information in paragraph (g)(1) of this AD to obtain FAA-approved repair instructions approved specifically for compliance with this AD and incorporate those instructions.

Note 2 to paragraph (f)(1) of this AD: At the issue date of this AD, no design solution is available to restore the airworthiness of the respective type design to a level corresponding to its approved type design specifications.

(2) As of June 15, 2017 (the effective date of this AD), do not install a front gear box listed in paragraph (c) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any glider to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

(1) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2017-0072-E, dated April 26, 2017, and Stemme AG Service Bulletin No. P062-980010, dated

April 21, 2017, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0451.

(2) For information concerning this action, contact STEMME AG service information identified in this AD, contact STEMME AG, Flugplatzstrasse F2, Nr. 6-7, D-15344 Strausberg, Germany; telephone: +49 (0) 3341-3612-0, fax: +49 (0) 3341-3612-30; Internet: www.stemme.com.

Issued in Kansas City, Missouri, on May 9, 2017.

Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-10402 Filed 5-25-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2016-9511; Airspace Docket No. 16-ASW-20]

Amendment of Class D Airspace; Kingsville, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the legal description of Class D airspace extending up to 2,500 feet above the surface at Kingsville Naval Air Station (NAS), Kingsville, TX. This action is necessary due to the decommissioning of the Kingsville radio beacon (RBN), and cancellation of the RBN approach, and enhances the safety and management of instrument flight rules (IFR) operations at the airport. This action also updates the geographic coordinates of Kingsville Naval Air Station, Kingsville, TX, to coincide with the FAA's aeronautical database.

DATES: Effective 0901 UTC, September 14, 2017. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the

National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11A at NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal-regulations/ibr_locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Ron Laster, Federal Aviation Administration, Contract Support, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5879.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends controlled airspace at Kingsville NAS, Kingsville, TX.

History

On March 27, 2017, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to modify Class D airspace at Kingsville NAS, Kingsville, TX (82 FR 15172). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class D airspace designations are published in paragraph 5000, of FAA Order 7400.11A, dated August 3, 2016, and effective September 15, 2016, which is incorporated by reference in 14 CFR part 71.1. The Class D airspace designation listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016. FAA Order 7400.11A is publicly available as

listed in the **ADDRESSES** section of this document. FAA Order 7400.11A lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

The FAA is finalizing this amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 by modifying Class D airspace extending up to and including 2,500 feet MSL within a 4.3-mile radius of Kingsville NAS by removing the area within two miles each side of the 200 degree bearing from the Kingsville RBN extending from the 4.3-mile radius to 4.9 miles south of the airport. This action also updates the geographic coordinates of the airport to be in concert with the FAA's aeronautical database.

Airspace reconfiguration is necessary due to the decommissioning of the RBN and cancellation of the RBN approach, and enhances the safety and management of standard instrument approach procedures for IFR operations at the airport.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016, is amended as follows:

Paragraph 6000 Class D Airspace Areas.
* * * * *

ASW TX D Kingsville, TX [Amended]

Kingsville Naval Air Station (NAS), TX
(Lat. 27°30'16" N., long. 97°48'30" W.)
Kingsville TACAN
(Lat. 27°29'57" N., long. 97°48'20" W.)

That airspace extends upward from the surface to and including 2,500 feet MSL within a 4.3-mile radius of Kingsville NAS, and within 1.3 miles each side of the 191° radial of the Kingsville TACAN extending from the 4.3-mile radius to 4.9 miles south of the airport.

Issued in Fort Worth, Texas on May 11, 2017.

Walter Tweedy,

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2017-10429 Filed 5-25-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 744

[Docket No. 170303229-7229-01]

RIN 0694-AH36

Addition of Certain Persons and Revisions to Entries on the Entity List

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: This rule amends the Export Administration Regulations (EAR) by