

38. The DHS/ALL-025 Law Enforcement Authority in Support of the Protection of Property Owned or Occupied by the Department of Homeland Security system of records consists of electronic and paper records and will be used by DHS and its components. The DHS/ALL-025 Law Enforcement Authority in Support of the Protection of Property Owned or Occupied by the Department of Homeland Security system is a repository of information held by DHS in connection with its several and varied missions and functions, including: The enforcement of civil and criminal laws; investigations, inquiries, and proceedings there under; and national security and intelligence activities. The DHS/ALL-025 Law Enforcement Authority in Support of the Protection of Property Owned or Occupied by the Department of Homeland Security system contains information that is collected by, on behalf of, in support of, or in cooperation with DHS and its components and may contain personally identifiable information collected by other federal, state, local, tribal, foreign, or international government agencies. The Secretary of Homeland Security, pursuant to 5 U.S.C. 552a(j)(2), has exempted this system from the following provisions of the Privacy Act: 5 U.S.C. 552a(c)(3), (c)(4); (d); (e)(1), (e)(2), (e)(3), (e)(4)(G), (e)(4)(H), (e)(4)(I), (e)(5), (e)(8); (f), (g)(1). Additionally, the Secretary of Homeland Security, pursuant to 5 U.S.C. 552a(k)(1), (k)(2), and (k)(5), has exempted this system from the following provisions of the Privacy Act: 5 U.S.C. 552a(c)(3); (d); (e)(1), (e)(4)(G), (e)(4)(H), (e)(4)(I); and (f). When a record received from another system has been exempted in that source system under 5 U.S.C. 552a(j)(2), DHS will claim the same exemptions for those records that are claimed for the original primary systems of records from which they originated and claims any additional exemptions set forth here. Exemptions from these particular subsections are justified, on a case-by-case basis to be determined at the time a request is made, for the following reasons:

(a) From subsection (c)(3) and (4) (Accounting for Disclosures) because release of the accounting of disclosures could alert the subject of an investigation of an actual or potential criminal, civil, or regulatory violation to the existence of that investigation and reveal investigative interest on the part of DHS as well as the recipient agency. Disclosure of the accounting would therefore present a serious impediment to law enforcement efforts and/or efforts to preserve national security. Disclosure of the accounting would also permit the individual who is the subject of a record to impede the investigation, to tamper with witnesses or evidence, and to avoid detection or apprehension, which would undermine the entire investigative process.

(b) From subsection (d) (Access to Records) because access to the records contained in this system of records could inform the subject of an investigation of an actual or potential criminal, civil, or regulatory violation to the existence of that investigation and reveal investigative interest on the part of DHS or another agency. Access to the records could permit the individual who is

the subject of a record to impede the investigation, to tamper with witnesses or evidence, and to avoid detection or apprehension. Amendment of the records could interfere with ongoing investigations and law enforcement activities and would impose an unreasonable administrative burden by requiring investigations to be continually reinvestigated. In addition, permitting access and amendment to such information could disclose security-sensitive information that could be detrimental to homeland security.

(c) From subsection (e)(1) (Relevancy and Necessity of Information) because in the course of investigations into potential violations of federal law, the accuracy of information obtained or introduced occasionally may be unclear, or the information may not be strictly relevant or necessary to a specific investigation. In the interests of effective law enforcement, it is appropriate to retain all information that may aid in establishing patterns of unlawful activity.

(d) From subsection (e)(2) (Collection of Information from Individuals) because requiring that information be collected from the subject of an investigation would alert the subject to the nature or existence of the investigation, thereby interfering with that investigation and related law enforcement activities.

(e) From subsection (e)(3) (Notice to Subjects) because providing such detailed information could impede law enforcement by compromising the existence of a confidential investigation or reveal the identity of witnesses or confidential informants.

(f) From subsections (e)(4)(G), (e)(4)(H), and (e)(4)(I) (Agency Requirements) and (f) (Agency Rules), because portions of this system are exempt from the individual access provisions of subsection (d) for the reasons noted above, and therefore DHS is not required to establish requirements, rules, or procedures with respect to such access. Providing notice to individuals with respect to the existence of records pertaining to them in the system of records or otherwise setting up procedures pursuant to which individuals may access and view records pertaining to themselves in the system would undermine investigative efforts and reveal the identities of witnesses, and potential witnesses, and confidential informants.

(g) From subsection (e)(5) (Collection of Information) because with the collection of information for law enforcement purposes, it is impossible to determine in advance what information is accurate, relevant, timely, and complete. Compliance with subsection (e)(5) would preclude DHS agents from using their investigative training and exercise of good judgment to both conduct and report on investigations.

(h) From subsection (e)(8) (Notice on Individuals) because compliance would interfere with DHS's ability to obtain, serve, and issue subpoenas, warrants, and other law enforcement mechanisms that may be filed under seal and could result in disclosure of investigative techniques, procedures, and evidence.

(i) From subsection (g)(1) (Civil Remedies) to the extent that the system is exempt from other specific subsections of the Privacy Act.

Dated: June 8, 2017.

Jonathan R. Cantor,
Acting Chief Privacy Officer, Department of Homeland Security.

[FR Doc. 2017-12253 Filed 6-13-17; 8:45 am]

BILLING CODE 9110-9B-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0338; Directorate Identifier 2016-NM-153-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL-600-2A12 (CL-601 Variant) and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants) airplanes. This proposed AD was prompted by a determination that the bushing holes on the engine mount rib might not conform to the engineering drawings and that certain inspections of the engine mount rib must be included in the airworthiness limitations section (ALS) of the Instructions for Continued Airworthiness (ICA). This proposed AD would require revising the maintenance or inspection program to incorporate certain airworthiness limitation items (ALIs). We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 31, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0338; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Aziz Ahmed, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, New York Aircraft Certification Office (ACO), FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7329; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2017-0338; Directorate Identifier 2016-NM-153-AD” at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2015-09R1, dated June 29, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2A12 (CL-601 Variant), and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants) airplanes. The MCAI states:

The aeroplane manufacturer has determined that the bushing holes on the engine mount rib may not conform to the engineering drawings. Non-conforming bushing holes could increase loading on adjacent fasteners, resulting in premature fatigue cracking of the engine mount rib.

In addition, it was also discovered that the inspection requirements for the engine mount rib were not listed in the Airworthiness Limitations Section of the Instructions for Continued Airworthiness.

Failure of the engine mount rib could compromise the structural integrity of the engine mount and could lead to subsequent detachment of an engine.

A new Time Limits/Maintenance Checks (TLMC) Airworthiness Limitations (AWL) task is introduced to ensure that any fatigue cracking of the engine mount rib is detected and corrected.

The original issue of this [Canadian] AD mandated the incorporation of a new TLMC AWL task [into the maintenance or inspection program, as applicable].

Revision 1 of this [Canadian] AD is issued to remove model CL-600-1A11 (600)

aeroplanes from the Applicability section of the [Canadian] AD since this model was incorrectly included in the original issue.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0338.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

This AD requires revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance under the provisions of paragraph (i)(1) of this proposed AD. The request should include a description of changes to the required actions that will ensure the continued damage tolerance of the affected structure.

Costs of Compliance

We estimate that this proposed AD affects 129 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revision of maintenance or inspection program ...	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$10,965

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII:

Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that

section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2017–0338; Directorate Identifier 2016–NM–153–AD.

(a) Comments Due Date

We must receive comments by July 31, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Bombardier, Inc., airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Bombardier, Inc., Model CL–600–2A12 (CL–601) airplanes, having serial numbers (S/Ns) 3001 through 3066 inclusive.

(2) Bombardier, Inc., Model CL–600–2B16 (CL–601–3A and CL–601–3R Variants) airplanes, having S/Ns 5001 through 5194 inclusive.

(3) Bombardier, Inc., Model CL–600–2B16 (CL–604 Variant) airplanes, having S/Ns 5301 through 5665 inclusive, and 5701 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 05, Periodic inspections.

(e) Reason

This AD was prompted by a determination that the bushing holes on the engine mount rib may not conform to the engineering drawings and that certain inspections of the engine mount rib must be included in the airworthiness limitations section (ALS) of the Instructions for Continued Airworthiness (ICA). We are issuing this AD to detect and correct failure of an engine mount rib. Failure of an engine mount rib could compromise the structural integrity of the engine mount and could lead to subsequent detachment of an engine.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 60 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate maintenance tasks, in accordance with a method approved by the Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA.

Note 1 to paragraph (g) of this AD: Applicable information on tasks required by paragraph (g) of this AD can be found in Chapter 5 of Time Limits/Maintenance Checks (TLMC) Manual PSP 601–5 (for Model CL–600–2A12 (CL–601 Variant) airplanes), TLMC Manual PSP 601A–5 (for CL–600–2B16 (CL–601–3A and CL–601–3R Variants) airplanes), TLMC Manual CL–604 (for Model CL–600–2B16 (CL–604 Variant) airplanes, S/Ns 5301 through 5665 inclusive), and TLMC Manual CL–605 (for Model CL–600–2B16 (CL–604 Variant) airplanes, S/Ns 5701 and subsequent).

(h) No Alternative Actions and/or Intervals

After the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) and/or intervals may be used, unless the actions and/or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO, ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In

accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2015–09R1, dated June 29, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0338.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE–171, New York Aircraft Certification Office (ACO), FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7329; fax 516–794–5531.

Issued in Renton, Washington, on May 8, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–09846 Filed 6–13–17; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R06–OAR–2015–0833; FRL–9962–49–Region 6]

Approval and Promulgation of Implementation Plans; Texas; Clean Air Act Requirements for Vehicle Inspection and Maintenance and Nonattainment New Source Review

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: Pursuant to the Federal Clean Air Act (CAA or Act), the Environmental Protection Agency (EPA) is proposing to approve a State Implementation Plan (SIP) revision submitted by the State of Texas for the