

Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2015–02–22, Amendment 39–18090 (80 FR 5452, February 2, 2015), and adding the following new AD:

2017–18–14 Rolls-Royce Corporation:
Amendment 39–19023; Docket No. FAA–2011–0961; Product Identifier 2011–NE–22–AD.

(a) Effective Date

This AD is effective October 13, 2017.

(b) Affected ADs

This AD replaces Airworthiness Directive (AD) 2015–02–22, Amendment 39–18090 (80 FR 5452, February 2, 2015).

(c) Applicability

This AD applies to Rolls-Royce Corporation (RRC) 250–C20, –C20B, –C20F, –C20J, –C20R, –C20R/1, –C20R/2, –C20R/4, –C20W, –C300/A1, and –C300/B1 turboshaft engines with either a 3rd-stage turbine wheel, part number (P/N) 23065818, or a 4th-stage turbine wheel, P/N 23055944 or RR30000240, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by in-service turbine wheel blade failures that revealed the need for changes to the inspections of certain 3rd-stage turbine wheels and removal from service of certain 4th-stage turbine wheels. We are issuing this AD to prevent failure of the 3rd-stage and 4th-stage turbine wheel blades, damage to the engine, and damage to the aircraft.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 1,775 hours since last visual inspection and fluorescent-penetrant inspection (FPI) or before the next flight after the effective date of this AD, whichever occurs later:

(i) Remove 3rd-stage turbine wheels, P/N 23065818, and perform a visual inspection and an FPI on the removed turbine wheels for cracks at the trailing edge of the turbine blades, near the fillet at the rim.

(ii) Thereafter, re-inspect the affected turbine wheels every 1,775 hours since last inspection (HSLI).

(2) Any time the turbine is disassembled, perform a visual inspection and an FPI on 3rd-stage turbine wheels, P/N 23065818, for cracks at the trailing edge of the turbine blades, near the fillet at the rim.

(3) Do not return to service any turbine wheels found to have cracks at the trailing edge, near the fillet at the rim, of the turbine blades.

(4) Within 1,775 HSLI, or at the next engine shop visit, whichever occurs later, remove 4th-stage turbine wheels, P/N 23055944, from service.

(5) Within 2,025 HSLI, or at the next engine shop visit, whichever occurs later, remove 4th-stage turbine wheels, P/N RR30000240, from service.

(g) Definition

For the purpose of this AD, an "engine shop visit" is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, FAA, Chicago ACO Branch, Compliance and Airworthiness Division, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO Branch, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact John Tallarovic, Aerospace Engineer, FAA, Chicago ACO Branch, Compliance and Airworthiness Division, 2300 E. Devon Ave., Des Plaines, IL 60018; phone: 847–294–8180; fax: 847–294–7834; email: john.m.tallarovic@faa.gov.

(j) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on August 31, 2017.

Robert J. Ganley,

Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2017–18910 Filed 9–7–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2016–9593; Airspace Docket No. 16–ACE–12]

Amendment of Class E Airspace; Falls City, NE

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies Class E airspace extending upward from 700 feet above the surface at Brenner Field

Airport, Falls City, NE. Airspace reconfiguration is necessary due to the decommissioning of the Brenner non-directional radio beacon (NDB), and cancellation of the NDB approach. This action enhances the safety and management of standard instrument approach procedures for instrument flight rules (IFR) operations at the airport.

DATES: Effective 0901 UTC, December 7, 2017. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11A at NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Walter Tweedy, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5900.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would modify Class E airspace extending upward from 700 feet above the surface

area at Brenner Field Airport, Falls City, NE, in support of standard instrument approach procedures for IFR operations at the airport.

History

The FAA published in the **Federal Register** (82 FR 16960, April 7, 2017) Docket No. FAA-2016-9593 a notice of proposed rulemaking (NPRM) to modify Class E airspace extending upward from 700 feet above the surface at Brenner Field Airport, Falls City, NE. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11A, dated August 3, 2016, and effective September 15, 2016, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016. FAA Order 7400.11A is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11A lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 modifies Class E airspace extending upward from 700 feet above the surface within a 6.5-mile radius (increased from 6.4 miles) of Brenner Field and cancels the NDB approach due to the decommissioning of the Brenner NDB. This action enhances the safety and management of the standard instrument approach procedures for IFR operations at the airport.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a

regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016, is amended as follows:

Paragraph 6005 Class E Airspace Areas.
* * * * *

ACE NE E5 Falls City, NE [Amended]

Falls City, Brenner Field, NE
(Lat. 40°04'44" N., long. 95°35'31" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Brenner Field.

Issued in Fort Worth, Texas on August 29, 2017.

Wayne Eckenrode,

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2017-18917 Filed 9-7-17; 8:45 am]

BILLING CODE 4910-13-P