

# Proposed Rules

Federal Register

Vol. 84, No. 60

Thursday, March 28, 2019

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0185; Product Identifier 2018-NM-178-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary for operational checks of the landing gear alternate extension system (AES). This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive airworthiness limitations. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by May 13, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0185; Product Identifier 2018-NM-178-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this NPRM.

#### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2018-31, dated November 28, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. The MCAI states:

During the Bombardier Maintenance Review Board (MRB) inspection escalation interval project, it was discovered that the current interval of 8000 hours air time and previous interval of 6000 hours air time for the MRB Task 320100-203 “Operational Check of the Landing Gear Alternate Extension System (AES)” does not meet the certification criteria to cover for all critical AES failure modes [which could reduce the ability of the flightcrew to maintain the safe flight and landing of the airplane]. For this reason, a new Certification Maintenance Requirement (CMR) task needs to be implemented in the maintenance program at a shorter interval of 1600 hours air time.

This [Canadian] AD mandates a new CMR task for an operational check of the AES with interval of 1600 hours air time.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185.

#### Related Service Information Under 14 CFR Part 51

Bombardier has issued Temporary Revision (TR) ALI-0652, dated July 9, 2018. This service information describes airworthiness limitations for a CMR task related to operational checks of the landing gear AES. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the

MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

#### Proposed Requirements of This NPRM

This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (i)(1) of this proposed AD.

#### Costs of Compliance

We estimate that this proposed AD affects 536 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

We have determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although we recognize that this number may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. FAA-2019-0185; Product Identifier 2018-NM-178-AD.

#### (a) Comments Due Date

We must receive comments by May 13, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

#### (e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary for operational checks of the landing gear alternate extension system (AES). We are issuing this AD to address a deficiency in the existing maintenance or inspection program, as applicable, that does not meet the certification criteria for all critical AES failure modes, which could reduce the ability of the flightcrew to maintain the safe flight and landing of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Bombardier Temporary Revision (TR) ALI-0652, dated July 9, 2018. The initial compliance time for doing the tasks is at the time specified in figure 1 to paragraph (g) of this AD.

FIGURE 1 TO PARAGRAPH (g) OF THIS AD—COMPLIANCE TIMES

Airplane flight hours	Compliance time
For airplanes with 4,400 flight hours or less since the last inspection done in accordance with Maintenance Review Board (MRB) Task 320100–203.	Within 1,760 flight hours from the effective date of this AD.
For airplanes with more than 4,400 flight hours since the last inspection done in accordance with MRB Task 320100–203.	Within 880 flight hours from the effective date of this AD.

**(h) No Alternative Actions or Intervals**

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(j) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2018–31, dated November 28, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0185.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7323; fax 516–794–5531; email [9-avs-nyacos@faa.gov](mailto:9-avs-nyacos@faa.gov).

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9,

Canada; Widebody Customer Response Center North America toll-free telephone 1–866–538–1247 or direct-dial telephone 1–514–855–2999; fax 514–855–7401; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on March 20, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–05896 Filed 3–27–19; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Office of the Secretary****14 CFR Part 250**

[Docket No. DOT–OST–2019–0025]

**RIN No. 2105–AE67**

**Modernizing Payment of Denied Boarding Compensation**

**AGENCY:** Office of the Secretary (OST), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The Department of Transportation is proposing to amend its rule on oversales to allow airlines to use electronic payment medias that are equivalent to cash as an option in lieu of check or cash payment to compensate passengers who are denied boarding involuntarily due to oversales; and allow airlines to provide a mandatory written denied boarding notice in an oversales situation by electronic means upon passengers' consent, in lieu of a paper copy. This action would not impact airlines' ability to offer a consumer who is denied boarding involuntarily a choice between flight vouchers or credits and the required denied boarding compensation.

**DATES:** Comments should be filed by May 28, 2019. Late-filed comments will be considered to the extent practicable.

**ADDRESSES:** You may file comments identified by the docket number DOT–OST–2019–0025 by any of the following methods:

○ *Federal eRulemaking Portal*: Go to <http://www.regulations.gov> and follow the online instructions for submitting comments.

○ *Mail*: Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Ave. SE, Room W12–140, Washington, DC 20590–0001.

○ *Hand Delivery or Courier*: West Building Ground Floor, Room W12–140, 1200 New Jersey Ave. SE, between 9:00 a.m. and 5:00 p.m. ET, Monday through Friday, except Federal Holidays.

○ *Fax*: (202) 493–2251.

*Instructions*: You must include the agency name and docket number DOT–OST–2019–0025 or the Regulatory Identification Number (RIN) for the rulemaking at the beginning of your comment. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided.

*Privacy Act*: Anyone is able to search the electronic form of all comments received in any of our dockets by the name of the individual submitting the comment (or signing the comment if submitted on behalf of an association, a business, a labor union, etc.). You may review DOT's complete Privacy Act statement in the **Federal Register** published on April 11, 2000 (65 FR 19477–78), or you may visit <http://DocketsInfo.dot.gov>.

*Docket*: For access to the docket to read background documents or comments received, go to <http://www.regulations.gov> or to the street address listed above. Follow the online instructions for accessing the docket.

**FOR FURTHER INFORMATION CONTACT:** Clereece Kroha or Blane A. Workie, Office of Aviation Enforcement and Proceedings, U.S. Department of Transportation, 1200 New Jersey Ave. SE, Washington, DC 20590, 202–366–9342 (phone), 202–366–7152 (fax), [clereece.kroha@dot.gov](mailto:clereece.kroha@dot.gov) or [blane.workie@dot.gov](mailto:blane.workie@dot.gov) (email).

**SUPPLEMENTARY INFORMATION:**