

United Kingdom; phone: 44 1702 549371; fax: 44 1702 540782; email: sales@lpeco.com.

(6) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(7) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on October 25, 2019.

Karen M. Grant,

Acting Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2019-24378 Filed 11-7-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0690; Product Identifier 2018-CE-022-AD; Amendment 39-19761; AD 2019-20-08]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace Corporation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Gulfstream Aerospace Corporation (Gulfstream) Model G-IV and Model GIV-X airplanes. This AD was prompted by a revision to the airworthiness limitations section (ALS) of the aircraft maintenance manual (AMM) based on fatigue and damage tolerance testing and updated analysis. This AD requires revising the maintenance or inspection program to incorporate updated inspection requirements and life limits that address fatigue cracking of principal structural elements. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 13, 2019.

The Director of the Federal Register approved the incorporation by reference

of a certain publication listed in this AD as of December 13, 2019.

ADDRESSES: For service information identified in this final rule, contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, GA 31402-2206; telephone: (800) 810-4853; fax: (912) 965-3520; email: pubs@gulfstream.com; internet: <https://www.gulfstream.com/en/contact/support/#form>. You may view this service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0690.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0690; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Ronald "Ron" Wissing, Airframe Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5552; fax: (404) 474-5606; email: ronald.wissing@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Gulfstream Model G-IV and Model GIV-X airplanes. The SNPRM published in the **Federal Register** on April 2, 2019 (84 FR 12530). The FAA preceded the SNPRM with a notice of proposed rulemaking (NPRM) that published in the **Federal Register** on August 2, 2018 (83 FR 37771). The NPRM proposed to require revising the ALS in the AMM to incorporate new inspections and life limits contained in Gulfstream Document No. GIV-GER-0008, Summary of Changes to the GIV Series and GIV-X Series Airworthiness

Limitations, Revision B, dated March 12, 2018. The NPRM was prompted by a revision to the ALS of the AMM based on fatigue and damage tolerance testing and updated analysis.

After the FAA issued the NPRM, Gulfstream updated the life limits in the ALS and issued Gulfstream Document No. GIV-GER-0008, Summary of Changes to the GIV Series and GIV-X Series Airworthiness Limitations, Revision D, dated August 20, 2018. Revision D differs from Revision B in that the part number (P/N) for the rudder for Model GIV airplanes has been corrected to reflect P/N 1159CS30004, and new life limits for fuselage cockpit side post P/N 1159BM50025-5 and P/N 1159BM50025-6 have been added per Revision C. The SNPRM proposed to require the later revision of the service information. The FAA is issuing this AD to address the unsafe condition on these products.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the SNPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Gulfstream Document No. GIV-GER-0008, Summary of Changes to the GIV Series and GIV-X Series Airworthiness Limitations, Revision D, dated August 20, 2018. This document contains new and revised inspections and life limits pertaining to fatigue cracking of principal structural elements. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 711 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise ALS and AMM	20 work-hours × \$85 per hour = \$1,700.	Not applicable	\$1,700	\$1,208,700

The extent of damage found during the inspection may vary from airplane to airplane. The FAA has no way of determining the number of airplanes that might need repairs or the cost of such repairs for each airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to small airplanes, gliders, balloons, airships, domestic business jet transport airplanes, and associated appliances to the Director of the Policy and Innovation Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–20–08 Gulfstream Aerospace

Corporation: Amendment 39–19761; Docket No. FAA–2018–0690; Product Identifier 2018–CE–022–AD.

(a) Effective Date

This AD is effective December 13, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace Corporation Model G–IV airplanes, certificated in any category, serial numbers 1000 through 1535; and Model GIV–X airplanes, certificated in any category, serial numbers 4001 through 4363.

Note 1 to paragraph (c) of this AD: Model G–IV airplanes are also referred to by the marketing designations G300 and G400. Model GIV–X airplanes are also referred to by the marketing designations G350 and G450.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 27, Flight Controls; 32, Landing Gear; 52, Doors; 53, Fuselage; 55, Stabilizers; 57, Wings; 71, Power Plant-General; and 78, Engine Exhaust.

(e) Unsafe Condition

This AD was prompted by a revision to the airworthiness limitations section (ALS) of the Model G–IV and Model GIV–X aircraft maintenance manuals based on fatigue and damage tolerance testing and updated analysis. The FAA is issuing this AD to detect and correct fatigue cracking of principal structural elements (PSEs). This unsafe condition, if unaddressed, could result in reduced structural integrity of a PSE or critical component and lead to loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Maintenance Manual Revisions

Within 12 months after December 13, 2019 (the effective date of this AD), revise the ALS of your maintenance or inspection program (e.g., maintenance manual) to incorporate the airworthiness limitations specified in Gulfstream Document No. GIV–GER–0008, Summary of Changes to the GIV Series and GIV–X Series Airworthiness Limitations, Revision D, dated August 20, 2018, as applicable to your model and serial number airplane.

(h) No Alternative Actions or Intervals

After the maintenance or inspection program (e.g., maintenance manual) has been revised as required by paragraph (g) of this AD, no alternative inspections or intervals may be used unless approved as an alternative method of compliance in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Ronald "Ron" Wissing, Airframe Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia

30337; phone: (404) 474-5552; fax: (404) 474-5606; email: ronald.wissing@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Gulfstream Document No. GIV-GER-0008, Summary of Changes to the GIV Series and GIV-X Series Airworthiness Limitations, Revision D, dated August 20, 2018.

(ii) [Reserved]

(3) For Gulfstream Aerospace Corporation service information identified in this AD, contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, GA 31402-2206; telephone: (800) 810-4853; fax: (912) 965-3520; email: pubs@gulfstream.com; internet: <https://www.gulfstream.com/en/contact/support/#form>.

(4) You may view this service information at FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on October 29, 2019.

Pat Mullen,

Aircraft Certification Service Manager, Small Airplane Standards Branch, AIR-690.

[FR Doc. 2019-24324 Filed 11-7-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 95

[Docket No. 31282; Amdt. No. 549]

IFR Altitudes; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts miscellaneous amendments to the required IFR (instrument flight rules) altitudes and changeover points for certain Federal airways, jet routes, or direct routes for which a minimum or maximum en route authorized IFR altitude is prescribed. This regulatory action is needed because of changes occurring in the National Airspace System. These changes are designed to provide for the safe and efficient use of the navigable airspace under instrument conditions in the affected areas.

DATES: *Effective:* 0901 UTC, December 5, 2019.

FOR FURTHER INFORMATION CONTACT: Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration, Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg 29 Room 104, Oklahoma City, OK 73125. Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 95 of the Federal Aviation Regulations (14 CFR part 95) amends, suspends, or revokes IFR altitudes governing the operation of all aircraft in flight over a specified route or any portion of that route, as well as the changeover points (COPs) for Federal airways, jet routes, or direct routes as prescribed in part 95.

The Rule

The specified IFR altitudes, when used in conjunction with the prescribed changeover points for those routes, ensure navigation aid coverage that is adequate for safe flight operations and free of frequency interference. The reasons and circumstances that create the need for this amendment involve matters of flight safety and operational efficiency in the National Airspace System, are related to published aeronautical charts that are essential to the user, and provide for the safe and efficient use of the navigable airspace. In addition, those various reasons or circumstances require making this amendment effective before the next scheduled charting and publication date

of the flight information to assure its timely availability to the user. The effective date of this amendment reflects those considerations. In view of the close and immediate relationship between these regulatory changes and safety in air commerce, I find that notice and public procedure before adopting this amendment are impracticable and contrary to the public interest and that good cause exists for making the amendment effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 95

Airspace, Navigation (air).

Issued in Washington, DC on November 1, 2019.

Rick Domingo,

Executive Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, part 95 of the Federal Aviation Regulations (14 CFR part 95) is amended as follows effective at 0901 UTC, December 5, 2019.

■ 1. The authority citation for part 95 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44719, 44721.

■ 2. Part 95 is amended to read as follows:

REVISIONS TO IFR ALTITUDES & CHANGEOVER POINT

[Amendment 549 Effective Date, December 05, 2019]

From	To	MEA	MAA
§ 95.4000 High Altitude RNAV Routes			
§ 95.4121 RNAV Route Q121 Is Amended To Read In Part			
POCATELLO, ID VOR/DME	SWTHN, MT WP	*24000	45000
*18000—GNSS MEA			