

(a) Comments Due Date

The FAA must receive comments by December 30, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A350-941 and -1041 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports of passenger door girt bar fitting assembly safety hooks being stuck in the upward position. We are issuing this AD to address this condition, which could lead to girt bar disengagement from the girt bar fitting assembly and consequent failure of the passenger door slide deployment during an emergency, possibly preventing safe evacuation of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0207, dated August 22, 2019 (“EASA AD 2019-0207”).

(h) Exceptions to EASA AD 2019-0207

(1) Where EASA AD 2019-0207 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0207 does not apply to this AD.

(3) Paragraph (4) of EASA AD 2019-0207 specifies to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(3)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 90 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 90 days after the effective date of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-

REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2019-0207 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Paperwork Reduction Act Burden Statement*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

(j) Related Information

(1) For information about EASA AD 2019-0207, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0865.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

Issued in Des Moines, Washington, on November 1, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-24532 Filed 11-14-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0864; Product Identifier 2019-NM-140-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. This proposed AD was prompted by a determination that new tests are necessary to address potential air leaks in the reservoir air pressurization lines. This proposed AD would require repetitive pressurization tests of the reservoir air pressurization lines for pipe rupture and leaks, and repair or replacement if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by December 30, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0864.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0864; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2019–0864; Product Identifier 2019–NM–140–AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any

personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0188, dated July 31, 2019 (“EASA AD 2019–0188”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes); Model A310 series airplanes; and Model A300F4–608ST airplanes. (Model A300F4–608ST airplanes are not on the U.S. Register; this proposed AD therefore does not include those airplanes in the applicability.)

This proposed AD was prompted by a determination that new tests are necessary to address potential air leaks in the reservoir air pressurization lines. The FAA is proposing this AD to address air leaks that could result in the loss of a hydraulic system and consequent reduced controllability of the airplane. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0188 describes airworthiness limitations involving repetitive pressurization tests of the reservoir air pressurization lines for pipe rupture and leaks, and repair and replacement of affected hydraulic pipes, ducts, and pressurization lines. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described

previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in EASA AD 2019–0188 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019–0188 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2019–0188 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2019–0188 that is required for compliance with EASA AD 2019–0188 will be available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0864 after the FAA final rule is published.

Interim Action

The FAA considers this proposed AD interim action. If final action is later identified, the FAA might consider further rulemaking then.

Costs of Compliance

The FAA estimates that this proposed AD affects 123 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = 170 per inspection cycle	\$0	\$170 per inspection cycle	\$20,910 per inspection cycle.

The FAA estimates the following costs to do any necessary on-condition action that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need this on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
3 work-hours × \$85 per hour = \$255	\$0	\$255

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus SAS: Docket No. FAA–2019–0864; Product Identifier 2019–NM–140–AD.

(a) Comments Due Date

The FAA must receive comments by December 30, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model airplanes specified in paragraphs (c)(1) through (5) of this AD, certificated in any category.

(1) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.

(2) Model A300 B4–605R and B4–622R airplanes.

(3) Model A300 F4–605R and F4–622R airplanes.

(4) Model A300 C4–605R Variant F airplanes.

(5) Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic power.

(e) Reason

This AD was prompted by a determination that new tests are necessary to address potential air leaks in the reservoir air pressurization lines. The FAA is issuing this AD to address air leaks that could result in the loss of a hydraulic system and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0188, dated July 31, 2019 (“EASA AD 2019–0188”).

(h) Exceptions to EASA AD 2019–0188

(1) Where EASA AD 2019–0188 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019–0188 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may

be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019-0188 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) For information about EASA AD 2019-0188, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0864.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

Issued in Des Moines, Washington, on November 1, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-24531 Filed 11-14-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF LABOR

48 CFR Part 2902

[DOL Docket No. DOL-2019-0002]

RIN 1291-AA42

Department of Labor Acquisition Regulations: Definitions for Head of Agency, Head of Contracting Activity, and Senior Procurement Executive

AGENCY: Office of the Assistant Secretary for Administration and Management, Department of Labor.

ACTION: Proposed rule; withdrawal.

SUMMARY: With this notice, the Department of Labor (Department) is withdrawing the proposed rule that accompanied its direct final rule (DFR) amending three definitions in the Department of Labor Acquisition Regulation (DOLAR) in order to provide the Secretary of Labor greater flexibility and a streamlined procedure to delegate procurement authority and appoint procurement officials.

DATES: The proposed rule published August 29, 2019 (84 FR 45456) is withdrawn as of November 15, 2019.

FOR FURTHER INFORMATION CONTACT:

Press inquiries: Ms. Megan P. Sweeney, Office of Public Affairs, Room No. S-2514, U.S. Department of Labor, 200 Constitution Ave. NW, Washington, DC 20210; telephone: (202) 693-4676; email: sweeney.megan.p@dol.gov.

General information: Herman J. Narcho, U.S. Department of Labor, Office of the Assistant Secretary for Administration and Management, Office of the Chief Procurement Officer, 200 Constitution Avenue NW, Room N-5305, Washington, DC 20210; telephone (202) 693-7171 (this is not a toll-free number).

SUPPLEMENTARY INFORMATION: On August 29, 2019, the Department published a proposed rule amending three DOLAR definitions found at 48 CFR 2902.101(b): Head of Agency, Head of Contracting Activity, and Senior Procurement Executive. The Department published a companion DFR rule proposing the same changes to the DOLAR definitions. In the DFR, the Department stated that it would withdraw the companion proposed rule and confirm the effective date of the DFR if no significant adverse comments were submitted on the DFR by September 30, 2019. The Department received no comments on the proposed rule. Accordingly, the Department is not proceeding with the proposed rule and is withdrawing it from the rulemaking process.

List of Subjects in 48 CFR Part 2902

Government procurement.

Bryan Slater,

Assistant Secretary for Administration and Management, Labor.

[FR Doc. 2019-24681 Filed 11-14-19; 8:45 am]

BILLING CODE 4510-04-P

DEPARTMENT OF COMMERCE

National Oceanic and Atmospheric Administration

50 CFR Parts 622 and 635

[Docket No. 191101-0072]

RIN 0648-BI61

Fisheries of the Caribbean, Gulf of Mexico, and South Atlantic; Atlantic Highly Migratory Species; Coral and Coral Reefs of the Gulf of Mexico; Amendment 9

AGENCY: National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

ACTION: Proposed rule; request for comments.

SUMMARY: NMFS proposes to implement management measures described in Amendment 9 to the Fishery Management Plan (FMP) for the Coral and Coral Reefs of the Gulf of Mexico (Amendment 9) and an associated framework action to the FMP, as prepared by the Gulf of Mexico Fishery Management Council (Council). This proposed rule would establish new habitat areas of particular concern (HAPCs), some of which include a prohibition of the deployment of bottom-tending gear, and modify current fishing regulations for the other existing HAPCs in the Gulf of Mexico (Gulf). Additionally, this proposed rule would implement complementary management measures for Atlantic highly migratory species (HMS) in the Gulf. The purpose of this proposed rule is to protect coral essential fish habitat in the Gulf.

DATES: Written comments must be received by December 16, 2019.

ADDRESSES: You may submit comments on this proposed rule identified by "NOAA-NMFS-2017-0146" by either of the following methods:

- *Electronic Submission:* Submit all electronic public comments via the Federal e-Rulemaking Portal. Go to www.regulations.gov #/docketDetail;D=NOAA-NMFS-2017-0146, click the "Comment Now!" icon, complete the required fields, and enter or attach your comments.