

PART 202—FEDERAL SEED ACT ADMINISTRATIVE PROCEDURES

■ 53. The authority citation for part 202 continues to read as follows:

Authority: 302, 305, 402, 408, 409, 413, 414, 53 Stat. 1275, as amended; 7 U.S.C. 1582, 1585, 1592, 1598, 1599, 1603, and 1604.

■ 54. In part 202, the heading is revised to read as set forth above.

Subpart C—Provisions Applicable to Other Proceedings

■ 55. In subpart C, revise the heading to read as set forth above.

Dated: January 9, 2020.

Bruce Summers,

Administrator, Agricultural Marketing Service.

[FR Doc. 2020-00400 Filed 1-24-20; 8:45 am]

BILLING CODE 3410-02-P

FEDERAL DEPOSIT INSURANCE CORPORATION

12 CFR Parts 303 and 308

RIN 3064-AF19

Incorporation of Existing Statement of Policy Regarding Requests for Participation in the Affairs of an Insured Depository Institution by Convicted Individuals; Extension of Comment Period

AGENCY: Federal Deposit Insurance Corporation.

ACTION: Notice of proposed rulemaking; extension of comment period.

SUMMARY: On December 16, 2019, the Federal Deposit Insurance Corporation (FDIC) published in the **Federal Register** a Notice of Proposed Rulemaking (Notice) that proposed to revise the existing regulations requiring persons convicted of certain criminal offenses to obtain prior written consent before participating in the conduct of the affairs of any depository institution to incorporate the FDIC's existing Statement of Policy, and to amend the regulations setting forth the FDIC's procedures and standards applicable to an application to obtain the FDIC's prior written consent. The FDIC has determined that an extension of the comment period until March 16, 2020, is appropriate.

DATES: The comment period for the Notice published on December 16, 2019 (84 FR 68353), is extended from February 14, 2020, to March 16, 2020.

ADDRESSES: You may submit comments by any of the methods identified in the proposal.

FOR FURTHER INFORMATION CONTACT:

Brian Zeller, Review Examiner, (319) 395-7394 x4125, or Larisa Collado, Section Chief, (202) 898-8509, in the Division of Risk Management Supervision; or Graham N. Rehrig, Senior Attorney, (202) 898-3829, John Dorsey, Acting Supervisory Counsel, (202) 898-3807, or Andrea Winkler, Acting Assistant General Counsel, (202) 898-3727 in the Legal Division.

SUPPLEMENTARY INFORMATION: On December 16, 2019, the FDIC published in the **Federal Register** a Notice that proposed to revise the existing regulations requiring persons convicted of certain criminal offenses to obtain prior written consent before participating in the conduct of the affairs of any depository institution to incorporate the FDIC's existing Statement of Policy, and to amend the regulations setting forth the FDIC's procedures and standards applicable to an application to obtain the FDIC's prior written consent. The Notice sought comment from the public regarding "the scope of Section 19, possible amendments to the relief process, the scope of the *de minimis* offense exemption, and the treatment of expunged criminal records," as well as comments related to the expected effects of the proposed rule. The Notice stated that the comment period would close on February 14, 2020. The FDIC has received a request to extend the comment period. An extension of the comment period would provide additional opportunity for the public to prepare comments to address questions posed by the FDIC. Therefore, the FDIC is extending the end of the comment period for the Notice from February 14, 2020, to March 16, 2020.

Federal Deposit Insurance Corporation.

Dated at Washington, DC, on January 22, 2020.

Annmarie H. Boyd,

Assistant Executive Secretary.

[FR Doc. 2020-01298 Filed 1-24-20; 8:45 am]

BILLING CODE 6714-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-1081; Product Identifier 2019-NM-153-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This proposed AD was prompted by reports of the loss of all air data system information provided to the flightcrew, which was caused by icing at high altitudes. This proposed AD would require revising the existing airplane flight manual (AFM) to provide the flightcrew with procedures to stabilize the airplane's airspeed and attitude. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by March 12, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email ac.yul@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1081; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Darren Gassetto, Aerospace Engineer,

Mechanical Systems and Admin Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-1081; Product Identifier 2019-NM-153-AD” at the beginning of your comments. The FAA specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-24, dated July 5, 2019

(referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD-100-1A10 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1081.

This proposed AD was prompted by reports of the loss of all air data system information provided to the flightcrew, which was caused by icing at high altitudes. The FAA is proposing this AD to address the loss of all air data system information provided to the flightcrew. If not addressed, this condition may adversely affect continued safe flight and landing. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

Bombardier has issued the following service information, which provides a procedure for “Unreliable Airspeed” in the Emergency Procedures section, and also provides a procedure for “Go-Around” in the Normal Procedures section of the applicable AFM. These documents are distinct since they apply to different airplane models.

- Bombardier Challenger 300 AFM, Publication No. CSP 100-1, Revision 56, dated July 8, 2019.
- Bombardier Challenger 350 AFM, Publication No. CH 350 AFM, Revision 22, dated July 8, 2019.

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$47,600

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an

unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require revising the existing AFM with procedures for “Unreliable Airspeed” in the Emergency Procedures section of the applicable AFM and with procedures for “Go-Around” in the Normal Procedures section of the applicable AFM, as described previously.

Costs of Compliance

The FAA estimates that this proposed AD affects 560 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2019-1081; Product Identifier 2019-NM-153-AD.

(a) Comments Due Date

The FAA must receive comments by March 12, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-100-1A10 airplanes, certificated in any category, serial numbers 20001 through 20688 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by reports of the loss of all air data system information provided to the flightcrew, which was caused by icing at high altitudes. The FAA is issuing this AD to address the loss of all air data system information provided to the flightcrew. If not addressed, this condition may adversely affect continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 30 days after the effective date of this AD: Revise the Emergency Procedures—Avionics (section 03-17) of the existing AFM to include the information in the “Unreliable Airspeed” procedure of the applicable AFM specified in figure 1 to paragraph (g) of this AD, and revise the Normal Procedures—After Take-off (section 04-04) of the existing AFM to include the information in the “Go-Around” procedure of the applicable AFM specified in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) – AFM revisions

Airplane Serial Numbers	AFM	AFM Revision	Issue Date
Serial numbers 20001 through 20500 inclusive	Bombardier Challenger 300 AFM, Publication No. CSP 100-1	Revision 56	July 8, 2019
Serial numbers 20501 through 20688 inclusive	Bombardier Challenger 350 AFM, Publication No. CH 350 AFM	Revision 22	July 8, 2019

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-24, dated July 5, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1081.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Admin Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avvs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email ac.yul@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on January 21, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-01235 Filed 1-24-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-1079; Product Identifier 2019-NM-194-AD]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR72 airplanes. This proposed AD was prompted by occurrences of smoke in the flight deck and flap extension difficulties due to wire chafing on the electrical harness under a certain panel. This proposed AD would require modifying the clamp installation of the electrical routing on a certain rib of the left- and right-hand side of the wing rear spars, as specified in a European Union Aviation Safety