

(m) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD; the nature and extent of confidentiality to be provided, if any. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(o) Related Information

(1) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyacoos@faa.gov.

(2) For service information identified in this AD, contact AVOX Systems Inc., 225 Erie Street, Lancaster, NY 14086; telephone 716-683-5100; internet <https://www.safran-aerosystems.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on April 23, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09115 Filed 4-30-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0347; Product Identifier 2020-NM-042-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A300 F4-600R series airplanes. This proposed AD was prompted by a report of damaged main deck cargo crossbeams on the right-hand side, between certain frame locations. This proposed AD would require repetitive detailed inspections of the affected main deck cargo crossbeams for any damage, and depending on findings, accomplishment of applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. This proposed AD would also provide optional terminating actions for the repetitive detailed inspections. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by June 15, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA,

Konrad-Adenauer-Ufer 3, 50668

Cologne, Germany; phone: +49 221 89990 1000; email: ADs@easa.europa.eu; internet:

www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0347.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0347; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225; email: dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-0347; Product Identifier 2020-NM-042-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0050, dated March 9, 2020; corrected March 11, 2020 (“EASA AD 2020-0050”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A300 F4-600R series airplanes.

This proposed AD was prompted by a report of damaged main deck cargo crossbeams on the right-hand side, between certain frame locations. The FAA is proposing this AD to address damaged main deck cargo crossbeams, which could adversely affect the structural integrity of the airplane. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2020-0050 describes procedures for repetitive detailed inspections of the affected main deck cargo crossbeams from frame (FR) 48 to FR54 for any damage (including bent, curved, and cracked crossbeams); corrective actions; and terminating actions. Corrective actions include detailed inspections of the right-hand and left-hand crossbeams and lugs for damage (including buckling and cracking) and correct diameter of the lug/crossbeam holes; repair; and replacement of damaged crossbeams. Optional terminating actions include replacement of crossbeams with reinforced machined crossbeams.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in EASA AD 2020-0050 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD. This proposed AD also would require sending the inspection results to Airbus SAS.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process

to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0050 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2020-0050 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2020-0050 that is required for compliance with EASA AD 2020-0050 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0347 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD affects 52 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510	\$0	\$510	\$26,520

The FAA estimates that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based

on these figures, the FAA estimates the cost of reporting the inspection results on U.S. operators to be \$4,420, or \$85 per product.

The FAA estimates the following costs to do any necessary on-condition

repairs that would be required based on the results of any required actions. The FAA has no way of determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION REPAIRS

Labor cost	Parts cost	Cost per product
6 work-hours × \$85 per hour = \$510	\$10,000	\$10,510

The FAA has received no definitive data that would enable the FAA to provide cost estimates for the on-

condition inspections and replacements specified in this proposed AD.

The FAA estimates the following costs to do the optional terminating actions specified in this proposed AD.

ESTIMATED COSTS FOR OPTIONAL TERMINATING ACTIONS

Labor cost	Parts cost	Cost per product
18 work-hours × \$85 per hour = \$1,530	\$10,000	\$11,530

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120-0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the

national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus SAS: Docket No. FAA-2020-0347; Product Identifier 2020-NM-042-AD.

(a) Comments Due Date

The FAA must receive comments by June 15, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A300 F4-605R and F4-622R airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020-0050, dated March 9, 2020; corrected March 11, 2020 ("EASA AD 2020-0050").

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of damaged main deck cargo crossbeams on the

right-hand side, between certain frame locations. The FAA is issuing this AD to address damaged main deck cargo crossbeams, which could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020-0050.

(h) Exceptions to EASA AD 2020-0050

(1) Where EASA AD 2020-0050 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2020-0050 does not apply to this AD.

(3) Paragraph (4) of EASA AD 2020-0050 specifies to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(3)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by

the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2020-0050 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Paperwork Reduction Act Burden Statement:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD; the nature and extent of confidentiality to be provided, if any. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

(j) Related Information

(1) For information about EASA AD 2020-0050, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0347.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225; email: dan.rodina@faa.gov.

Issued on April 23, 2020.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2020-09139 Filed 4-30-20; 8:45 am]

BILLING CODE 4910-13-P

Avenue U, Building 216, Galveston, Texas 77551.

Instructions: Comments sent by any other method, to any other address or individual, or received after the end of the comment period, may not be considered by NOAA. All comments received are part of the public record and will generally be posted for public viewing on www.regulations.gov without change. All personal identifying information (e.g., name, address), confidential business information, or otherwise sensitive information submitted voluntarily by the sender will be publicly accessible. NOAA will accept anonymous comments (enter "N/A" in the required fields if you wish to remain anonymous).

To participate in the public hearings, online registration is requested in advance via the following links. If you are unable to participate online, you can also connect to the public hearings using the phone numbers provided below.

(1) June 8, 2020, 1:00 p.m.—3:00 p.m. CDT

Registration: <https://attendee.gotowebinar.com/register/9162740973626770700>

Phone: +1 (213) 929-4232 PIN: 704-409-034

(2) June 8, 2020, 6:00 p.m.—8:00 p.m. CDT

Registration: <https://attendee.gotowebinar.com/register/1668176149101021196>

Phone: +1 (213) 929-4232 PIN: 682-728-246

(3) June 11, 2020, 6:00 p.m.—8:00 p.m. CDT

Registration: <https://attendee.gotowebinar.com/register/5569362151706075916>

Phone: +1 (415) 655-0052 PIN: 486-551-096

If you would like to provide comment during the hearings, please sign up in advance. Select "yes" during the online registration. The line-up of speakers will be based on your date and time of registration.

If you will be participating by phone, please send an email to fbexpansion@noaa.gov to add your name to the speaker list.

For more details on the public hearings, please visit <https://flowergarden.noaa.gov/management/expansionnpr.html>.

Copies of the proposed rule, the DEIS, maps of the proposed expansion areas, and additional background materials can be found on the FGBNMS website at <https://flowergarden.noaa.gov/management/expansionnpr.html>. The notice of proposed rulemaking (NPRM) can also be downloaded or viewed on

DEPARTMENT OF COMMERCE

National Oceanic and Atmospheric Administration

15 CFR Part 922

[Docket No. 200330-0093]

RIN 0648-BA21

Proposed Expansion of Flower Garden Banks National Marine Sanctuary

AGENCY: Office of National Marine Sanctuaries (ONMS), National Ocean Service (NOS), National Oceanic and Atmospheric Administration (NOAA), Department of Commerce (DOC).

ACTION: Proposed rule; request for public comments.

SUMMARY: The National Oceanic and Atmospheric Administration (NOAA) proposes to expand the boundaries of Flower Garden Banks National Marine Sanctuary (FGBNMS) and revise the sanctuary's terms of designation. The purpose of this action is to expand the sanctuary to include portions of 14 additional reefs and banks in the northwestern Gulf of Mexico, representing a 104 square mile increase in area. The existing FGBNMS regulations would be applied to the expanded locations. NOAA is soliciting public comment on the proposed rule.

DATES: NOAA will consider all comments received by July 3, 2020. Flower Garden Banks National Marine Sanctuary will hold three virtual public hearings on the following dates and times: June 8, 2020 1:00 p.m.—3:00 p.m. CDT and 6:00 p.m.—8:00 p.m. CDT and June 11, 2020 6:00 p.m.—8:00 p.m. CDT.

ADDRESSES: You may submit comments on this document, identified by NOAA-NOS-2019-0033, by:

- **Electronic Submission:** Submit all electronic public comments via the Federal e-Rulemaking Portal. Go to <http://www.regulations.gov/#/docketDetail;D=NOAA-NOS-2019-0033>, click the "Comment Now!" icon, complete the required fields, and enter or attach your comments.

- Written comments may also be mailed to: George P. Schmahl, Superintendent, Flower Garden Banks National Marine Sanctuary, 4700