

programs to supervised institutions, and as required by statute.

- Examiners will not criticize (through the issuance of matters requiring attention, matters requiring immediate attention, matters requiring board attention, documents of resolution, and supervisory recommendations) a supervised financial institution for, and agencies will not issue an enforcement action on the basis of, a “violation” of or “non-compliance” with supervisory guidance. In some situations, examiners may reference (including in writing) supervisory guidance to provide examples of safe and sound conduct, appropriate consumer protection and risk management practices, and other actions for addressing compliance with laws or regulations.

- Supervisory criticisms should continue to be specific as to practices, operations, financial conditions, or other matters that could have a negative effect on the safety and soundness of the financial institution, could cause consumer harm, or could cause violations of laws, regulations, final agency orders, or other legally enforceable conditions.

- The agencies also have at times sought, and may continue to seek, public comment on supervisory guidance. Seeking public comment on supervisory guidance does not mean that the guidance is intended to be a regulation or have the force and effect of law. The comment process helps the agencies to improve their understanding of an issue, to gather information on institutions’ risk management practices, or to seek ways to achieve a supervisory objective most effectively and with the least burden on institutions.

- The agencies will aim to reduce the issuance of multiple supervisory guidance documents on the same topic and will generally limit such multiple issuances going forward.

The agencies will continue efforts to make the role of supervisory guidance clear in their communications to examiners and to supervised financial institutions and encourage supervised institutions with questions about this statement or any applicable supervisory guidance to discuss the questions with their appropriate agency contact.

**Brian P. Brooks,**

*Acting Comptroller of the Currency.*

By order of the Board of Governors of the Federal Reserve System.

**Ann E. Misback,**

*Secretary of the Board.*

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on or about October 20, 2020.

**James P. Sheesley,**

*Assistant Executive Secretary.*

By the National Credit Union Administration Board on October 28, 2020.

**Melane Conyers-Ausbrooks,**

*Secretary of the Board.*

**Kathleen L. Kraninger,**

*Director, Bureau of Consumer Financial Protection.*

Dated: On or about October 29, 2020.

[FR Doc. 2020-24484 Filed 11-4-20; 8:45 am]

**BILLING CODE 4810-33-P; 6210-01-P; 7535-01-P; 6714-01-P; 4810-AM-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0982; Project Identifier MCAI-2020-01037-T]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A318, A319, A320, and A321 series airplanes. This proposed AD was prompted by a report that the oil used to protect the nose landing gear (NLG) main fittings for transportation and storage was not removed before final heat treatment of the affected parts, possibly generating sub-surface cavities during heat treatment of the affected parts. This proposed AD would require replacing each affected NLG main fitting with a serviceable part, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 21, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0982.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0982; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email [Sanjay.Ralhan@faa.gov](mailto:Sanjay.Ralhan@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2020-0982; Product Identifier MCAI-2020-01037-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the

following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email [Sanjay.Ralhan@faa.gov](mailto:Sanjay.Ralhan@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0165, dated July 23, 2020 ("EASA AD 2020-0165") (also referred to as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Airbus SAS Model A318, A319, and A321 series airplanes and Model A320-211, -212, -214, -215, -216, -231, -232, -233,

-251N, -252N, -253N, -271N, -272N, and -273N airplanes. Model A320-215 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by a report that the oil used to protect the NLG main fittings for transportation and storage was not removed before final heat treatment of the affected parts, possibly generating sub-surface cavities during heat treatment of the affected parts. The FAA is proposing this AD to address possible sub-surface cavities in the NLG main fittings, which could cause detrimental impact on fatigue performance and affect the structural integrity of the NLG. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2020-0165 describes procedures for replacing each NLG main fitting having a certain part number and serial number with a serviceable part. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in

EASA AD 2020-0165 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0165 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2020-0165 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service information specified in EASA AD 2020-0165 that is required for compliance with EASA AD 2020-0165 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0982 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD affects 15 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
8 work-hours × \$85 per hour = \$680 .....	\$*	\$680	\$10,200

\* The FAA has received no definitive data on which to base the parts cost estimates for the replacements specified in this proposed AD.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected

individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has

included all known costs in the cost estimate.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

## § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Airbus SAS:** Docket No. FAA–2020–0982; Project Identifier MCAI–2020–01037–T.

### (a) Comments Due Date

The FAA must receive comments by December 21, 2020.

### (b) Affected ADs

None.

### (c) Applicability

This AD applies to all Airbus SAS airplanes, certificated in any category, as identified in paragraphs (c)(1) through (4) of this AD.

(1) Model A318–111, –112, –121, and –122 airplanes.

(2) Model A319–111, –112, –113, –114, –115, –131, –132, –133, –151N, –153N, and –171N airplanes.

(3) Model A320–211, –212, –214, –216, –231, –232, –233, –251–252N, –253N, –271N, –272N, and –273N airplanes.

(4) Model A321–111, –112, –131, –211, –212, –213, –231, –232, –251N, –252N, –253N, –271N, –272N, –251NX, –252NX, –253NX, –271NX, and –272NX airplanes.

### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

### (e) Reason

This AD was prompted by a report that the oil used to protect the nose landing gear (NLG) main fittings for transportation and storage was not removed before final heat treatment of the affected parts, possibly generating sub-surface cavities during heat treatment of the affected parts. The FAA is issuing this AD to address possible sub-surface cavities in the NLG main fittings, which could cause detrimental impact on fatigue performance and affect the structural integrity of the NLG.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0165, dated July 23, 2020 ("EASA AD 2020–0165").

### (h) Exceptions to EASA AD 2020–0165

(1) Where EASA AD 2020–0165 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2020–0165 does not apply to this AD.

### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2020–0165 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

## (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2020–0165 that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

## (k) Related Information

(1) For information about EASA AD 2020–0165, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0982.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email [Sanjay.Ralhan@faa.gov](mailto:Sanjay.Ralhan@faa.gov).

Issued on October 29, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.*

[FR Doc. 2020-24535 Filed 11-4-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0480; Product Identifier 2019-NM-041-AD]

**RIN 2120-AA64**

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Supplemental notice of proposed rulemaking (SNPRM); reopening of comment period.

**SUMMARY:** The FAA is revising an earlier proposal to supersede Airworthiness Directive (AD) 2013-07-09, which applies to certain The Boeing Company Model 737-700, -700C, -800, and -900ER series airplanes, Model 747-400F series airplanes, and Model 767-200 and -300 series airplanes. This action revises the notice of proposed rulemaking (NPRM) by adding airplanes to the applicability. The FAA is proposing this AD to address the unsafe condition on these products. Since these actions would impose an additional burden over that proposed in the NPRM, the FAA is reopening the comment period to allow the public the chance to comment on these proposed changes.

**DATES:** The comment period for the NPRM published in the **Federal Register** on June 25, 2019 (84 FR 29818), is reopened.

The FAA must receive comments on this SNPRM by December 21, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Boeing service information identified in this SNPRM, contact

Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. For Intertechnique service information identified in this SNPRM, contact Aerotechnics, 61 rue Pierre Curie BP 1, 78373 Plaisir, CEDEX, France; phone: +33 1 6486 6964; internet <http://www.zodiac aerospace.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0480.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0480; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this SNPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Eric Brown, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3563; email: [Eric.M.Brown@faa.gov](mailto:Eric.M.Brown@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to participate in this rulemaking by submitting written comments, data, or views about this proposal. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one copy of the comments. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0480; Product Identifier 2019-NM-041-AD" at the beginning of your comments. Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, as well as a

report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments received by the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this SNPRM because of those comments.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this SNPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this SNPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this SNPRM. Submissions containing CBI should be sent to Eric Brown, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3563; email: [Eric.M.Brown@faa.gov](mailto:Eric.M.Brown@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Discussion

The FAA issued AD 2013-07-09, Amendment 39-17413 (78 FR 22178, April 15, 2013) ("AD 2013-07-09"). AD 2013-07-09 requires actions to address an unsafe condition on certain The Boeing Company Model 737-700, -700C, -800, and -900ER series airplanes, Model 747-400F series airplanes, and Model 767-200 and -300 series airplanes. AD 2013-07-09 requires a general visual inspection for affected serial numbers of the crew oxygen mask stowage box units, and replacement or re-identification as necessary.

The FAA issued an NPRM to amend 14 CFR part 39 by adding an AD to supersede AD 2013-07-09 that would apply to all The Boeing Company Model 737-700, -700C, -800, and -900ER series airplanes, Model 747-400F series airplanes, and Model 767-200 and -300 series airplanes. The NPRM published