

correct cracks on the stabilator tip tube and weight assembly. The unsafe condition, if not addressed, could cause weakening of the complete structure and lead to loss of the trim tab and counter balance weight, which may result in reduced airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Previously Required Actions Retained From AD 78-02-03

(1) Within 50 hours time-in-service (TIS) after January 26, 1978 (the effective date of AD 78-02-03), do the following inspections and modifications.

(i) For airplanes with serial numbers 27-7654001 through 27-7754054, inspect both stabilator tip ribs for missing rivets and missing tube and weight assembly attachment screws and if necessary alter in accordance with Piper Service Bulletin (SB) 547, dated March 1, 1977.

(ii) For airplanes with serial numbers 27-7654001 through 27-7754127, 27-7754130, 27-7754131, 27-7754133 through 27-7754136, and 27-7754138 through 27-7754144, replace the right and left stabilator tab forward inboard rib/horn assemblies by installing Piper Kit 761 143 or equivalent kit in accordance with Piper SB 569, dated August 24, 1977.

(iii) For airplanes with serial numbers 27-7654001 through 27-7754041 equipped with stabilators Piper part number (P/N) 15658-2, 15658-3, 15658-22 or 15658-23, reinforce the mounting of the stabilator tube and weight assemblies by installing additional nose-ribs with Piper Kit 761 141 or equivalent kit in accordance with Piper Service Letter 807A, dated September 8, 1977.

(2) Before further flight after completing the alterations in paragraphs (g)(1)(ii) and (iii) of this AD, balance the stabilator.

(h) Inspection of Stabilator Tip Tube and Weight Assembly

Within 10 hours TIS after the effective date of this AD or within 100 hours TIS after completing the last inspection required by paragraph (a) of AD 78-02-03, whichever occurs later, and thereafter at intervals not to exceed 100 hours TIS, inspect the left and right stabilator balance weight assemblies for cracks and complete any necessary repairs by following Parts I and II of the Instructions in Piper SB No. 540B, dated February 9, 2021, except you are not required to contact Piper for repair instructions. Instead, repair in accordance with FAA-approved procedures.

(i) Credit for Previous Actions

You may take credit for the initial inspection and corrective actions required by paragraph (h) of this AD if you performed those actions before the effective date of this AD using Piper SB No. 540, dated January 4, 1977, or SB No. 540A, dated October 20, 1980.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs

for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the following provisions apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact John Marshall, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5524; fax: (404) 474-5605; email: john.r.marshall@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piper Service Bulletin No. 547, dated March 1, 1977.

(ii) Piper Service Bulletin No. 569, dated August 24, 1977.

(iii) Piper Service Letter No. 807A, dated September 8, 1977.

(iv) Piper Service Bulletin No. 540B, February 9, 2021.

(3) For the service information identified in this AD, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL 32960; phone: (772) 299-2141; website: <https://www.piper.com/>.

(4) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27510 Filed 12-20-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket Number USCG-2021-0916]

RIN 1625-AA00

Safety Zone; Corpus Christi Ship Channel, Mile Markers 19 and 20, Victoria, TX

AGENCY: Coast Guard, Department of Homeland Security (DHS).

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary safety zone for all navigable waters of the Corpus Christi Ship Channel, between mile markers 19 and 20. The safety zone is needed to protect personnel, vessels, and the marine environment from potential hazards created by pipelines that will be removed from the floor of the Corpus Christi Ship Channel. Entry of vessels or persons into this zone is prohibited unless specifically authorized by the Captain of the Port Sector Corpus Christi or a designated representative.

DATES: This rule is effective from 10 a.m. through 2:30 p.m. every day from December 21, 2021, until December 22, 2021. For the purposes of enforcement, actual notice will be used from December 15, 2021, until December 21, 2021.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Lieutenant Commander Anthony Garofalo, Sector Corpus Christi Waterways Management Division, U.S. Coast Guard; telephone 361-939-5130, email CCWaterways@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Abbreviations

CFR Code of Federal Regulations
DHS Department of Homeland Security
FR Federal Register
NPRM Notice of proposed rulemaking
§ Section
U.S.C. United States Code

II. Background Information and Regulatory History

The Coast Guard is issuing this temporary rule without prior notice and

opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under 5 U.S.C. 553(b)(B), the Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule because it is impracticable. We must establish this safety zone immediately to protect personnel, vessels, and the marine environment from potential hazards created by pipelines removal operations and lack sufficient time to provide a reasonable comment period and then consider those comments before issuing the rule.

Under 5 U.S.C. 553(d)(3), the Coast Guard finds that good cause exists for making this rule effective less than 30 days after publication in the **Federal Register**. Delaying the effective date of this rule would be contrary to the public interest because immediate action is needed to respond to the potential safety hazards associated with pipeline removal operations in the Corpus Christi Ship Channel.

III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority in 46 U.S.C. 70034. The Captain of the Port Sector Corpus Christi (COTP) has determined that potential hazards associated with pipeline removal operations occurring from 10 a.m. through 2:30 p.m. every day from December 15, 2021, through December 22, 2021, will be a safety concern for anyone within the Corpus Christi Ship Channel between mile markers 19 and 20. The purpose of this rule is to ensure safety of vessels and persons on these navigable waters in the safety zone while pipelines are removed from the floor of the Corpus Christi Ship Channel.

IV. Discussion of the Rule

This rule establishes a temporary safety zone from 10 a.m. through 2:30 p.m. every day from December 15, 2021, through December 22, 2021. The safety zone will encompass all navigable waters of the Corpus Christi Ship Channel defined by the following coordinates; 27°49'27" N, 097°8'38" W; 27°49'34" N, 097°8'41" W; 27°49'26" N, 097°8'29" W; 27°49'35" N, 097°8'31" W. The pipeline will be removed along the floor of the Corpus Christi Ship Channel. No vessel or person is permitted to enter the temporary safety

zone during the effective period without obtaining permission from the COTP or a designated representative, who may be contacted on Channel 16 VHF-FM (156.8 MHz) or by telephone at 361-939-0450. The Coast Guard will issue Broadcast Notices to Mariners, Local Notices to Mariners, and/or Safety Marine Information Broadcasts as appropriate.

V. Regulatory Analyses

We developed this rule after considering numerous statutes and Executive orders related to rulemaking. Below we summarize our analyses based on a number of these statutes and Executive orders, and we discuss First Amendment rights of protestors.

A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. This rule has not been designated a “significant regulatory action,” under Executive Order 12866. Accordingly, this rule has not been reviewed by the Office of Management and Budget (OMB).

This regulatory action determination is based on the size, location, and duration of the safety zone. The temporary safety zone of 1,300 feet by 1,900 feet will be enforced for a short period of only 4.5 hours every day. The rule does not completely restrict the traffic within a waterway and allows mariners to request permission to enter the zone.

B. Impact on Small Entities

The Regulatory Flexibility Act of 1980, 5 U.S.C. 601–612, as amended, requires Federal agencies to consider the potential impact of regulations on small entities during rulemaking. The term “small entities” comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000. The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities.

While some owners or operators of vessels intending to transit the temporary safety zone may be small entities, for the reasons stated in section V.A above, this rule will not have a significant economic impact on any vessel owner or operator.

Under section 213(a) of the Small Business Regulatory Enforcement

Fairness Act of 1996 (Pub. L. 104–121), we want to assist small entities in understanding this rule. If the rule would affect your small business, organization, or governmental jurisdiction and you have questions concerning its provisions or options for compliance, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section.

Small businesses may send comments on the actions of Federal employees who enforce, or otherwise determine compliance with, Federal regulations to the Small Business and Agriculture Regulatory Enforcement Ombudsman and the Regional Small Business Regulatory Fairness Boards. The Ombudsman evaluates these actions annually and rates each agency’s responsiveness to small business. If you wish to comment on actions by employees of the Coast Guard, call 1-888-REG-FAIR (1-888-734-3247). The Coast Guard will not retaliate against small entities that question or complain about this rule or any policy or action of the Coast Guard.

C. Collection of Information

This rule will not call for a new collection of information under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501–3520).

D. Federalism and Indian Tribal Governments

A rule has implications for federalism under Executive Order 13132, Federalism, if it has a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government. We have analyzed this rule under that order and have determined that it is consistent with the fundamental federalism principles and preemption requirements described in Executive Order 13132.

Also, this rule does not have tribal implications under Executive Order 13175, Consultation and Coordination with Indian Tribal Governments, because it does not have a substantial direct effect on one or more Indian tribes, on the relationship between the Federal Government and Indian tribes, or on the distribution of power and responsibilities between the Federal Government and Indian tribes. If you believe this rule has implications for federalism or Indian tribes, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section above.

E. Unfunded Mandates Reform Act

The Unfunded Mandates Reform Act of 1995 (2 U.S.C. 1531–1538) requires Federal agencies to assess the effects of their discretionary regulatory actions. In particular, the Act addresses actions that may result in the expenditure by a State, local, or tribal government, in the aggregate, or by the private sector of \$100,000,000 (adjusted for inflation) or more in any one year. Though this rule will not result in such an expenditure, we do discuss the effects of this rule elsewhere in this preamble.

F. Environment

We have analyzed this rule under Department of Homeland Security Directive 023–01 and Environmental Planning COMDTINST 5090.1 (series), which guide the Coast Guard in complying with the National Environmental Policy Act of 1969 (42 U.S.C. 4321–4370f), and have determined that this action is one of a category of actions that do not individually or cumulatively have a significant effect on the human environment. This rule involves establishment of a temporary safety zone for navigable waters of the Corpus Christi Ship Channel between markers 19 and 20. The safety zone is needed to protect personnel, vessels, and the marine environment from potential hazards created by pipeline that will be removed from the floor of the Corpus Christi Ship Channel. It is categorically excluded from further review under paragraph L60(c) Appendix A, Table 1 of DHS Instruction Manual 023–01–001–01, Rev. 1. A record of environmental consideration is not necessary, but will be added to the docket if needed.

G. Protest Activities

The Coast Guard respects the First Amendment rights of protesters. Protesters are asked to contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to coordinate protest activities so that your message can be received without jeopardizing the safety or security of people, places or vessels.

List of Subjects in 33 CFR Part 165

Harbors, Marine safety, Navigation (water), Reporting and recordkeeping requirements, Security measures, Waterways.

For the reasons discussed in the preamble, the Coast Guard amends 33 CFR part 165 as follows:

PART 165—REGULATED NAVIGATION AREAS AND LIMITED ACCESS AREAS

■ 1. The authority citation for part 165 continues to read as follows:

Authority: 46 U.S.C. 70034, 70051; 33 CFR 1.05–1, 6.04–1, 6.04–6, and 160.5; Department of Homeland Security Delegation No. 00170.1, Revision No. 01.2.

■ 2. Add § 165.T08–0916 to read as follows:

§ 165.T08–0916 Safety Zone; Corpus Christi Ship Channel, Miler Markers 19 to 20, Victoria, TX.

(a) *Location.* The following area is a safety zone: All navigable waters of the Corpus Christi Ship Channel defined by the following coordinates; 27°49′27″ N, 097°8′38″ W; 27°49′34″ N, 097°8′41″ W; 27°49′26″ N, 097°8′29″ W; 27°49′35″ N, 097°8′31″ W.

(b) *Effective period.* This section is effective from 10 a.m. through 2:30 p.m. every day from December 21, 2021, until December 22, 2021. For the purposes of enforcement, actual notice will be used from December 15, 2021, until December 21, 2021.

(c) *Regulations.* (1) According to the general regulations in § 165.23, entry into this temporary safety zone is prohibited unless authorized by the Captain of the Port Sector Corpus Christi (COTP) or a designated representative. They may be contacted on Channel 16 VHF–FM (156.8 MHz) or by telephone at 361–939–0450.

(2) If permission is granted, all persons and vessels shall comply with the instructions of the COTP or designated representative.

(d) *Information broadcasts.* The COTP or a designated representative will inform the public of the enforcement times and date for this safety zone through Broadcast Notices to Mariners, Local Notices to Mariners, and/or Safety Marine Information Broadcasts as appropriate.

H.C. Govertsen,

Captain, U.S. Coast Guard, Captain of the Port Sector Corpus Christi.

[FR Doc. 2021–27548 Filed 12–20–21; 8:45 am]

BILLING CODE 9110–04–P

ENVIRONMENTAL PROTECTION AGENCY**40 CFR Part 180**

[EPA–HQ–OPP–2020–0022; FRL–9123–01–OCSPJ]

Spinetoram; Pesticide Tolerances

AGENCY: Environmental Protection Agency (EPA).

ACTION: Final rule.

SUMMARY: This regulation establishes tolerances for residues of spinetoram in or on multiple commodities which are identified and discussed later in this document. Clarke Mosquito Control Products, Inc., requested these tolerances under the Federal Food, Drug, and Cosmetic Act (FFDCA).

DATES: This regulation is effective December 21, 2021. Objections and requests for hearings must be received on or before February 22, 2022, and must be filed in accordance with the instructions provided in 40 CFR part 178 (see also Unit I.C. of the **SUPPLEMENTARY INFORMATION**).

ADDRESSES: The docket for this action, identified by docket identification (ID) number EPA–HQ–OPP–2020–0022, is available at <https://www.regulations.gov> or at the Office of Pesticide Programs Regulatory Public Docket (OPP Docket) in the Environmental Protection Agency Docket Center (EPA/DC), West William Jefferson Clinton Bldg., Rm. 3334, 1301 Constitution Ave. NW, Washington, DC 20460–0001. The Public Reading Room is open from 8:30 a.m. to 4:30 p.m., Monday through Friday, excluding legal holidays. The telephone number for the Public Reading Room is (202) 566–1744, and the telephone number for the OPP Docket is (703) 305–5805.

Due to the public health concerns related to COVID–19, the EPA Docket Center (EPA/DC) and Reading Room is closed to visitors with limited exceptions. The staff continues to provide remote customer service via email, phone, and webform. For the latest status information on EPA/DC services and docket access, visit <https://www.epa.gov/dockets>.

FOR FURTHER INFORMATION CONTACT: Marietta Echeverria, Registration Division (7505P), Office of Pesticide Programs, Environmental Protection Agency, 1200 Pennsylvania Ave. NW, Washington, DC 20460–0001; main telephone number: (703) 305–7090; email address: RDFRNotices@epa.gov.

SUPPLEMENTARY INFORMATION:**I. General Information***A. Does this action apply to me?*

You may be potentially affected by this action if you are an agricultural producer, food manufacturer, or pesticide manufacturer. The following list of North American Industrial Classification System (NAICS) codes is not intended to be exhaustive, but rather provides a guide to help readers determine whether this document applies to them. Potentially affected entities may include: