Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on November 24, 2025.

#### Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–21437 Filed 11–26–25; 8:45 am]

BILLING CODE 4910-13-P

# **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2025-5037; Project Identifier AD-2025-00212-A]

#### RIN 2120-AA64

Airworthiness Directives; Textron Aviation, Inc. (Type Certificate Previously Held by Cessna Aircraft Company) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Textron Aviation, Inc., Model 525B airplanes. This proposed AD was prompted by the manufacturer's revision of the aircraft maintenance manual (AMM) to introduce more restrictive inspection intervals. This proposed AD would require revising the Airworthiness Limitations Section (ALS) of the existing AMM or instructions for continued airworthiness (ICA) and the existing approved maintenance or inspection program, as applicable. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 12, 2026.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
  - Fax: (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M— 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2025–5037; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

# FOR FURTHER INFORMATION CONTACT: Soban Saeed, Aviation Safety Engineer, FAA, 1801 South Airport Road, Wichita,

FAA, 1801 South Airport Road, Wichits KS 67209; phone: (316) 946–4123; email: *CCB-COS@faa.gov*.

#### SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the ADDRESSES section. Include "Docket No. FAA–2025–5037; Project Identifier AD–2025–00212–A" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may revise this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

# **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM

contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Soban Saeed, Aviation Safety Engineer, FAA, 1801 South Airport Road, Wichita, KS 67209. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### **Background**

The FAA was notified by Textron Aviation that the existing Model 525B AMM contained incorrect inspection intervals for airworthiness limitation tasks for Chapter 54—Nacelle/Pylons and Chapter 55—Stabilizers. The incorrect inspection intervals were introduced during a technical manual update. The FAA is issuing this AD to prevent undetected cracks in the engine mount and vertical stabilizer front and rear spar caps. The unsafe conditions, if not addressed, could result in reduced structural integrity and consequent reduced controllability of the airplane.

#### **FAA's Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

# Proposed AD Requirements in This NPRM

This proposed AD would require revising the ALS of the existing AMM or ICA and the existing approved maintenance or inspection program, as applicable, by incorporating the actions and associated thresholds and intervals specified in table 1 to paragraph (g) of this proposed AD.

# **Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 601 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

#### **ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise the ALS	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$51,085

# **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866.
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

# The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Textron Aviation Inc.:** Docket No. FAA–2025–5037; Project Identifier AD–2025–00212–A.

# (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 12, 2026

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Textron Aviation, Inc. (Type Certificate previously held by Cessna Aircraft Company) Model 525B airplanes, certificated in any category.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 5530, Vertical Stabilizer Structure; 5415, Nacelle/Pylon, Attach Fittings.

#### (e) Unsafe Condition

This AD was prompted by the manufacturer's revision of the aircraft maintenance manual (AMM) to introduce more restrictive inspection intervals. The FAA is issuing this AD to prevent undetected cracks in the engine mount and vertical stabilizer front and rear spar caps. The unsafe conditions, if not addressed, could result in reduced structural integrity and consequent reduced controllability of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

# (g) Revision of the (ALS) or ICA

Within 150 hours time-in-service (TIS) or 12 months after the effective date of this AD, whichever occurs first: Revise the Airworthiness Limitations Section (ALS) of the existing AMM or instructions for continued airworthiness (ICA) and the existing approved maintenance or inspection program, as applicable, by incorporating the revised tasks and associated thresholds and intervals identified in table 1 to paragraph (g) of this AD.

TABLE 1 TO PARAGRAPH (g)—REVISED MODEL 525B AIRWORTHINESS LIMITATION TASKS

Task No.	Task title	Existing task interval	Revised task interval	Inspection document	Zone
54-50-00-250	Forward Engine Mount Channel Flange (Eddy Current) Special Detailed Inspection.	6,000 hours TIS	6,100 hours TIS, then 4,100 hours TIS thereafter.	4–12–NA	411, 412
54-50-00-252	Aft Engine Beam Aft Upper Angle Common to Aft Web, BL 24.50 (Eddy Current) Special Detailed Inspection.	11,500 hours TIS	14,100 hours TIS, then every 2,700 hours TIS thereafter.	4–12–MR	311, 312
54-50-00-254	Forward Engine Mount Aft Channel Web (Eddy Current) Special Detailed Inspection.	12,000 hours TIS	16,300 hours TIS, then every 11,600 hours TIS thereafter.	4–12–MS	410, 420
54-50-00-255	Forward Engine Mount Forward Channel Web (Eddy Current) Special Detailed In- spection.	12,000 hours TIS	15,600 hours TIS, then every 11,100 hours TIS thereafter.	4–12–NB	410, 420
55-40-00-250	Vertical Fin Left and Right Front Spar Cap at Attachment Hole #2 (Eddy Current) Special Detailed Inspection.	9,000 hours TIS, then every 7,500 hours TIS thereafter.	9,000 hours TIS, then every 7,000 hours TIS thereafter.	4–12–ML	340
55-40-00-251	Vertical Fin Left and Right Front Spar Cap at Attachment Hole #1 (Eddy Current) Special Detailed Inspection.	15,000 hours TIS	17,700 hours TIS, then every 14,900 hours TIS thereafter.	4–12–MO	340

TABLE I TO I ARAGRAFII (9)—HEVISED MODEL 3230 AIRWORTHINESS EIMITATION TASKS—CONTINUES									
Task No.	Task title	Existing task interval	Revised task interval	Inspection document	Zone				
55–40–00–252	Vertical Fin Left and Right Rear Spar Cap at	15,000 hours TIS,	23,600 hours TIS,	4-12-MQ	340				

then every 14,500

hours TIS thereafter.

TABLE 1 TO PARAGRAPH (a)—REVISED MODEL 525R AIRWORTHINESS LIMITATION TASKS-

Note 1 to paragraph (g): Additional guidance for accomplishing the actions required by this AD can be found in Textron Aviation Service Letter SL525B-05-04, Revision 1, dated January 7, 2025.

Detailed Inspection.

#### (h) Provisions for Alternative Actions and Intervals

After the action required by paragraph (g) of this AD has been done, no alternative actions and associated thresholds and intervals are allowed unless they are approved as specified in the provisions of paragraph (i) of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Central Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Central Certification Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@ faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

# (j) Additional Information

- (1) For more information about this AD, contact Soban Saeed, Aviation Safety Engineer, FAA, 1801 South Airport Road, Wichita, KS 67209; phone: (316) 946-4123; email: CCB-COS@faa.gov.
- (2) For Textron Aviation material identified in this AD that is not incorporated by reference, contact Textron Aviation, Inc., P.O. Box 7706, Wichita, KS 67277; phone: (316) 517-6215; email: citationpubs@ txtav.com; website: ww2.txtav.com/ technical publications/.

# (k) Material Incorporated by Reference

None.

Issued on November 24, 2025.

# Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification

[FR Doc. 2025-21416 Filed 11-26-25; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

Attachment Hole #1 (Eddy Current) Special

[Docket No. FAA-2025-5036: Project Identifier MCAI-2024-00748-R]

#### RIN 2120-AA64

#### Airworthiness Directives; Airbus **Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Model EC120B helicopters. This proposed AD was prompted by a report of cyclic flight control restrictions due to the incorrect positioning of the bonding braid on the socket of the pilot cyclic stick, which limited full movement of the pilot cyclic stick during flight. This proposed AD would require a one-time inspection of the position of the bonding braid on the socket of the pilot cyclic stick and, depending on the results, correcting the positioning of the bonding braid and installing a binding clamp. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this NPRM by January 12, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
  - Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-5036; or in person at Docket Operations between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

then every 12,100

hours TIS thereafter.

Material Incorporated by Reference:

• For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

 You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA,

call (817) 222-5110.

### FOR FURTHER INFORMATION CONTACT:

Steven Warwick, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222–5225; email: steven.r.warwick@faa.gov.

#### SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the ADDRESSES section. Include "Docket No. FAA-2025-5036; Project Identifier MCAI-2024-00748-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received

about this NPRM.