

Proposed Rules

This section of the **FEDERAL REGISTER** contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-5403; Project Identifier AD-2025-01167-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Proposed rule; correction.

SUMMARY: The FAA is correcting a notice of proposed rulemaking (NPRM) that was published in the **Federal Register**. The NPRM proposed to issue an airworthiness directive (AD) that would apply to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. As published, the docket number referenced throughout the NPRM is incorrect. This document corrects that error. In all other respects, the original document remains the same; however, for clarity, the FAA is publishing the entire proposed rule in the **Federal Register**.

DATES: The last date for submitting comments on the NPRM (91 FR 931, January 9, 2026) remains February 23, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to regulations.gov. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-5403; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this “proposed rule; correction,” the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com. It is also available at regulations.gov under Docket No. FAA-2025-5403.

FOR FURTHER INFORMATION CONTACT:

Raymond Vital, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3521; email: Raymond.J.Vital@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “FAA-2025-5403; Project Identifier AD-2025-01167-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and

Federal Register

Vol. 91, No. 11

Friday, January 16, 2026

actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Raymond Vital, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3521; email: Raymond.J.Vital@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued an NPRM (91 FR 931, January 9, 2026) that would apply to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes.

The NPRM proposed to require measuring the freeplay of the horizontal stabilizer pivot hinges and the jackscrew, and applicable on-condition actions. The NPRM was prompted by reports from multiple operators of pitch oscillations events due to excessive horizontal stabilizer freeplay. The FAA is proposing this AD to address excessive horizontal stabilizer freeplay. The unsafe condition, if not addressed, could lead to a flutter event, which can result in loss of control of the airplane.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025. This material specifies procedures for measuring freeplay of the left and right horizontal stabilizer pivot hinges and the jackscrew to determine freeplay value, and applicable on-condition actions. On-condition actions include determining total horizontal stabilizer freeplay, repeating the freeplay measurement procedure of the horizontal stabilizer pivot hinges and the jackscrew, and

replacement or repair of any worn parts. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Need for the Correction

As published, the docket number referenced throughout the NPRM is incorrect. The NPRM incorrectly references “Docket No. FAA-2025-0540.” The correct docket number is “Docket No. FAA-2025-5403.”

Although no other part of the preamble or regulatory information has been corrected, for clarity the FAA is publishing the entire proposed rule in the **Federal Register**.

The comment due date of the NPRM remains February 23, 2026.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA-2025-5403; Project Identifier AD-2025-01167-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by February 23, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025.

(d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

(e) Unsafe Condition

This AD was prompted by reports from multiple operators of pitch oscillations events due to excessive horizontal stabilizer

freeplay. The FAA is issuing this AD to address excessive horizontal stabilizer freeplay. The unsafe condition, if not addressed, could lead to a flutter event, which can result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-55A1104, dated June 12, 2025, which is referred to in Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025.

(h) Exception to Requirements Bulletin Specifications

Where the “Effectivity” paragraph and the Boeing Recommended Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025, refer to the original issue date of the Requirements Bulletin 737-55A1104 RB, this AD requires using the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Raymond Vital, Aviation Safety

Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3521; email: Raymond.J.Vital@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-55A1104 RB, dated June 12, 2025.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 13, 2026.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FIR Doc. 2026-00842 Filed 1-15-26; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE INTERIOR

Office of Surface Mining Reclamation and Enforcement

30 CFR Part 950

[SATS No. WY-054-FOR; Docket ID: OSM-2024-0004; S1D1S SS08011000; SX064A000256S180110; S2D2S SS08011000 SX064A00025X501520]

Wyoming Regulatory Program

AGENCY: Office of Surface Mining Reclamation and Enforcement, Interior.

ACTION: Proposed rule; public comment period and opportunity for public hearing on proposed amendment.

SUMMARY: We, the Office of Surface Mining Reclamation and Enforcement (OSMRE), are announcing receipt of a proposed rule amendment to the Wyoming regulatory program (Wyoming program) under the Surface Mining Control and Reclamation Act of 1977 (SMCRA or the Act). Between 2017 and 2021, the Wyoming Environmental Quality Council (EQC) approved several changes to the Wyoming Department of