

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 2001–NM–107–AD.

Applicability: Model A320–111, –211, –212, and –231 series airplanes having manufacturer serial numbers 0002 through 0107 inclusive; certificated in any category; except those airplanes on which Airbus Modification 21202/K1432 has been incorporated in production, or Airbus Service Bulletin A320–53–1029, Revision 01, dated April 29, 2002, has been incorporated in service.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking around the fasteners connecting the pressure panel to the flexible bracket at frame 36, adjacent to the longitudinal beams on the left and right sides of the airplane, which could result in reduced structural integrity and possible rapid decompression of the airplane, accomplish the following:

Inspection and Follow-On Actions

(a) Prior to the accumulation of 30,000 total flight cycles, do a rotating probe inspection on airplanes with a center fuel tank, or a detailed inspection on airplanes without a center fuel tank, to detect cracking around the fasteners that attach the pressure panel to the flexible bracket at frame 36, adjacent to the longitudinal beams on the left and right sides of the airplane, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–53–1030, Revision 01, dated May 21, 2002.

Note 1: For the purposes of this AD, a detailed inspection is defined as: “An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

(b) If no cracks are detected by the inspection required by paragraph (a) of this AD, repeat the applicable inspection thereafter at intervals not to exceed 6,000 flight cycles for airplanes without a center fuel tank, and at intervals not to exceed 18,000 flight cycles for airplanes with a center fuel tank.

Corrective Actions

(c) If any cracking is detected during any inspection required by paragraph (a) of this AD, before further flight, repair the affected structure by accomplishing all applicable actions in accordance with paragraphs 3.B. through 3.E. of the Accomplishment Instructions of Airbus Service Bulletin A320–53–1030, Revision 01, dated May 21, 2002. Repeat the applicable inspection thereafter at intervals not to exceed 6,000 flight cycles for airplanes without a center fuel tank, and at intervals not to exceed 18,000 flight cycles for airplanes with a center fuel tank. For any area where cracking is repaired, the repair

constitutes terminating action for the repetitive inspection of that area.

Note 2: Airbus Service Bulletin A320–53–1030 references Airbus Service Bulletin A320–53–1029, Revision 01, dated April 29, 2002, as an additional source of service information for certain repairs.

(d) If any service bulletin specifies to contact the manufacturer for appropriate action: Before further flight, repair in accordance with a method approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate or the Direction Gale de l’Aviation Civile (or its delegated agent).

Optional Terminating Action

(e) Modification of the structure around the fasteners that attach the pressure panel to the flexible bracket at frame 36, adjacent to the longitudinal beams on the left and right sides of the airplane, by accomplishing all applicable actions in accordance with paragraphs 3.A. through 3.E of the Accomplishment Instructions of Airbus Service Bulletin A320–53–1029, Revision 01, dated April 29, 2002, constitutes terminating action for this AD.

Credit for Actions Done per Previous Issue of Service Bulletins

(f) Accomplishment of the required actions before the effective date of this AD in accordance with Airbus Service Bulletin A320–53–1030, dated January 5, 2000; or Airbus Service Bulletin A320–53–1029, dated January 5, 2000; is considered acceptable for compliance with the applicable requirements of paragraphs (a), (b), and (c) of this AD.

Alternative Methods of Compliance

(g) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, FAA, is authorized to approve alternative methods of compliance for this AD.

Note 3: The subject of this AD is addressed in French airworthiness directive 2000–531–155(B), dated December 27, 2000.

Issued in Renton, Washington, on November 10, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–28606 Filed 11–14–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71****Proposed Modification of the Los Angeles Class B Airspace Area; CA**

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of public meetings.

SUMMARY: This notice announces four fact-finding informal airspace meetings

to solicit information from airspace users, and others, concerning a proposal to revise the Class B airspace at Los Angeles, CA. The purpose of these meetings is to provide interested parties an opportunity to present views, recommendations, and comments on the proposal. All comments received during these meetings will be considered prior to any revision or issuance of a notice of proposed rulemaking.

DATES: The informal airspace meetings will be held on Tuesday, January 20, 2004; Thursday, January 22, 2004; Tuesday, January 27, 2004; and Thursday, January 29, 2004; beginning at 7 p.m. Comments must be received on or before February 29, 2004.

ADDRESSES: (1) The meeting on Tuesday, January 20, 2004, will be held at the Embassy Suites Los Angeles South—Imperial Ballroom, 1440 E. Imperial Avenue, El Segundo, CA, 90245. Directions: Take the 405 Freeway to the 105 Freeway, go west to Freeway end. Then turn left at California Street. The hotel is on the left. (2) The meeting on Thursday, January 22, 2004, will be held at the James Monroe High School—Odens Hall/Multi Purpose Room, 9229 Haskell Avenue, North Hills, CA, 91343. Directions: Take the 405 Freeway to Nordhoff Street, turn left and go two blocks to Haskell Avenue. High school is on the right. (3) The meeting on Tuesday, January 27, 2004, will be held at the Riverside Marriot Hotel—Grand Ball Room, 3400 Market Street, Riverside, CA, 92501. Directions: Take 60 East, then take the exit for Market Street and turn right. The hotel is ½ mile on the left. (4) The meeting on Thursday, January 29, 2004, will be held at the Costa Mesa Neighborhood Community Center, 1845 Park Avenue, Costa Mesa, CA, 92627. Directions: Take the 55 Freeway south and turn right on 19th Street. Go two lights and turn left on Park Avenue. The facility is on the right.

Comments: Send or deliver comments on the proposal in triplicate to: Manager, Air Traffic Division, AWP–500, Federal Aviation Administration, PO Box 92007, Los Angeles, CA, 90009–2007.

FOR FURTHER INFORMATION CONTACT: Debra Trindle, Air Traffic Division, AWP–520, FAA, Western-Pacific Regional Office, telephone (310) 725–6611.

SUPPLEMENTARY INFORMATION:**Meeting Procedures**

The following procedures will be used to facilitate the meeting:

(a) The meetings will be informal in nature and will be conducted by one or

more representatives of the FAA Western-Pacific Region. Representatives from the FAA will present a formal briefing on the proposed modifications to the Class B airspace area. Each participant will be given an opportunity to deliver comments or make a presentation.

(b) The meetings will be open to all persons on a space-available basis. There will be no admission fee or other charge to attend and participate.

(c) Any person wishing to make a presentation to the FAA panel will be asked to sign in and estimate the amount of time needed for such presentation. This will permit the panel to allocate an appropriate amount of time for each presenter.

(d) The meetings will not be adjourned until everyone on the list has had an opportunity to address the panel.

(e) Position papers or other handout material relating to the substance of these meetings will be accepted. Participants wishing to submit handout material should present *three* copies to the presiding officer. There should be additional copies of each handout available for other attendees.

(f) These meetings will not be formally recorded. However, a summary of the comments made at the meeting will be filed in the docket.

Agenda for the Meetings

- Opening Remarks and Discussion of Meeting Procedures.
- Briefing on Background of the Class B Proposal.
- Public Presentations and Comments.
- Closing Comments.

Issued in Washington, DC, on November 4, 2003.

Paul B. Gallant,

Acting, Manager, Airspace and Rules Division.

[FR Doc. 03-28528 Filed 11-14-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2003-15411; Airspace Docket No. 02-ANM-15]

RIN 2120-AA66

Establishment of Restricted Area 4601 A, B, C, and D, Bearpaw; MT

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish new restricted areas (R-4601

A, B, C, and D) in the vicinity of Bearpaw, MT, as part of a Montana Air National Guard (MANG) training initiative. The MANG has requested the airspace be established to improve current air-to-ground training efficiency for the 120th Fighter Wing (120th FW).

DATES: Comments must be received on or before January 16, 2004.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2003-15411, and Airspace Docket No. 02-ANM-15) and be submitted in triplicate to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You may also submit comments through the Internet at <http://dms.dot.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2003-15411, and Airspace Docket No. 02-ANM-15." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received.

All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the **Federal Register's** Web page at <http://www.gpoaccess.gov/fr/index.html>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see address in "Comments Invited" section) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 1601 Lind Avenue, #14, SW., Renton, WA 98055.

Persons interested in being placed on a mailing list for future NPRM's should call the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

History

Air National Guard units must be capable of responding to a variety of needs, wartime situations, and peacekeeping missions that were formerly assigned to the active duty Air Force. To respond to these situations rapidly and effectively, Air National Guard units must train to the same standards established for the active duty Air Force, including weapons delivery training at air-to-ground training ranges. The establishment of a training range in Montana would result in time and cost savings to the 120th FW. The 120th FW currently conducts most of its air-to-ground training at the Utah Test and Training Range. A "local" training range (within a distance of 150 nautical miles from Great Falls) would save at least 41 minutes of flying time for each mission while increasing the amount of time spent training on that mission by 38 minutes. By reducing distance traveled to conduct air-to-ground training the efficiency and effectiveness of training would be enhanced.

The Proposal

The FAA is proposing an amendment to 14 Code of Federal Regulations (CFR) part 73 (part 73) to establish R-4601 A, B, C, and D, in the vicinity Bearpaw, MT, as part of a MANG training initiative. The proposed training range would be located beneath Hays Military Operations Area (MOA) where the MANG, 120th FW currently conducts