

the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2015–22–51 Agusta S.p.A.:** Amendment 39–18386; Docket No. FAA–2016–2069 Directorate Identifier 2015–SW–070–AD.

#### (a) Applicability

This AD applies to Model A109A and A109AII helicopters with a main rotor blade (blade) part number (P/N) 109–0103–01–7, P/N 109–0103–01–9, or P/N 109–0103–01–115 that has 500 or more hours time-in-service installed, certificated in any category.

#### (b) Unsafe Condition

This AD defines the unsafe condition as a crack in a blade. This condition, if not detected, could result in failure of a blade and subsequent loss of control of the helicopter.

#### (c) Effective Date

This AD becomes effective February 16, 2016 to all persons except those persons to whom it was made immediately effective by Emergency AD 2015–22–51, issued on October 23, 2015, which contains the requirements of this AD.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

(1) Before further flight, and thereafter at intervals not to exceed 24 clock-hours, using a 3X or higher power magnifying glass, visually inspect the top and bottom surface of each blade for a crack in the area between the station at the end of the doublers and the station at the beginning of the abrasion strip. If there is a crack, before further flight, replace the blade with an airworthy blade.

(2) Before each flight, check the top and bottom surface of each blade for a crack in the area between the station at the end of the doublers and the station at the beginning of the abrasion strip. If there is a crack, inspect the blade in accordance with paragraph (e)(1) of this AD. The check required by this paragraph may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9 (a)(1) through (a)(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

#### (f) Special Flight Permits

A special flight permit may be permitted for the inspection in paragraph (e)(1) of this AD provided there is no crack in a blade.

#### (g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5110; email: 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

#### (h) Additional Information

(1) AgustaWestland Mandatory Alert Bollettino Tecnico No. 109–150, dated September 17, 2015, which is not incorporated by reference, contains additional information about the subject of this final rule. For service information identified in this final rule, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39–0331–664757; fax 39–0331–664680; or at <http://www.agustawestland.com/technical-bulletins>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015–0190–E, dated September 18, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA–2016–2069.

#### (i) Subject

Joint Aircraft Service Component (JASC) Tracking Code: 6210 Main Rotor Blade.

Issued in Fort Worth, Texas, on January 21, 2016.

#### Lance T. Gant,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2016–01739 Filed 1–29–16; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG–2016–0040]

#### Drawbridge Operation Regulation; Inner Harbor Navigation Canal, New Orleans, LA

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of deviation from drawbridge regulation.

**SUMMARY:** The Coast Guard has issued a temporary deviation from the operating schedule that governs the Senator Ted Hickey (Leon C. Simon Blvd./Seabrook) bascule bridge across the Inner Harbor Navigation Canal, mile 4.6, at New Orleans, Louisiana. The deviation is necessary to accommodate the New Orleans Endurance Festival event. This deviation allows the bridge to remain closed-to-navigation during the event.

**DATES:** This deviation is effective from 7 a.m. through 2 p.m. on April 3, 2016.

**ADDRESSES:** The docket for this deviation, [USCG–2016–0040] is available at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this temporary deviation, call or email Jim Wetherington, Bridge Administration Branch, Coast Guard, telephone (504)671–2128, email [james.r.wetherington@uscg.mil](mailto:james.r.wetherington@uscg.mil).

**SUPPLEMENTARY INFORMATION:** Premier Event Management, through the Louisiana Department of Transportation and Development (LDOTD), requested a temporary deviation from the operating schedule of the Senator Ted Hickey (Leon C. Simon Blvd./Seabrook) bascule bridge across the Inner Harbor Navigation Canal, mile 4.6, at New Orleans, Louisiana. The deviation was requested to accommodate the New Orleans Endurance Festival event. The vertical clearance of the bascule span bridge is 46 feet above mean high water in the closed-to-navigation position and unlimited in the open-to-navigation position. The bridge is governed by 33 CFR 117.458(c).

This deviation is effective on April 3, 2016, from 7 a.m. through 2 p.m. This deviation allows the bridge to remain closed-to-navigation for seven hours on the day of the event.

Navigation on the waterway consists of small tugs with and without tows, commercial vessels, and recreational craft, including sailboats.

Vessels able to pass through the bridge in the closed-to-navigation

position may do so at any time. The bridge will be able to open for emergencies, and there is no immediate alternate route. The Coast Guard will also inform the users of the waterways through our Local and Broadcast Notices to Mariners of the change in operating schedule for the bridge to minimize any impact caused by the temporary deviation.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 26, 2016.

**David M. Frank,**

*Bridge Administrator, Eighth Coast Guard District.*

[FR Doc. 2016-01731 Filed 1-29-16; 8:45 am]

**BILLING CODE 9110-04-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG-2016-0045]

#### Drawbridge Operation Regulation; Sloop Channel, Wantagh, NY

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of deviation from drawbridge regulation.

**SUMMARY:** The Coast Guard has issued a temporary deviation from the operating schedule that governs the Wantagh Parkway Bridge across the Sloop Channel, mile 15.4, at Wantagh, New York. The deviation is necessary to accommodate the Jones Beach July 4th Fireworks. This deviation allows the bridge to remain in the closed position for approximately 3 hours.

**DATES:** This deviation is effective from 9 p.m. to midnight on July 4, 2016.

**ADDRESSES:** The docket for this deviation, [USCG-2016-0045] is available at <http://www.regulations.gov>. Type the docket number in the "SEARCH" box and click "SEARCH". Click on Open Docket Folder on the line associated with this deviation.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this temporary deviation, call or email Ms. Judy K. Leung-Yee, Project Officer, First Coast Guard District, telephone (212) 514-4330, email [judy.k.leung-yee@uscg.mil](mailto:judy.k.leung-yee@uscg.mil).

**SUPPLEMENTARY INFORMATION:** New York State Office of Parks, Recreation and Historic Preservation requested this

temporary deviation from the normal operating schedule to accommodate the Jones Beach July 4th Fireworks.

The Wantagh Parkway Bridge, mile 15.4, across the Sloop Channel has a vertical clearance in the closed position of 16 feet at mean high water and 19.5 feet at mean low water. The existing bridge operating regulations are found at 33 CFR 117.5.

The waterway is transited by commercial and recreation vessel traffic.

Under this temporary deviation, the Wantagh Parkway Bridge may remain in the closed position from 9 p.m. to midnight on July 4, 2016.

Vessels able to pass under the bridge in the closed position may do so at anytime. The bridge will not be able to open for emergencies and there is no immediate alternate route for vessels to pass.

The Coast Guard will also inform the users of the waterways through our Local and Broadcast Notices to Mariners of the change in operating schedule for the bridge so that vessels can arrange their transits to minimize any impact caused by the temporary deviation.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 22, 2016.

**C.J. Bisignano,**

*Supervisory Bridge Management Specialist, First Coast Guard District.*

[FR Doc. 2016-01719 Filed 1-29-16; 8:45 am]

**BILLING CODE 9110-04-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG-2016-0038]

#### Drawbridge Operation Regulation; Lake Pontchartrain, Near New Orleans, LA

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of deviation from drawbridge regulation.

**SUMMARY:** The Coast Guard has issued a temporary deviation from the operating schedule that governs the US 11 bascule bridge across Lake Pontchartrain, mile 4.75, between New Orleans and Slidell, Orleans and St. Tammany Parishes, Louisiana. The deviation is necessary to accommodate the Louisiana Paradise Bridge Run event. The deviation will

allow the draw of the bridge to remain in the closed-to-navigation position during the event.

**DATES:** This deviation is effective from 6:45 a.m. through 8:45 a.m. on February 20, 2016.

**ADDRESSES:** The docket for this deviation, [USCG-2016-0038] is available at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this temporary deviation, call or email Jim Wetherington, Bridge Administration Branch, Coast Guard, telephone (504)671-2128, email [james.r.wetherington@uscg.mil](mailto:james.r.wetherington@uscg.mil).

**SUPPLEMENTARY INFORMATION:** The Slidell Memorial Hospital Foundation, through the Louisiana Department of Transportation and Development (LDOTD), requested a temporary deviation from the operating schedule of the US 11 bascule bridge across Lake Pontchartrain, mile 4.75, between New Orleans and Slidell, Orleans and St. Tammany Parishes, Louisiana. The deviation was requested to allow the draw of the bridge to remain in the closed-to-navigation position during the Louisiana Paradise Bridge Run event. The vertical clearance of the vertical lift span bridge is 13 feet above mean high water in the closed-to-navigation position and 61 feet in the open-to-navigation position. The bridge is governed by 33 CFR 117.5.

This deviation is effective on February 20, 2016 from 6:45 a.m. through 8:45 a.m. The deviation will allow the draw of the bridge to remain in the closed-to-navigation position during the Bridge Run event.

Navigation on the waterway consists of small tugs with and without tows, commercial vessels, and recreational craft, including sailboats.

Vessels able to pass through the bridge in the closed-to-navigation position may do so at any time. The bridge will be able to open for emergencies, and there is no immediate alternate route. The Coast Guard will also inform the users of the waterways through our Local and Broadcast Notices to Mariners of the change in operating schedule for the bridge.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.